

Lead in Water Testing Results

South Washington County Schools

District Program Center/Alternative High School

On December 31st, 2020 the District Program Center/Alternative High School's drinking water was tested for concentration of lead.

The following water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Nurse's Office (AHS)	SINK	16.1
Hallway (SE, left)	FOUNTAIN	0
Hallway (SE, right)	FOUNTAIN	0
Hallway (SE)	BOTTLE FILLER	0
Room 117 (middle room)	SINK	2.2
Room 117 (by laundry)	SINK	2.0
Hallway (west, left)	FOUNTAIN	.54
Hallway (west, right)	FOUNTAIN	.49
Senior Kitchen (left)	SINK	10.6
Senior Kitchen (right)	SINK	11.6
Senior Kitchen	SPRAYER	.60
Senior Center (main area)	SINK	.73
Lunchroom Kitchen (on wall, right)	SINK	12.8
Lunchroom Kitchen (middle, west)	SINK	8.0
Lunchroom Kitchen (middle, east)	SINK	10.8
Special Services Work Room	SINK	2.5

Room 123 (left)	SINK	11.9
Room 123 (right)	SINK	2.6
Room 125 (left)	SINK	2.8
Room 125 (right)	SINK	11.0
Hallway (NE, left)	FOUNTAIN	2.0
Halway (NE, right)	FOUNTAIN	.53
Room 126 (left)	SINK	15.1
Room 126 (right)	SINK	19.7
Nurse's Office (DPC)	SINK	2.4
Room 130	SINK	11.7
Room 130 (white)	SINK	3.2
Room 128	SINK	11.1
Room 128 (white)	SINK	6.3
Hallway (NW)	FOUNTAIN	.32
Hallway (NW)	BOTTLE FILLER	.41
Comm Ed Staff	SINK	3.9
Lobby (left)	FOUNTAIN	.36
Lobby (right)	FOUNTAIN	.38
Room 132	SINK	16.7
Room 132 (white)	SINK	1.3

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources have been replaced and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion and no further action was taken at this time.

LOCATION	SOURCE	INITIAL RESULTS (in ug/L)	RE-TEST RESULTS
Room 117 Staff Dining	SINK	30.6	15.4

Kitchen LR, wall left	SINK	21.1	8.0
Room 124	SINK	20.8	7.4