

Lead in Water Testing Results
South Washington County Schools
Lake Middle School

On January 14th, 2021 the Lake Middle School's drinking water was tested for concentration of lead.

The following water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Office Work Room	SINK	1.9
Concessions	SINK	6.1
G103	SINK	1.4
G103	FOUNTAIN	1.2
Hallway (1)	FOUNTAIN	0
Hallway (3)	FOUNTAIN	0
Hallway (3)	BOTTLE FILLER	0
Hallway (4)	FOUNTAIN	2.5
Hallway (5)	FOUNTAIN	3.7
Hallway (6)	FOUNTAIN	11.4
Hallway (7)	FOUNTAIN	0
Hallway (7)	BOTTLE FILLER	0
Hallway (8)	FOUNTAIN	19.1
Hallway (9)	FOUNTAIN	0
Hallway (9)	BOTTLE FILLER	0
Hallway (10)	FOUNTAIN	.48
Hallway (11)	FOUNTAIN	0

Hallway (11)	BOTTLE FILLER	0
Hallway (12)	FOUNTAIN	.30
Hallway (13)	FOUNTAIN	.24
Hallway (14)	FOUNTAIN	5.9
Hallway (15, left)	FOUNTAIN	3.2
Hallway (15, right)	FOUNTAIN	.65
Hallway (15)	BOTTLE FILLER	.74
Staff A Pod	SINK	1.9
Staff B Pod	SINK	2.4
Staff C Pod	SINK	2.0
Kitchen	SPRAYER	1.2
Kitchen	SINK	16.2

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources have been replaced and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion, and no further action will be taken at this time.

LOCATION	SOURCE	INITIAL RESULTS (in ug/L)	RE-TEST RESULTS
Nurse's Office	SINK	25.0	19.9