## LEONARDTOWN CENTRAL ADMINISTRATION OFFICES 23160 & 23130 Moakley Street Leonardtown, Maryland 20650

SCHOOL FACILITIES DATA								
Structure	Date *	Area	Number Floors	General Structural Condition	Total Area			
Original Building #1	1983	15,297	2	Good	15,297			
Addition	2002	17,535	2	Excellent	17,535			
Original Building #2	1987	5,488	2	Good	5,488			
Total					38,320			
Total acreage of grou	nds: (Origina	4.39						
Total acreage of grou	nds: (Origina	0.59						
Total Acreage		4.98						
Public Utilities:		Water	Yes	Sewer	Yes			

Remarks: The Central Administration offices are located in these facilities, including the following departments:

- Superintendent
  - Deputy Superintendent
  - Assessment and Accountability
  - Curriculum and Instruction
  - Fiscal Services
  - Human Resources
  - Legal Counsel
  - Safety and Security
  - Special Education
  - Student Services
  - Equity, Engagement, and Early Access
  - Strategic Initiatives

<sup>\*</sup> This is the year construction was completed and not necessarily the year the facility was opened.

## DIVISION OF SUPPORTING SERVICES 27190 Point Lookout Road Loveville, Maryland 20656

SCHOOL FACILITIES DATA								
Structure	Date *	Area	Number Floors	General Structural Condition	Total Area			
Original Building	1962	20,775	1	Good	20,775			
Warehouse	2000	5,000	1	Excellent	5,000			
Warehouse	2019	3,600	1	Excellent	3,600			
Total acreage of grou	unds:			24.60 ^				
Public Utilities:		Water	No	Sewer	Yes			

Remarks: The Division of Supporting Services is located at this facility, including the following departments:

- Office of the Assistant Superintendent of Supporting Services
  - Department of Capital Planning
  - Department of Design and Construction
  - Department of Facility Coordination, P.E., Athletics
  - Department of Food and Nutrition Services
  - Department of Information Technology Services
  - Department of Maintenance
  - Department of Operations
  - Department of Transportation

<sup>^</sup> Benjamin Banneker Elementary School and the Division of Supporting Services reside on the same property parcel. The property parcel totals 66 acres. 41.4 acres are associated with Benjamin Banneker Elementary School and 24.6 acres are associated with the Division of Supporting Services.

<sup>\*</sup> This is the year construction was completed and not necessarily the year the facility was opened.