

Radon Testing Results - Springfield School District

The EPS's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting

Six spike tests were conducted to ensure the integrity of the testing process and all spike test passed satisfactorily.

Site Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test	Results (pCi/L)
Thurston Elementary	Main Office Reception	RK108177	2/25/2022	Detector Kit	0.7
Thurston Elementary	A110	RK108073	2/25/2022	Detector Kit	0.9
Thurston Elementary	A111	RK108227	2/25/2022	Detector Kit	1.2
Thurston Elementary	A115	RK108252	2/25/2022	Detector Kit	0.8
Thurston Elementary	A114	RK108778	2/25/2022	Detector Kit	1.0
Thurston Elementary	Workroom	RK108057	2/25/2022	Detector Kit	0.5
Thurston Elementary	A101	RK108785	2/25/2022	Detector Kit	1.0
Thurston Elementary	A102	RK108234	2/25/2022	Detector Kit	0.9
Thurston Elementary	A103	RK108220	2/25/2022	Detector Kit	0.8
Thurston Elementary	A103	RK108241	2/25/2022	Duplicate	0.8
Thurston Elementary	A104	RK108783	2/25/2022	Detector Kit	0.6
Thurston Elementary	A100	RK108195	2/25/2022	Detector Kit	0.6
Thurston Elementary	Library	RK108239	2/25/2022	Detector Kit	0.7
Thurston Elementary	Library	RK108207	2/25/2022	Detector Kit	0.6
Thurston Elementary	Library	RK108204	2/25/2022	Duplicate	0.7
Thurston Elementary	Speech	RK108131	2/25/2022	Detector Kit	2.0
Thurston Elementary	Gym	RK108216	2/25/2022	Detector Kit	0.7
Thurston Elementary	Gym	RK108210	2/25/2022	Detector Kit	< 0.4
Thurston Elementary	Gym	RK108858	2/25/2022	Duplicate	< 0.4
Thurston Elementary	B100	RK108230	2/25/2022	Detector Kit	0.9
Thurston Elementary	B101	RK108231	2/25/2022	Detector Kit	0.4
Thurston Elementary	B102	RK108315	2/25/2022	Detector Kit	1.0
Thurston Elementary	B103	RK108816	2/25/2022	Detector Kit	0.8
Thurston Elementary	B104	RK108840	2/25/2022	Detector Kit	0.5
Thurston Elementary	Commons	RK108316	2/25/2022	Detector Kit	< 0.4
Thurston Elementary	Commons	RK108760	2/25/2022	Duplicate	< 0.4
Thurston Elementary	Commons	RK108171	2/25/2022	Detector Kit	0.4

Thurston Elementary	C108	RK108763	2/25/2022	Detector Kit	0.7
Thurston Elementary	C107	RK108825	2/25/2022	Detector Kit	0.4
Thurston Elementary	C106	RK108806	2/25/2022	Detector Kit	< 0.3
Thurston Elementary	C101	RK108190	2/25/2022	Detector Kit	0.4
Thurston Elementary	C102	RK108224	2/25/2022	Detector Kit	< 0.4
Thurston Elementary	C103	RK108155	2/25/2022	Detector Kit	< 0.3
Thurston Elementary	C104	RK108189	2/25/2022	Detector Kit	0.4