

Radon Testing Results - Springfield School District

The EPS's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting

Six spike tests were conducted to ensure the integrity of the testing process and all spike test passed satisfactorily.

Site Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test	Results (pCi/L)
Maple Elementary	Reception	RK107810	2/18/2022	Detector Kit	< 0.5
Maple Elementary	A110	RK107845	2/18/2022	Detector Kit	< 0.5
Maple Elementary	A111	RK107912	2/18/2022	Detector Kit	< 0.7
Maple Elementary	A115	RK107398	2/18/2022	Detector Kit	< 0.6
Maple Elementary	A113	RK107889	2/18/2022	Detector Kit	< 0.5
Maple Elementary	Work Room	RK107911	2/18/2022	Detector Kit	< 0.7
Maple Elementary	A100	RK107813	2/18/2022	Detector Kit	< 0.5
Maple Elementary	A101	RK107898	2/18/2022	Detector Kit	< 0.6
Maple Elementary	A101	RK107825	2/18/2022	Duplicate	< 0.5
Maple Elementary	A102	RK107919	2/18/2022	Detector Kit	< 0.5
Maple Elementary	A103	RK107805	2/18/2022	Detector Kit	0.7
Maple Elementary	A104	RK107780	2/18/2022	Detector Kit	0.5
Maple Elementary	A106	RK107909	2/18/2022	Detector Kit	< 0.5
Maple Elementary	Library	RK107807	2/18/2022	Detector Kit	< 0.5
Maple Elementary	Library	RK107806	2/18/2022	Detector Kit	< 0.5
Maple Elementary	Gym	RK107874	2/18/2022	Detector Kit	1
Maple Elementary	Gym	RK107900	2/18/2022	Detector Kit	1
Maple Elementary	B100	RK107768	2/18/2022	Detector Kit	DNR
Maple Elementary	B101	RK107885	2/18/2022	Detector Kit	< 0.5
Maple Elementary	B101	RK107802	2/18/2022	Duplicate	< 0.4
Maple Elementary	B102	RK108294	2/18/2022	Detector Kit	< 0.6
Maple Elementary	B103	RK107788	2/18/2022	Detector Kit	< 0.6
Maple Elementary	B104	RK107803	2/18/2022	Detector Kit	< 0.6
Maple Elementary	Commons	RK107927	2/18/2022	Detector Kit	< 0.5
Maple Elementary	Commons	RK107907	2/18/2022	Detector Kit	< 0.6
Maple Elementary	C107	RK107857	2/18/2022	Detector Kit	< 0.5
Maple Elementary	C108	RK107772	2/18/2022	Detector Kit	< 0.4

Maple Elementary	C101	RK107846	2/18/2022	Detector Kit	< 0.5
Maple Elementary	C102	RK107914	2/18/2022	Detector Kit	< 0.6
Maple Elementary	C102	RK107765	2/18/2022	Duplicate	< 0.4
Maple Elementary	C103	RK107945	2/18/2022	Detector Kit	< 0.8
Maple Elementary	C104	RK107869	2/18/2022	Detector Kit	< 0.6
Maple Elementary	C106	RK107922	2/18/2022	Detector Kit	< 0.6