

Radon Testing Results - Springfield School District

The EPS's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting

Six spike tests were conducted to ensure the integrity of the testing process and all spike test passed satisfactorily.

Site Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test	Results (pCi/L)
Hamlin Middle School	Main Office	RK107779	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Conference Room A	RK107949	2/18/2022	Detector Kit	1.0 ± 0.4
Hamlin Middle School	Admin Secretary Office	RK107948	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	Work Room	RK107859	2/18/2022	Detector Kit	< 0.8
Hamlin Middle School	Ms. Grendel Office	RK107777	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	Mr. Muir Office	RK107787	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Commons West	RK107820	2/18/2022	Detector Kit	< 0.7
Hamlin Middle School	Commons East	RK107847	2/18/2022	Detector Kit	1.1 ± 0.3
Hamlin Middle School	Culinary Arts	RK108308	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	B105	RK107855	2/18/2022	Detector Kit	1.3 ± 0.4
Hamlin Middle School	B104	RK107763	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	B103	RK107778	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	B102	RK107770	2/18/2022	Detector Kit	0.6 ± 0.4
Hamlin Middle School	B106	RK107771	2/18/2022	Detector Kit	0.9 ± 0.4
Hamlin Middle School	B107	RK107755	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	B101	RK107817	2/18/2022	Detector Kit	0.9 ± 0.4
Hamlin Middle School	B108	RK107946	2/18/2022	Detector Kit	1.1 ± 0.5
Hamlin Middle School	B109	RK107863	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	B109	RK107871	2/18/2022	Duplicate	< 0.5
Hamlin Middle School	B100	RK107774	2/18/2022	Detector Kit	0.6 ± 0.4
Hamlin Middle School	B110	RK107862	2/18/2022	Detector Kit	< 0.7
Hamlin Middle School	Alder Workroom	RK107797	2/18/2022	Detector Kit	1.0 ± 0.4
Hamlin Middle School	Media Center	RK107433	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Media Center Reading Room	RK107431	2/18/2022	Detector Kit	1.0 ± 0.4
Hamlin Middle School	Media Center Office	RK107796	2/18/2022	Detector Kit	0.9 ± 0.5
Hamlin Middle School	Media Center Office	RK107441	2/18/2022	Duplicate	0.8 ± 0.4
Hamlin Middle School	A100	RK107944	2/18/2022	Detector Kit	< 0.6

Hamlin Middle School	A101	RK107423	2/18/2022	Detector Kit	0.8 ± 0.4
Hamlin Middle School	A102	RK107941	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	A110	RK107789	2/18/2022	Detector Kit	1.2 ± 0.4
Hamlin Middle School	A110 Laundry Room	RK107437	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	A103	RK107430	2/18/2022	Detector Kit	1.9 ± 0.4
Hamlin Middle School	A104	RK108329	2/18/2022	Detector Kit	< 0.7
Hamlin Middle School	A105	RK107421	2/18/2022	Detector Kit	0.8 ± 0.4
Hamlin Middle School	A105	RK107422	2/18/2022	Duplicate	1.3 ± 0.4
Hamlin Middle School	A106	RK107429	2/18/2022	Detector Kit	0.6 ± 0.4
Hamlin Middle School	A107	RK107406	2/18/2022	Detector Kit	1.6 ± 0.3
Hamlin Middle School	A108	RK108255	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	A109	RK108309	2/18/2022	Detector Kit	1.7 ± 0.3
Hamlin Middle School	C101	RK107415	2/18/2022	Detector Kit	< 0.8
Hamlin Middle School	C101 Office	RK107444	2/18/2022	Detector Kit	1.3 ± 0.4
Hamlin Middle School	C102	RK107394	2/18/2022	Detector Kit	2.1 ± 0.4
Hamlin Middle School	C102 Office	RK107363	2/18/2022	Detector Kit	0.7 ± 0.4
Hamlin Middle School	SRC Main Office	RK107750	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Vice Principal Office	RK107781	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Health Room	RK107749	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	Conference Room B	RK107748	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	FRC	RK108254	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	FRC	RK107391	2/18/2022	Duplicate	0.7 ± 0.4
Hamlin Middle School	Office #1	RK107381	2/18/2022	Detector Kit	< 0.4
Hamlin Middle School	Room 180	RK107371	2/18/2022	Detector Kit	< 0.5
Hamlin Middle School	Mr. Vanhorn Office	RK107830	2/18/2022	Detector Kit	0.6 ± 0.3
Hamlin Middle School	Auxiliary Gym West	RK107389	2/18/2022	Detector Kit	< 0.6
Hamlin Middle School	Auxiliary Gym East	RK107405	2/18/2022	Detector Kit	< 0.7
Hamlin Middle School	Auxiliary Gym North	RK107407	2/18/2022	Detector Kit	< 0.9
Hamlin Middle School	Fitness Room	RK107379	2/18/2022	Detector Kit	< 0.8
Hamlin Middle School	Main Gym West	RK107790	2/18/2022	Detector Kit	DNR
Hamlin Middle School	Main Gym East	RK107400	2/18/2022	Detector Kit	< 0.9
Hamlin Middle School	PE Storage Room	RK107393	2/18/2022	Detector Kit	< 0.8