



Frank G. Lindsey Elementary School

Hendrick Hudson School District



- Update playground equipment
- Exterior ramp/access improvements
- Improve entry security
- Replace hand rails to meet code
- Replace water fountains to meet code
- Replace gym partition door
- Replace older exterior doors
- Spalling concrete repairs
- Structural steel recoating
- Improve kitchen ventilation to meet code
- Update fire alarm strobe lights to meet code
- Update exterior lighting (safety / security)
- Electrical safety improvements
- Door locks / security improvements
- Miscellaneous plumbing / piping replacements




Safety and Security



How Students Learn



Infrastructure Upgrades



Community Facilities