


Buchanan-Verplank Elementary School

Hendrick Hudson School District



Concrete replacements at entry	●	●
Replace miscellaneous doors to meet code	●	●
Improve fire rated partitions to meet code	●	●
Repair misc. masonry cracks	●	●
Replace older windows at main entry	●	●
Replace gym partition door	●	●
Ventilation upgrades to meet code	●	●
Kitchen ventilation updates to meet code	●	●
Miscellaneous plumbing / piping replacements	●	●
Improve entry security	●	●
Electrical safety improvements	●	●
Door locks / security improvements	●	●
Cafetorium furnishing upgrades	●	●

