

Columbine Hills Elementary School		Sampled 4/12/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
09500-156-SWB	Sink with Bubbler in Classroom 156	<0.1*	
09500-155-SWB	Sink with Bubbler in Classroom 155	0.1	
09500-154-SWB	Sink with Bubbler in Classroom 154	0.3	
09500-153-SWB	Sink with Bubbler in Kindergarten Classroom 153	0.1	
09500-152-SWB	Sink with Bubbler in Kindergarten Classroom 152	0.7	
09500-150-SWB	Sink with Bubbler in Classroom 150	1.2	
09500-158H-DFL	Hallway Drinking Fountain near Kindergarten Classroom 153/Left	2.9	
09500-158H-DFR	Hallway Drinking Fountain near Kindergarten Classroom 153/Right	1.8	
09500-143-SWB	Sink with Bubbler in Classroom 143	0.6	
09500-142-SWB	Sink with Bubbler in Classroom 142	0.2	
09500-138-S	Sink in Clinic	0.3	
09500-100H-DF	Hallway Drinking Fountain near Principal's Office	0.1	
09500-2022-100H-WBFS	Water Bottle Filling Station Near Principal's Office	0.1	
09500-129-S	Sink in Teacher's Lounge	0.2	
09500-128-SWB	Sink with Bubbler in Art Room	0.4	
09500-C101-SWB	Sink with Bubbler in Classroom C101	2.3	
09500-113XH-DF	Hallway Drinking Fountain near Classroom C103	4.7	
09500-C103-SWB	Sink with Bubbler in Classroom C103	0.8	
09500-C104-SWB	Sink with Bubbler in Classroom 104	1.5	
09500-C105-SWB	Sink with Bubbler in Classroom 105	0.6	
09500-C111-SWB	Sink with Bubbler in Room C111	0.5	
09500-101XH-DF	Hallway Drinking Fountain near Classroom C113	2.7	
09500-C113-SWB	Sink with Bubbler in Classroom C113	0.6	
09500-C112-SWB	Sink with Bubbler in Classroom C112	0.3	
09500-C100-SWB	Sink with Bubbler in Classroom C100	1	
09500-B109BH-DF	Hallway Drinking Fountain near Classroom B103	not in use	
09500-B103-SWB	Sink with Bubbler in Classroom B103	not in use	
09500-B107-SWB	Sink with Bubbler in Classroom B107	not in use	
09500-B108-SWB	Sink with Bubbler in Classroom B108	not in use	
09500-B105-SWB	Sink with Bubbler in Classroom B105	not in use	
09500-119H-DFL1	Hallway Drinking Fountain near Gym/Left	7.2	Repairs Pending
09500-119H-DFL2	Hallway Drinking Fountain near Gym/Left	2.2	

09500-119H-DFR1	Hallway Drinking Fountain near Gym/Right	not in use	
09500-119H-DFR2	Hallway Drinking Fountain near Gym/Right	2.1	
09500-102-S2	Food Service Sink-Food Prep	1.8	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			