

Frank D'Angelis (previously Mortensen)		Sampled 4/29/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
26000-2022-132H-DF	Hallway Drinking Fountain	19.8	Repairs Pending
26000-2022-114H-DF	Hallway Drinking Fountain	0.2	
26000-2022-114H-WBFS	Hallway Water Bottle Filling Station	0.2	
26000-2022-Workroom-S	Sink in Workroom	6.9	Repairs Pending
26000-2022-Music Room-S	Sink in Music Room	22.8	Repairs Pending
26000-2022-143H-DF	Hallway Drinking Fountain	0.8	
26000-2022-143H-WBFS	Hallway Water Bottle Filling Station	0.7	
26000-2022-159H-DF	Hallway Drinking Fountain	0.8	
26000-2022-176H-S	Hallway Sink	1.9	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			