

Ed Center - Sampled 6/2/2017			
SampleNumber	Description	Lead Result	Unit
98000-2017-155-S	Sink in Lounge	0.5	ppb
98000-2017-ELEC13H-DFL	1st Floor Hallway Drinking Fountain outside restrooms-Left	3.1	ppb
98000-2017-ELEC13H-DFR	1st Floor Hallway Drinking Fountain outside restrooms-Right	0.2	ppb
98000-2017-ELEC22-DFL	2nd Floor Drinking Fountain outside of restrooms-Left	0.2	ppb
98000-2017-ELEC22-DFR	2nd Floor Drinking Fountain outside of restrooms-Right	<0.1*	ppb
98000-2017-3RDFL-DFL	3rd Floor Drinking Fountain outside of restrooms-Left	0.4	ppb
98000-2017-3RDFL-DFR	3rd Floor Drinking Fountain outside of restrooms-Right	0.2	ppb
98000-2017-3RDFL-LUNCH-S	3rd Floor Sink in Lounge	0.8	ppb
98000-2017-3RDFL-LUNCH-IM	3rd Floor Ice Machine in Lounge	0.7	ppb
98000-2017-4THFL-DFL	4th Floor Drinking Fountain outside of restrooms-Left	1.6	ppb
98000-2017-4THFL-DFR	4th Floor Drinking Fountain outside of restrooms-Right	<0.1*	ppb
98000-2017-SUPERINTENDENT-S	Sink in Superintendent Office	1.3	ppb
98000-2017-5THFL-DFL	5th Floor Drinking Fountain outside of restrooms-Left	0.6	ppb
98000-2017-5THFL-DFR	5th Floor Drinking Fountain outside of restrooms-Right	0.4	ppb
98000-2017-1STFL-CAFÉ-S1	1st Floor Sink in Café	9.7	ppb
98000-2017-1STFL-CAFÉ-S2	1st Floor Sink in Café	2.1	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			