

Ken Caryl Middle School		Sampled 4/12/2022
CustomerSampleNumber	Description	Lead Results (ppb)
64100-014-S	Sink in Clinic Restroom	0.7
64100-036H-DFL	Hallway Drinking Fountain across from Main Office/Left	0.4
64100-036H-DFR	Hallway Drinking Fountain across from Main Office/Right	0.2
64100-2022-036H-WBFS	water bottle filling station across from Main Office	0.3
64100-029H-DFL	Hallway Drinking Fountain near Restrooms by Main Office/Left	0.4
64100-029H-DFR	Hallway Drinking Fountain near Restrooms by Main Office/Right	3.5
64100-84XH-DF	Hallway Drinking Fountain outside of Science Classroom 60	0.5
64100-2022-84XH-WBFS	Hallway water bottle filling station outside of Science Classroom 60	0.4
64100-135-S1	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.1
64100-135-S2	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.2
64100-135-S3	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.1
64100-135-S4	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.1
64100-135-S5	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	3.1
64100-135-S6	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.3
64100-135-S7	Sink in Food Lab - Room 86 (Room 135 per Facilities Floor Plan)	0.2
64100-C101H-DFL	Hallway Drinking Fountain by Girl's Locker Room/Left	0.2
64100-C101H-DFR	Hallway Drinking Fountain by Girl's Locker Room/Right	0.3
64100-161H-DFL	Hallway Drinking Fountain by Boy's Locker Room/Left	<0.1*
64100-161H-DFR	Hallway Drinking Fountain by Boy's Locker Room/Right	<0.1*
64100-100-S	Sink in Teacher's Lounge	<0.1*
64100-100H-DFL	Hallway Drinking Fountain outside of Teacher's Lounge/Left	<0.1*
64100-100H-DFR	Hallway Drinking Fountain outside of Teacher's Lounge/Right	<0.1*
64100-2022-100H-WBFS	Hallway water bottle filling station outside of Teacher's Lounge	<0.1*
64100-106-S2	Food Service Sink-Food Prep	1.4
64100-2022-C012H-DFL	Drinking Fountain	<0.1*
64100-2022-C012H-DFR	Drinking Fountain	<0.1*
64100-2022-C012H-WBFS	water bottle filling station	<0.1*
64100-2022-C013H-DFL	Drinking Fountain/ left	<0.1*
64100-2022-C013H-DFM	Drinking Fountain/ middle	<0.1*

64100-2022-C013H-DFR	Drinking Fountain/ right	<0.1*
64100-2022-C013H-WBFS	water bottle filling station	<0.1*
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.		