

Peiffer Elementary School - 6/17/16				Resampled* 11/15/16		Resampled** 5/14/19	
SampleNumber	Description	Lead Result	Units	Lead Result	Units	Lead Result	Units
32800-157-S1	Food Service Sink-Food Prep	8.6	ppb			4.3	ppb
32800-157-S2	Food Service Sink-Hose Connection Spigot	24.5	ppb	Fixture Removed			
32800-170X-S1	Art Room Sink	5.7	ppb				
32800-170X-S2	Art Room Sink	3.7	ppb				
32800-16-SWB	Sink with Bubblers in Classroom 16	5.7	ppb			12.3	ppb
32800-13-SWB	Sink with Bubblers in Classroom 13	4.4	ppb			9.6	ppb
32800-12-SWB	Sink with Bubblers in Classroom 12	1.4	ppb			1.7	ppb
32800-11-SWB	Sink with Bubblers in Classroom 11	1.6	ppb			1.8	ppb
32800-10-SWB	Sink with Bubblers in Classroom 10	3.9	ppb			2.1	ppb
32800-9-SWB	Sink with Bubblers in Classroom 9	1.2	ppb			2.0	ppb
32800-8-SWB	Sink with Bubblers in Classroom 8	2.3	ppb				
32800-7-SWB	Sink with Bubblers in Classroom 7	1.9	ppb			0.4	ppb
32800-4-SWB	Sink with Bubblers in Classroom 4	2.8	ppb			3.4	ppb
32800-3-SWB	Sink with Bubblers in Classroom 3	2.9	ppb			2.5	ppb
32800-2-SWB	Sink with Bubblers in Classroom 2	1.4	ppb			1.6	ppb
32800-135-DF	Hallway Drinking Fountain near Computer Lab	22.4	ppb			1.6	ppb
32800-135-WBFS	Water Bottle Filling Station near Computer Lab	1.9 ***	ppb				
32800-143BXH-SWB	Hallway Sink with Bubblers	5.3	ppb			7.2	ppb
32800-182XH-SWB	Hallway Sink with Bubblers	9.9	ppb			6.9	ppb
32800-181XH-SWB	Hallway Sink with Bubblers	10.0	ppb			7.0	ppb
32800-20-SWB	Sink with Bubblers in Room 20	4.6	ppb			5.3	ppb
32800-19-SWB	Sink with Bubblers in Room 19	8.8	ppb			15.6†	ppb
32800-18-SWB	Sink with Bubblers in Room 18	6.6	ppb	8.5	ppb		
32800-17-SWB	Sink with Bubblers in Room 17	7.0	ppb	9.5	ppb		
32800-31XH-SWB	Hallway Sink with Bubblers	0.7	ppb	0.3	ppb		
32800-32XH-SWB	Hallway Sink with Bubblers	1.0	ppb	0.4	ppb		
32800-15-SWB	Sink with Bubblers in Classroom 15	7.9	ppb	9.5	ppb		
32800-14-SWB	Sink with Bubblers in Classroom 14	10.4	ppb	12.7	ppb		
32800-28XH-SWB	Hallway Sink with Bubblers	0.7	ppb	0.5	ppb		
32800-27XH-SWB	Hallway Sink with Bubblers	0.3	ppb	0.2	ppb		
32800-6-SWB	Sink with Bubblers in Classroom 6	4.1	ppb	3.3	ppb		
32800-5-SWB	Sink with Bubblers in Classroom 5	2.7	ppb				
32800-R1-160-S1	Sink in Temp R1-160	5.4	ppb				
32800-R1-160-S2	Sink in Temp R1-160	3.0	ppb				
32800-R1-160-DF	Drinking Fountain in Temp R1-160	3.6	ppb				
32800-R1-157-S1	Sink in Temp R1-157	7.5	ppb				
32800-R1-157-DF	Drinking Fountain in Temp R1-157	4.1	ppb				
32800-R1-157-S2	Sink in Temp R1-157	10.6	ppb				
32800-R1-050-DF	Drinking Fountain in Temp R1-050	4.1	ppb				
32800-R1-050-S1	Sink in Temp R1-050	0.9	ppb				
32800-R1-050-S2	Sink in Temp R1-050	0.7	ppb				
32800-101-SWB	Sink with Bubblers in Kindergarten Classroom 101	2.7	ppb	1.8	ppb		
32800-107-SWB	Sink with Bubblers in Kindergarten Classroom 107	3.6	ppb	1.8	ppb		
32800-130-SWB	Sink with Bubblers in Clinic	2.3	ppb	1.8	ppb		
32800-124-S	Sink in Office Workroom	18.8	ppb	16.1‡	ppb		
32800-195X-S	Sink in Teacher's Lounge	2.3	ppb	1.4	ppb		
32800-177X-SWBR	Cafeteria Sink with Bubblers/Right	3.1	ppb	0.8	ppb		
32800-177X-SWBL	Cafeteria Sink with Bubblers/Left	1.0	ppb	0.3	ppb		
32800-157X-S1	Food Service Sink-Hand Sink	6.5	ppb				
32800-157X-S2	Food Service Sink-Wash/Rinse	7.5	ppb				
32800-157X-S3	Food Service Sink- Rinse/Sanitize	2.2	ppb				
32800-R1-091-DF	Drinking Fountain in Temp R1-091	1.7	ppb				
32800-R1-091-S1	Sink in Temp R1-091	0.8	ppb				
32800-R1-158-S1	Sink in Temp R1-158	2.8	ppb				
32800-R1-158-S2	Sink in Temp R1-158	6.1	ppb				
32800-R1-091-S2	Sink in Temp R1-091	2.4	ppb				

* Resampling results after elevated fixtures were repaired, removed, or replaced.

** Resampling results were from samples collected on 5/14/19 as part of an ongoing rotation of lead testing.

*** This fixture was sampled for the first time on 5/14/19.

† This fixture is signed "Fountain out of Service, Do Not Drink".

‡ This fixture is signed "No Food Prep, Do Not Drink, For Handwashing Only".