

Powderhorn Elementary School		Sampled 4/7/2022
CustomerSampleNumber	Description	Lead Results (ppb)
33500-A102H-DFL	Hallway Drinking Fountain by Main Office/Left	<0.1*
33500-A102H-DFR	Hallway Drinking Fountain by Main Office/Right	<0.1*
33500-2022-A102H-WBFS	Hallway Water Bottle Filling Station by Main Office	<0.1*
33500-A105-SWB	Sink with Bubblers in Kindergarten Classroom A105	2.6
33500-A106-SWB	Sink with Bubblers in Kindergarten Classroom A106	0.7
33500-A107-SWB	Sink with Bubblers in Classroom A107	0.2
33500-A108-SWB	Sink with Bubblers in Classroom A108	0.4
33500-A109-SWB	Sink with Bubblers in Classroom A109	0.1
33500-A110-SWB	Sink with Bubblers in Kindergarten Classroom A110	<0.1*
33500-A121-SWB	Sink with Bubblers in Classroom A121	0.1
33500-A122-SWB	Sink with Bubblers in Classroom A122	0.1
33500-A123-SWB	Sink with Bubblers in Classroom A123	<0.1*
33500-A124-SWB	Sink with Bubblers in Classroom A124	<0.1*
33500-A125-SWB	Sink with Bubblers in Classroom A125	1.4
33500-A126-SWB	Sink with Bubblers in Classroom A126	0.1
33500-A136-SWB	Sink with Bubblers in Classroom A136	<0.1*
33500-A137-SWB	Sink with Bubblers in Classroom A137	0.2
33500-A152-S	Sink in Teacher's Lounge	1
33500-A138-SWB	Sink with Bubblers in Classroom A138	0.2
33500-A139-SWB	Sink with Bubblers in Classroom A139	0.2
33500-A140-SWB	Sink with Bubblers in Resource Room A140	0.1
33500-A141-SWB	Sink with Bubblers in Resource Room A141	<0.1*
33500-B102H-DFL	Hallway Drinking Fountain outside of Music Room/Left	<0.1*
33500-B102H-DFR	Hallway Drinking Fountain outside of Music Room/Right	<0.1*
33500-2022-B102H-WBFS	Hallway Water Bottle Filling Station outside of music room	<0.1*
33500-B105-SWB	Sink with Bubblers in Classroom B105	4.7
33500-B106-SWB	Sink with Bubblers in Classroom B106	0.8
33500-B107-SWB	Sink with Bubblers in Classroom B107	0.1
33500-B108-SWB	Sink with Bubblers in Classroom B108	0.1
33500-B109-SWB	Sink with Bubblers in Classroom B109	<0.1*
33500-B110-SWB	Sink with Bubblers in Classroom B110	<0.1*
33500-B127-S3	Food Service Sink-Food Prep	0.5
33500-A162-S	Sink in Clinic	1.6

* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.