LOUISIANA DEPARTMENT OF ENVIRONMENTAL QUALITY OES, PUBLIC PARTICIPATION AND PERMIT SUPPORT DIVISION NOTIFICATIONS AND ACCREDITATIONS SECTION



Required Elements for Asbestos Management Plans for School and State Buildings Form AAC-8 LAC 33:III.Chapter 27

Directions: Please note that the current AAC-8 form is an interactive Asbestos Management Plan and the information shall be typed or legibly hand written on the form itself, not referencing another document as in the previous AAC-8 form. This form must be completed properly and submitted as the asbestos Management Plan required for a school (Kindergarten through Post-graduate), state owned, leased, or state-used building. A written explanation must be provided for any incomplete section. The explanation must be included in the section or if too long, attached behind the corresponding section. You may find the following link useful, complete with Most Frequently Asked Questions, forms, Training Providers, etc: http://www.deq.louisiana.gov/portal/tabid/2883/Default.aspx.

Completion of the AAC-8 will ensure that the Management Plan meets federal (40 CFR Part 763.93) and state (*LAC 33:III.Chapter 27*) requirements and will facilitate accurate and timely state review.

All schools must submit their Asbestos Management Plan directly to: LDEQ, OES, Public Participation and Permit Support Division, Notifications and Accreditations Section, P.O. Box 4313, Baton Rouge, LA 70821-4313.

Any Asbestos Management Plan for a state building, whether it is owned, leased, or otherwise used as a state building must submit the Asbestos Management Plan directly to: Real Estate Leasing Administrator, Division of Administration, Facility Planning and Control, Real Estate Leasing Section, P.O. Box 94095, Baton Rouge, LA 70804-9095.

APPLICABILITY:

This building is being used for the following purpose:

School (Kindergarten through Post-Graduate)	New School (Constructed after October 12, 1988)
State building (Owned, Leased, or Used)	Other:
form 7000 -00	

form_7082_r00 Revised: 9/15/2011

STATE BUILDING EXEMPTION (LAC 33:111.2701.B)

I. If the following exemption applies, complete pages 1, 2, Section A, and provide supporting evidence as applicable.

1. This building is <u>not</u> a school building (see definition of school building) used for grades kindergarten through post-graduate; and

2. This state building was built after 1978 and is exempt from the requirements of this Chapter because there is no possibility of the presence of asbestos (*LAC 33:III.2701.B.2*); or

3. This state building was built before 1979 and is exempt from the requirements of this Chapter because an inspection was conducted in accordance with *LAC 33:III.2707.A*, and no asbestos is contained in the building, provided that:

- a. a copy of the inspection report is submitted within 90 days of the inspection;
- b. a copy of the report is maintained at the administrative office; and
- c. no asbestos material was added in a renovation.
- **II.** If an exemption is being requested from the requirements of submitting an asbestos Management Plan as indicated in *LAC 33:III.2701.B.2*, "State buildings built after 1978 are exempt from the requirements of this Chapter unless there is the possibility of the presence of asbestos or the building is used for education of grades kindergarten through post-graduate."

The undersigned does hereby certify that the building will be used as a state building and there is no possibility of the presence of asbestos in the building as stated above (*LAC* 33:III.2701.B.2).

Responsible Individual (printed/typed name):	
Responsible Individual Signature:	
Responsible Individual Contact Information:	Phone No: _()
Fax No: _()	Email Address:

III. If an exemption is being requested from the requirements of submitting an asbestos Management Plan as indicated in *LAC 33:III.2701.B.3*, "This state building was built before 1979 and is exempt from the requirements of this Chapter because an inspection was conducted in accordance with *LAC 33:III.2707.A*, and no asbestos is contained in the building," attach the inspection report as noted above and a copy of current Louisiana inspector accreditation certificate behind this page. (*LAC 33:III.2707.A.3*)

Name of Louisiana Accredited Inspector:	
Louisiana Accredited Inspector Signature:	
Louisiana DEQ Accreditation No:	
Expiration Date:	

STATE BUILDING EXEMPTION (Continued) (LAC 33:111.2735.C)

*Please note that, in accordance with LAC 33:III.2735.B, "If ACBM is subsequently found in a homogeneous or sampling area of the state government [the responsible party for the state building] that had been identified as receiving an exclusion by an accredited inspector under Paragraph A.3, 4, or 5 of this Section, or an architect, project engineer, or accredited inspector under Paragraph A.7 of this Section, the state government [responsible party for the state building] shall have 180 days following the date of identification of ACBM to comply with this Chapter."

SCHOOL BUILDING EXCLUSIONS (LAC 33:111.2735)

- I. If the following exclusions apply, complete pages 1, Section A, and provide supporting evidence as applicable.
 - a. An architect or project engineer responsible for the <u>construction of a new school building built</u> <u>after October 12, 1988</u>, or an accredited inspector signs a statement that no ACBM was specified as a building material in any construction document for the building or, to the best of his or her knowledge, no ACBM was used as a building material in the building. The local education agency shall submit a copy of the signed statement of the architect, project engineer, or accredited inspector to the Office of Environmental Services and shall include the statement in the management plan for that school.

The signed statement (supporting evidence) shall be placed behind this Section.

*Please note that, in accordance with LAC 33:III.2735.B, "If ACBM is subsequently found in a homogeneous or sampling area of a local education agency or the state government [responsible party for the state building] that had been identified as receiving an exclusion by an accredited inspector under Paragraph A.3, 4, or 5 of this Section, or an architect, project engineer, or accredited inspector under Paragraph A.7 of this Section, the local education agency or the state government [responsible party for the state building] shall have 180 days following the date of identification of ACBM to comply with this Chapter."

b. If the school or state bldg has been abated, and a thorough reinspection has confirmed that there is <u>no friable and nonfriable known or assumed ACBM in each building, further reinspections</u> <u>are no longer required (LAC 33:III.2707.B.1).</u>

*Note in the management plan all of the information contained in the reinspection, including the inspection report, sampling and analysis report, inspector's name, address, contact information, including telephone no and email address, etc.

c. If the school meets either a. or b. above, periodic surveillance is no longer required.

*There are no exclusions from maintaining an Asbestos Management Plan for schools, which shall be kept in the administrative office for review. The management plan shall be available, without cost or restriction, for inspection by representatives of EPA and the state, and the public, including parents, teachers, other school or public personnel, and their representatives. The local education agency or the responsible party for the state building may charge a reasonable cost to make copies of management plans. (LAC 33:III.2723.F.1)

Section A

Print Legibly or Type

FACILITY INFORMATION (LAC 33:III.2723.D.1)

Building Information (Required): I.

Name of Building	Henry Heights Elementary		
Building Address	3600 Louisiana Avenue	:	
	City: Lake Charles	State: LA	Zip code: 70605
Date of Construction of Building	1960's era		

A. Mailing Information Required if for a School or School Building:

Responsible Official for School Print/Type Name & Title	Patrick Thomas		
School is Owned by:	Name of Building Owr	ner (School Board,	other)
□ City ⊠ Parish □ State □ Private	Calcasieu Parish Schoo	ol Board	
Mailing Address	3800 Mallard Cove Drive		
	City: Lake Charles	State: LA	Zip code: 70615

B. Lessor Information (Required if building is leased):

Lessor's Name					
Lessor's Address					
	City:		State:		Zip code:
Lessor's Contact Person					
Lessor's Email Address					
Lessor's Telephone No. ()		Lessor's Fax	x No. ()	

C.	Is Asbestos	present in the	building?
	🛛 Yes		No

D. Yes, the building contains: Friable ACBM Nonfriable ACBM Friable and Nonfriable suspected ACBM assumed to ACBM

 \triangleright

Section **B**

INSPECTIONS CONDUCTED

(Check Appropriate Box)

Inspections conducted <u>before</u> December 14, 1987 – Complete all Section A and B, Part I. (LAC 33:III.2723.D.2)

Inspections conducted <u>after</u> December 14, 1987 – Complete all Sections A-G, except Section B, Part I. (*LAC 33:III.2723.D.3 and 2707*)

If the inspection report was conducted <u>before</u> December 14, 1987, attach inspection report behind Section B, Part I.

If the inspection report was conducted <u>after</u> December 14, 1987, attach inspection report behind Section B, Part II.

Section B Part I

A. The following shall be included for each inspection conducted <u>before</u> December 14, 1987:

Date of Inspection (*LAC 33:III.2723.D.2.a*)

Bulk Sampling Location Diagram – (*LAC 33:III.2723.D.2.b*):

Location of Sampling Area	Approx. Square or Linear ft of any Homogeneous or Sampling Areas where Material was Sampled for Asbestos Containing Material (ACM)	Exact Locations where Bulk Samples were Collected	Date of Collection

Attach blueprints, diagrams or written descriptions of all homogeneous or sampling areas behind Section B, Part I.

form_7082_r00 Revised: 9/15/2011

Section B Part I

Analysis (*LAC 33:III.2723.D.2.c*):

- Copy of analyses of any bulk samples taken
- Date of Analyses
- Copy of any other lab reports pertaining to the analyses

Response Actions/Preventative Measures (*LAC 33:III.2723.D.2.d*):

- Description of any response actions or preventative measures taken to reduce exposure
- Names and addresses of the contractors involved
- Start and completion dates of the work
- Results of any air samples analyzed during and upon completion of work

A description of assessments, required to be made of material that was identified before December 14, 1987, as friable Asbestos Containing Building Material (ACBM), including all Thermal System Insulation (TSI) or friable suspected ACBM (*LAC 33:III.2723.D.2.e*).

Section B Part I

Accreditation information for each person making assessment (*LAC 33:III.2723.D.2.e*):

Name	Accreditation No	Expiration Date	Signature

Section B Part II

B. The following shall be included for each inspection conducted after December 14, 1987:

List the following information for each accredited inspector who performed the inspection and re-inspection(s). (*LAC* 33:III.2707.A.2, 2705, 2709, &2711). For state owned, leased or otherwise used state buildings only, 3 year re-inspections are not required; however, 6 month surveillance is required. Please attach a copy of each inspector's Louisiana DEQ accreditation certificate behind Section B, Part II.

Inspection/Re-inspection Date	Inspector's Name (Printed or Typed)	Louisiana Accreditation No	Inspector's Signature
9/20/22	Todd Peterson	MI165930	Tadelleteran
7/29/19	Todd Peterson	0I165930	Todel Peterson Todel Peterson Matter
6/29/16	Troy Hawthorne	7I190801	M tatto
See archive file data for			
records prior to 2016			

STATE OF LOUISIANA

DEPARTMENT OF ENVIRONMENTAL QUALITY

certifies that

William T Peterson

Has complied with all requirements of the Louisiana Department of Environmental Quality and is authorized to perform the duties of

Asbestos Inspector

Accreditation No. MI165930

AI No. 165930

Date of Issuance February 16, 2022

Expiration March 21, 2023

Failure to comply with all applicable provisions of La. R.S. 2025.E. (1)(a) and La. R.S. 2025.F. (2)(a) may result in civil and/or criminal enforcement actions by the State.

Permit Support Services Division Office of Environmental Services

Section B Part III

Sampling:

A. Attach a blueprint or diagram of the building which identifies each location where material was sampled for ACM. Assign a sample identifier to each sample collected.

Attach the document behind Section B, Part III. (LAC 33:III.2709)

- B. Attach a table of all the bulk samples collected, including the following: Attach the document behind Section B, Part III. (*LAC 33:III.2709*):
 - 1. The corresponding sample identifier.
 - 2. The approximate square or linear footage where material was sampled for ACM.
 - 3. The date of collection for each sample.
 - 4. Identify whether the sample collected was friable, nonfriable or assumed ACBM.
 - 5. Schematic of the building of floor documenting the location of the samples taken.
- C. Describe the manner used to determine sampling location. Attach written statement behind Section B, Part III. (*LAC 33:III.2709*)

See archive file data

Name of Louisiana Inspector Collecting Samples:	Todd Peterson
Accredited Inspector's Signature:	Todeleteren
Louisiana Accreditation No.:	MI165930
Date of Expiration:	03/21/2023

form_7082_r00 Revised: 9/15/2011

2013 Re-Inspection and Asbestos Management Plan Update

for

Calcasieu Parish School Board

Henry Heights Elementary School 3600 Louisiana Avenue Lake Charles, Louisiana

July 2013

13027

Prepared by:

Wyan & White

Wynn L. White Consulting Engineers, Inc. P.O. Box 83527 Baton Rouge, LA 70884-3527 (225) 761-9141 (225) 761-4450 Fax

I. Introduction

A. Summary

The visual re-inspection found friable ACBM in the facility. The friable ACBM, pipe insulation, is in good overall condition and may remain in the facility until its condition deteriorates or is affected by renovation or demolition.

B. Background

The Asbestos Hazard Emergency Response Act (AHERA) became law on October 12, 1986. The law required Environmental Protection Agency (EPA) to develop regulations addressing asbestos in schools. The Louisiana Legislature enacted Title 33, Environmental Quality, Part III Air, Chapter 27 Asbestos-Containing Materials in Schools and Public Buildings Regulations on September 20, 1989. The Louisiana act follows the AHERA regulations and applies to State owned or leased buildings. This re-inspection report is prepared according to AHERA and Louisiana guidelines.

- II. Inspection Results
 - A. Purpose and Inspection Data

The purpose of the re-inspection is to locate and assess ACBM. The building was inspected, suspect materials located, and the condition assessed. The building was re-inspected to identify and assess asbestos containing building materials on July 29, 2013. The inspection and assessment were performed by Chris White, who is a Louisiana Department of Environmental Quality accredited Inspector (#3I95575).

B. Friable Asbestos Assessments

The friable ACBM is assigned a Hazard Rank of 2.

III. Recommended Preventive Measures and Response Actions

The visual re-inspection found friable ACBM in the facility. The friable ACBM, pipe insulation, is in good overall condition and may remain in the facility until its condition deteriorates or is affected by renovation or demolition.

IV. Asbestos Remaining Upon Completion of Response Actions

The friable ACBM is in good overall condition and may remain in the facility.

Page 1 of 2

V. Re-inspection, Operation and Maintenance Activities, and Periodic Surveillance Implementation Schedule

Periodic Surveillance of the facility is required every six (6) months to assess the condition of the asbestos containing materials remaining in the building. Reinspection is required every three (3) years until the asbestos containing materials are removed. Below is a schedule for periodic surveillance and re-inspection:

Periodic Surveillance Periodic Surveillance Periodic Surveillance Periodic Surveillance Periodic Surveillance Re-inspection January 2014 July 2014 January 2015 July 2015 January 2016 July 2016

VI. Information Program

Training of custodians or maintenance personnel is required if the building contains asbestos, and should be completed within thirty (30) days of employment. Documentation of training shall be placed with the Management Plan for the facility. Calcasieu Parish School Board shall notify in writing occupants of the building of the availability of the management plan.

VII. Resource Evaluation

The estimated annual cost for training and periodic surveillance is three hundred dollars (\$300). The estimated cost to remove the asbestos containing materials, including consultant costs, is twenty-five thousand dollars (\$25,000).

VIII. Consultant Data

Wynn L. White Consulting Engineers, Inc. used LDEQ accredited personnel to carry out the re-inspection of the facility. The following personnel were involved in preparation of the re-inspection report: Chris White (Inspector No. 3i95575) and Wynn L. White (Management Planner No. 3P95572).

IX. Designated Person


Mitch Trahan has been designated to see that the duties required by AHERA and LAC 33:III.Chapter 27.H are carried out. Mr. Trahan's office is located at the Chennault Airport in Lake Charles, Louisiana.

X. Conclusion

The visual re-inspection found friable ACBM in the facility. The friable ACBM, pipe insulation, is in good overall condition and may remain in the facility until its condition deteriorates or is affected by renovation or demolition.

Page 2 of 2

HENRY HEIGHTS ELEMENTARY SCHOOL



Section B Part IV

A. Laboratory and Analysis Information (LAC 33:III.2711)

In accordance with LAC 33:I.Chapter 45, LELAP Accreditation is required by laboratories performing analysis. Attach a copy of the LELAP accreditation certificate behind Section B, Part III.

Attach a copy of the analyses of any bulk samples collected and analyzed. Place analyses report behind Section B, Part IV of the application. The Lab analysis MUST include the following:

 \boxtimes Name of Laboratory that analyzed the bulk samples;

Address of Laboratory;

Statement that Laboratory meets the requirements of *LAC 33:III.2711.A*;

Date of Analysis;

 \bowtie Name of person performing the analysis; and

 \boxtimes Signature of person performing the analysis.

B. Assessment (LAC 33:III.2713)

Within 30 days of the assessment, an accredited inspector shall provide a written assessment required by LAC 33:III.2713 for all ACBM and suspected ACBM assumed to be ACM. Classification shall be given as indicated in LAC 33:III.2713.B.1-7, eg. indicate whether the ACM is damaged or significantly damaged thermal system insulation, damaged friable surfacing, etc. Write in space below or attach written statement behind Section B, Part IV.

Check if there is no ACM is in the building:

See archive file information

Name of Louisiana Inspector Collecting Samples: Todd Peterson

Tadel Peterson

Accredited Inspector's Signature: Louisiana Accreditation No.: Date of Expiration:

MI165930 03/21/2023

form 7082 r00 Revised: 9/15/2011

Section C

<u>DESIGNATED PERSON</u> (LAC 33:III.2705.A.7 and 2705.A.8)

Name of Designated Person:	Patrick Thomas
Address of Designated Person:	3800 Mallard Cove Drive Lake Charles, LA 70615
Phone Number:	337-217-4350
Fax Number:	337-217-4351
E-mail of Designated Person:	patrick.thomas@cpsb.org

Attach copy of the training certificate received by the Designated Person from a recognized trainer. Place the certificate behind Section C. You may find a list of Training Providers that teach this course on the Asbestos Web page at http://www.deq.louisiana.gov/portal/tabid/2883/Default.aspx.

Course Name:	Asbestos Contractor Supervisor Refresher
Date of Training:	1/7/2022
Length of Training (hours):	8
Training Organization:	Mendez Environmental
Instructor(s):	Kim D. Chapital

Note: Training must be completed within 6 months of submitting the Management Plan to LDEQ.

CERTIFICATE OF TRAINING

EPA/AHERA Training Program



This is to certify that

PATRICK R. THOMAS LA. DL. 004 256 235

Has completed 8 hours of training and PASSED the test required by LAC 33:III.2799, Appendix A; Section 206 of TSCA Title II and in accordance with LOUISIANA STATE ASBESTOS REGULATIONS entitled

ASBESTOS CONTRACTOR SUPERVISOR REFRESHER (English)

Presented by Mendez Environmental ™ 1005 Veterans Memorial Blvd, Suite 101 ~ Kenner, LA 70062 Phone: (504) 468-8858 ~ Fax: (504) 541-0989 www.mendezenvironmental.com

Director:

Course Date: 01/07/2022

Josefina Mendez-Rosa

Certificate Number: AS0122KLAPPT24383

Instructor:

Test Date: 01/07/2022 Grade: PASS Expiration Date: 01/07/2023





Section D

RESPONSE ACTIONS

A. Attach recommendations made to the <u>local education agency</u> (LEA) regarding Response Actions under *LAC 33:III.2717*. Attach recommendations behind Section D.

Check if the building is <u>NOT</u> used for Educational purposes.

Check if there is no ACM in the building.

Name of Person Making Recommendation:	Chris White, P.E.	
Recommendation Person's Signature:	Chis white	
Louisiana DEQ Accreditation No:	JP095575	
Date of Expiration:	1/17/2023	

Section D

B. Provide the following written detailed description of preventive measures/response actions to be taken for any friable ACBM, including the following: (*LAC 33:III.2723.D.6*) Recordkeeping Requirements are to be maintained as part of the management plan (*LAC 33:III.2725*)

Methods to be used	The reinspection found friable and non-friable ACBM in the facility. The friable ACBM, pipe insulation, and non-friable flooring in good general condition may remain in the facility until the condition deteriorates or disturbed by renovation or demolition.
Location where measure or action will be taken	Main building
Reason for selecting response action or preventive measure	Condition of material
Beginning date	6/1/2017
Completion date	To be determined

Section D

- C. Provide a detailed description in the form of blueprint, diagram, or written location description of ACBM, or assumed ACM, that does or will remain after response action. Attachment, if any should be placed behind Section D. (*LAC 33:III.2723.D.8*)
 - Check if there is no ACM in the building.
- D. The undersigned does hereby certify that he/she is accredited under the provision of Appendix A of *LAC 33:III.2799.Appendix A*. (This applies to the person who inspected for ACBM and who will design or carry out response action, except O & M). (*LAC 33:III.2723.D.7*)

Name of Louisiana Inspector Collecting Samples:	Todd Peterson
Accredited Inspector's Signature:	Todel Clerson
Louisiana Accreditation No:	MI165930
Date of Expiration:	03/21/2023
Louisiana Accredited Project Designer's Name:	

Louisiana Accredited Project Designer's Name:	
Project Designer's Signature:	
Louisiana DEQ Accreditation No:	
Date of Expiration:	

Section E

ACTIVITY PLANS (LAC 33:III.2723.D.9)

Check if there is no ACM in the building.

If there is ACM in the building, attach the following:

A. Attach a written plan for Re-inspection behind Section E (Required <u>only</u> for schools, including post graduate facilities, i.e. universities, etc. in accordance with *LAC 33:III.2707*).

B. Attach a written plan for Periodic Surveillance behind Section E (Required for <u>all</u> schools <u>and</u> state owned, leased, or otherwise used buildings *LAC 33:III.2721.B*).

C. Attach a copy of the Operations and Maintenance plan behind Section E. The O & M plan must be completed in accordance with *LAC 33:III.2719*.

D. Attach a copy of the Management Planner's recommendation regarding additional cleaning under *LAC 33:III.2719.C.2* as part of an operations, maintenance, and repair program.

E. Attach a copy of the Response to the Management Planner's recommendation by the local education agency (LEA) or owner or responsible party of the state owned, leased or used building.

Section E Additional Data

Periodic Surveillance/Reinspection Plan:

Periodic Surveillance: January 2020

Periodic Surveillance: July 2020

Periodic Surveillance: January 2021

Periodic Surveillance: July 2021

Periodic Surveillance: January 2022

Reinspection: July 2022

Management planner's recommendation regarding additional cleaning: None at this time.

Response to management planner's recommendation regarding additional cleaning: not yet

programmed.

Section F

NOTIFICATIONS AND RESOURCES EVALUATION

Attach the following behind Section F:

NOTIFICATION

Attach a copy of the notification letter sent to parents, teachers, and employees concerning the availability of the Management Plan, including any response actions or activities that took place. Attach behind Section F. (*LAC 33:III.2723.F and LAC 33:III.2723.D.10*)

RESOURCES EVALUATION

Attach an evaluation of resources needed to complete response actions successfully and carry out re-inspection(s), operations and maintenance activities, periodic surveillance, and training. Attach behind Section F. (*LAC 33:III.2723.D.11*)

Section F Additional Data

Resource Evaluation:		
Reinspection conceptual budget: \$350		
Operations and Maintenance conceptual budget: \$500 implementation		
Annual Periodic Surveillance conceptual budget: \$300		
Annual training conceptual budget: \$300		
Asbestos Abatement Conceptual Budget (Construction): \$25,000		

TRANSMITTAL LETTER

DATE: September 23, 2015

TO: All Principals and Building supervisors

From: Mitch Trahan

Planning & construction/ AHERA

P.O. Box 800

Lake Charles, La.70602

We transmit the attached correspondence, directives or documents for your information. If you have any questions or comments fell free to contact me.

DESCRIPTION:

PLEASE POST THE ATACHED NOTIFICATION FOR THE PUBLIC

This is a requirement of the EP and DEQ offices.

Mitch Trahan

Mitch Trahan, Planning & construction/ AHERA

MT/eg

Enclosures:

Cc: Mr. Karl Bruchhaus

File



TO: Parents and Staff of Calcasieu Parish Schools

FROM: Mitch Trahan, Planning & construction / AHERA

DATE: September 23, 2015

In compliance with the U>S> Environmental Protection Agency 9EPA) Asbestos Hazard Response Act (AHERA), in the fall of 1988 we performed inspections of each of our school buildings for asbestoscontaining building materials. The inspection findings and asbestos management plans have been on file in each school administrative office since that time.

The EPA requires us to perform I inspections of the asbestos materials every three years. During the month of August 1988, accredited asbestos inspectors performed these inspections. An accredited management planner reviewed the results of the inspections and recommend actions we should take to safely manage each asbestos material in our buildings.

As designated and responsible person for the asbestos program for the Calcasieu Parish Schools, I agree with recommendations of Wynn White, Management Planner, for response actions he has recommended in the reinspections plans. I will follow his guidelines and time table for the removal of asbestos and continue our Operations and Management Program as set forth in the reinspection plan.

The results of the reinspections are on file in the management plan in the school's administrative office. Everyone is welcome to view these anytime during the normal school hours (M-F, 8:00 AM - 3:30 PM). The Asbestos Program Manager, Mitch Trahan, is available to answer any questions you may have about asbestos in our buildings at (337) 217-4350 Ext. 5104.

Sincerely, Mitch Traham

Mitch Trahan Planning & Construction/ AHERA MT/eg

Cc: File

Building Foundations for the Future



August 10, 2015

PUBLIC NOTICE

Public notice is hereby given that in compliance with the Asbestos Hazard Emergency Response Act (AHERA) of 1986, asbestos management plans for Calcasieu Parish Schools are available at the various schools and facilities upon request.

Gary Anderson Assistant Superintendent Human Resources/Auxiliary Services

Publish: American Press and Southwest Daily News August 14, 21, 28, 2015

Building Foundations for the Future



Publication: American Press; Date: Aug 14, 2015; Section: Classified; Page: D4

LECALS CMT124CT005 Seeded III DIS for the lower protocol and the lower protocol and the lower protocol and the control layers protocol protocol layers LA Subject Control Layer Control and Jince East Subject Control Layer Control and Jince East Subject Late Controls LA Control and Layers Later Control and Later Control Later Control Later Control Later Control and Later Control La

Friday, August 21, 2015

available at the various schools and facilities upon request. Gary Anderson Assistant Superintendent Emergency Response Act (AHERA) of 1986, asbestos management plans for Calcasieu Parish Schools are PUBLIC NOTICE P u b I i c n o t i c e i s hereby given that in compliance with the Asbestos Hazard Human Resources/ Auxiliary Services Aug 14,21,28 3t 00925931

D4 AMERICAN PRESS FRIDAY AUGUST 28, 2015

PUBLIC NOTICE Public notice is compliance with the Asbestos Hazard Emer-(AHERA) of 1986, asbestos management plans for Calcasieu Parish the various schools and facilities upon request. Gary Anderson Superintendent Human Resourcest Auxiliary Services

Aug 14,21,28 00925931

4

Mandro P. C. Sandowski and Sand

AV Williem J. Rose, 111, Executive Orecord and Terminel District Jul 34-31, Avg 7,74 4 0072304

This is to odvise

Affidavit of Publication

STATE OF LOUISIANA Parish of Calcasieu

Before me the undersigned authority, personally came and appeared

hindaJrahan

who being duly sworn, deposes and says:

He/She is a duly authorized agent of LAKE CHARLES AMERICAN PRESS

a newspaper published daily at 4900 Highway 90 East, Lake Charles, Louisiana, 70615. (Mail address: P.O. Box 2893 Lake Charles, LA 70602)

The attached Notice was published in said newspaper in its issue(s) dated:

00925931 - \$25.00 August 14, 2015, August 21, 2015, August 28, 2015

inda Irahan

Duly Authorized Agent

Subscribed and sworn to before me on this 28th day of August, 2015 at Lake Charles LA un

Notary Public

06100179

CALCASIEU PARISH SCHOOL



PUBLIC NOTIC Public osuHazara IERA) of 19 Calcasieu is are availa rjous sch acilities upon re



August 10, 2015

PUBLIC NOTICE

Public notice is hereby given that in compliance with the Asbestos Hazard Emergency Response Act (AHERA) of 1986, asbestos management plans for Calcasieu Parish Schools are available at the various schools and facilities upon request.

Gary Anderson Assistant Superintendent Human Resources/Auxiliary Services

Publish: American Press and Southwest Daily News August 14, 21, 28, 2015

Building Foundations for the Future



August 10, 2015

Mark Hayes, President Calcasieu Association of Educators 300 East McNeese Street Ste. 4A Lake Charles, Louisiana 70605

Dear Mr. Hayes,

The Asbestos Hazard Emergency Response Act (AHERA) of 1986 requires that teacher and employee organizations be given written notification by the local education agency of the availability of management plans. This letter serves as our annual notification.

The principals and/or building administrators have the plans at this time and the plans are available upon request.

Please make this announcement available to your membership.

Thanks for your assistance in this matter.

Sincere Day Elinduson

Gary Anderson Assistant Superintendent Auxiliary Services

GA:dv

Building Foundations for the Future

MANAGEMENT PLAN CONTRIBUTORS

A. List the accredited management planner and all other consultants who contributed to the Management Plan. Attach Louisiana accreditation certificate for <u>current</u> asbestos management planner behind Section F. (*LAC 33:III.2723.D.12*)

Name	Accreditation No.	Expiration Date	Signature	Email address
Chris White	JP095575	1/17/23	Chis White	cwhite@wynnwhite.com
Chris White	9195575	12/22/19	Chis White	cwhite@wynnwhite.com
Wynn White	9P95572	12/21/19	Wyan X White	wwhite@wynnwhite.com

STATE OF LOUISIANA

DEPARTMENT OF ENVIRONMENTAL QUALITY

certifies that

Christopher M White

Has complied with all requirements of the Louisiana Department of Environmental Quality and is authorized to perform the duties of

Asbestos Management Planner

Accreditation No. JP095575

AI No. 95575

Date of Issuance February 4, 2022

Expiration January 17, 2023

Failure to comply with all applicable provisions of La. R.S. 2025.E. (1)(a) and La. R.S. 2025.F. (2)(a) may result in civil and/or criminal enforcement actions by the State.

Permit Support Services Division Office of Environmental Services

B. THIRD PARTY ASBESTOS MANAGEMENT PLAN REVIEWER (optional)

A local education agency or the responsible party for the state building <u>may</u> require each management plan to contain a statement signed by a third party accredited management planner as a reviewer to the current accredited management planner, that such person has prepared or assisted in the preparation of such plan or has reviewed such plan, and that such plan is in compliance with *LAC 33:III.Chapter 27*. (*LAC 33:III.2723.E*)

 $\hfill\square$ Statement is Required by LEA or State $\hfill \boxtimes$ Statement is NOT Required by LEA or State

The undersigned does hereby certify that they have reviewed the management plan and testify that the plan complies with *LAC 33:III.2723* of the Louisiana Air Quality regulations. (Statement may NOT be signed by a person who, in addition to preparing or assisting in preparing the Management Plan, also implements or will implement the Management Plan). If signed, attach copy of current management planner accreditation certificate behind Section F. (optional as part of *LAC 33:III.2723.E*)

Name of Louisiana Accredited <u>Reviewing</u> Management Planner:

Section G Part I

RECORDKEEPING

PREVENTATIVE MEASURES/ RESPONSE ACTIONS

For each preventative measure and response action performed after December 14, 1987, the local education agency or responsible party for the state building shall provide the following information:

- A. A detailed written description of the action taken. The description should include the following information. Attach behind Section G, Part I. (*LAC 33:III.2725.B.1*)
 - Methods Used
 - Location of Measure or Action
 - Reason for Selection of Action
 - Names and Addresses of all Contractors Involved
 - Louisiana Accreditation Number of Contractor/Supervisor(s)
 - Storage or Disposal Site if ACM was Removed

B. The name and signature of any person collecting air samples required at the completion of response actions. (*LAC* 33:III.2725.B.2) Note that the person conducting air monitoring must be LDEQ accredited as an asbestos Contractor/Supervisor.

Name	Accreditation No	Expiration Date	Signature
See archive file data			

- C. A written description of the locations where samples were collected. The following information should be included in the description. Attach behind Section G, Part I. (*LAC 33:III.2725.B.2*) Note that the laboratory conducting analysis of air samples must be a LELAP accredited lab. Attach a copy of the LELAP certificate behind Section G, Part I.
 - Date of Collection
 - Name and Address of Analyzing Laboratory
 - Date of Analysis
 - Results of Analysis
 - Methods of Analysis
 - Name and Signature of Analyst
 - LELAP Laboratory Accreditation Certificate

EMPLOYEE TRAINING:

List each person required to be trained under *LAC 33:III.2721.A.1-3* and for supervisors who direct workers who may disturb ACM. <u>Note:</u> all members of its custodial and maintenance staff who may work in a building that contains ACBM, whether or not they are required to disturb ACBM, shall receive **at least two hours of awareness training** within 60 days after commencement of employment; and staff who conduct any activities that will result in disturbance of 3 square or linear feet of ACBM shall receive **14 hours of additional training**. The following information must be provided for each employee trained. (*LAC 33:III.2725.C*) Attach behind Section G, Part I.

Name	Job Title	Date of Training Completed	Location of Training	Trainer/ Trainer Provider	Number of Hours Completed
See archive file data					

Section G Part II

SURVEILLANCE

List each time that a periodic surveillance under *LAC 33:III.2721*.B is performed. (*LAC 33:III.2723.D*)

Date of	Name	Louisiana	Expiration	Changes in Conditions
Periodic	(Printed or Typed)	Accreditation	Date	
Surveillance		No.		
See archive				
file data				

Section G Part III

CLEANING

List each time that cleaning under *LAC 33:III.2719.C* is performed. (*LAC 33:III.2725.E*)

Date of	Name	Locations Cleaned	Methods used to perform cleaning
Cleaning	(Printed or Type)		
See archive			
file data			

Section G Part IV

O & M ACTIVITIES

List the following information for each Operation and Maintenance activity conducted after December 14, 1987: (*LAC 33:III.2725.F*) Attach behind Section G, Part IV.

- Name of Person(s) Performing the Activity
- Start and Completion Dates for each Activity
- Location where Such Activity Occurred
- Description of Activity
- If Asbestos was Removed, the Name and Location of Storage or Disposal Site

MAINTENANCE ACTIVITIES OTHER THAN SMALL SCALE SHORT DURATION (SSSD)

List the following information for each time a major asbestos activity under *LAC 33:III.2719.E* is performed: (*LAC 33:III.2725.G*) Attach behind Section G, Part IV.

Name of the Person	Start/Completion	Location	Description of the Activity	If Asbestos was Removed Name and Location of Storage and Disposal Site
Performing the Activity See archive file data	Dates		Activity	Location of Storage and Disposal Site

FIBER RELEASE EPISODE

For each fiber release episode that has occurred post December 14, 1987, list the following information: (*LAC 33:III.2725.H*) Attach behind Section G, Part IV.

- Date and Location of Episode
- Method of Repair
- Preventive Measures or Response
- Name of Person Performing the Work
- If Asbestos was Removed, the Name and Location of Storage and Disposal Site

DESIGNATED PERSON GENERAL RESPONSIBILITIES UNDER LAC 33:III.Chapter 27

Pursuant to *LAC 33:III.2705.A* and *LAC 33:III.2723.H* of the Louisiana Air Quality Regulations, (Asbestos-Containing Materials in Schools and State Buildings), each Management Plan must contain a true and correct statement, signed by the Designated Person, that certifies that the general Management Plan responsibilities have been met. This form is provided to assist you in complying with this portion of *LAC 33:III.Chapter 27*.

School/Agency:	Henry Heights Elementary			
Building Address:	3600 Louisiana A	3600 Louisiana Avenue, Lake Charles, LA 70605		
Designated Person:	Patrick Thomas			
Designated Person's	3800 Mallard Cove Drive			
Address:				
City: Lake Charles	State: LA		Zip Code: 70615	
Phone No: 337-217-4350)	Email: patrick.thomas@cpsb.org		

ASSURANCES

This asbestos Management Plan was developed and has been submitted pursuant to *LAC* 33:III.Chapter 27 of the Louisiana Air Regulations, Asbestos-Containing Materials is Schools and States Buildings, and the undersigned does hereby certify that the Designated Person has and will ensure the following:

- \boxtimes 1) The activities of any person, who performs inspections, re-inspections, and periodic surveillance, develops and updates Management Plans, and develops and implements response actions, including operations and maintenance, are carried out in accordance with *LAC 33:III.Chapter 27*.
- 2) All custodial and maintenance employees are properly trained as required in *LAC* 33:III.Chapter 27 and all other applicable federal and/or state regulations (e.g., the Occupational Safety and Health Administration Asbestos Standard for Construction, the EPA Worker Protection Rule, or applicable state regulations).
- 3) All workers and building occupants, or their legal guardians, are informed annually about inspections, response actions, post-response action activities, including periodic re-inspection, if applicable, and surveillance activities, that are planned or in progress.
- (1) All short-term workers (e.g., telephone repair workers, utility workers, or exterminators etc.) who may come in contact with asbestos in a school are provided information

form_7082_r00 Revised: 9/15/2011 regarding the locations of ACBM and suspected ACBM assumed to be ACM.

- 5) All warning labels are posted in accordance with *LAC 33:III.2727*.
- 6) All management plans are available for inspection and that notification of such availability has been provided as specified in the Management Plan under *LAC* 33:III.2723.F.
- 7) The undersigned Designated Person pursuant to *LAC 33:III.2705.A.7* received adequate training as stipulated in *LAC 33:III.2705.A.8*.
- 8) The Designated Person will consider whether any conflict of interest may arise from the interrelationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under *LAC 33:III.Chapter 27*.

Signature:	signature unavailable Designated Person, pursuant to <i>LAC 33:III.2723.H</i>	Phone No: _	337-217-4350
Email Add	ress: <u>patrick.thomas@cpsb.org</u>	Fax No:	337-217-4351