

Bradford Intermediate School		Sampled 4/26/2022	Status
SampleNumber	Description	Lead Results (ppb)	
05200-203H-DFL	Hallway Drinking Fountain across from Gym/Left	<0.1*	
05200-203H-DFR	Hallway Drinking Fountain across from Gym/Right	<0.1*	
05200-2022-203H-WBFS	Water Bottle Filling station across from Gym	<0.1*	
05200-210-S4	Food Service Sink-Food Prep	2.8	
05200-201-SWB	Sink with Bubblers in Music Room	1.4	
05200-201-S	Sink in Music Room	12.2	Repairs Pending
05200-181H-DF	Hallway Drinking Fountain near Library	0.2	
05200-018-SWB	Sink with Bubblers in Classroom 018	0.2	
05200-017-SWB	Sink with Bubblers in Classroom 2 (Room 017 per Facilities Floor Plan)	1.3	
05200-016-SWB	Sink with Bubblers in Classroom 3 (Room 016 per Facilities Floor Plan)	0.2	
05200-015-SWB	Sink with Bubblers in Classroom 4 (Room 015 per Facilities Floor Plan)	0.1	
05200-014-SWB	Sink with Bubblers in Classroom 5 (Room 014 per Facilities Floor Plan)	4.5	
05200-013-SWB	Sink with Bubblers in Classroom 6 (Room 013 per Facilities Floor Plan)	0.5	
05200-012-SWB	Sink with Bubblers in Classroom 7 (Room 012 per Facilities Floor Plan)	0.3	
05200-011-SWB	Sink with Bubblers in Classroom 8 (Room 011 per Facilities Floor Plan)	0.4	
05200-010-SWB	Sink with Bubblers in Classroom 9 (Room 010 per Facilities Floor Plan)	0.4	
05200-009-SWB	Sink with Bubblers in Classroom 10 (Room 009 per Facilities Floor Plan)	0.6	
05200-008-SWB	Sink with Bubblers in Classroom 11 (Room 008 per Facilities Floor Plan)	0.4	
05200-007-SWB	Sink with Bubblers in Classroom 12 (Room 007 per Facilities Floor Plan)	0.2	
05200-006-SWB	Sink with Bubblers in Classroom 13 (Room 006 per Facilities Floor Plan)	0.3	
05200-005-SWB	Sink with Bubblers in Classroom 14 (Room 005 per Facilities Floor Plan)	1.1	
05200-004-SWB	Sink with Bubblers in Classroom 15 (Room 004 per Facilities Floor Plan)	0.2	
05200-001-SWB	Sink with Bubblers in Classroom 16 (Room 001 per Facilities Floor Plan)	1.6	
05200-002-SWB	Sink with Bubblers in Classroom 17 (Room 002 per Facilities Floor Plan)	3.1	
05200-003-SWB	Sink with Bubblers in Classroom 18 (Room 003 per Facilities Floor Plan)	0.3	
05200-114-S	Sink in Teacher's Lounge	0.4	
05200-106-S	Sink in Clinic	39.4	Repairs Pending
05200-106-SWB	Sink with Bubblers in Clinic	0.6	

\* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.