


Neighbor Bowl

New Entrance & Remodel
Schematic Design Presentation



Hanford Joint Union High School District

Site Plan



9. New Scoreboard
Replace Existing Scoreboard with New LED Scoreboard In Existing Concrete Block Enclosure and Repair Mowstrip

Existing Home Bleacher Capacity: **3,071**
New Home Bleacher Capacity:..... **3,008**
Existing Visitor Bleacher Capacity:..... **1,055**
New Visitor Bleacher Capacity:..... **1,477**

12. Expand Visitor Grandstand Seating
In Lieu of Artificial Turf, Expand the North and South End Grandstands With New Sections of Concrete Bleacher Seating

4. Visitor Grandstand Repairs & Upgrades
Partial Berm Removal, Path of Travel Upgrades, Creation of Accessible Wheelchair Seating Zones, Intermediate Aisle Handrails, Concrete Grandstand Surface Repairs, Replace Track Separation Fencing, New Concrete Walk, New Retaining Curbs, Two New Concrete Ramps Up The Berm, Visitor Restroom Bldg. Accessibility Upgrades.

10. New Kensington Way Bus Loading Zone
Create New Pull-Out Bus Loading Zone On West Side of Kensington Way Adjacent the Neighbor Bowl

3. Home Grandstand Repairs & Upgrades
Path of Travel Upgrades, Creation of Accessible Wheelchair Seating Zones, Intermediate Aisle Handrails, Mid Aisle Step Correction, Concrete Grandstand Surface Repairs, Replace Track Separation Fencing

6. Berm Landscape Restoration
Miscellaneous Landscape and Concrete Removal, Reshape Berm Contours, New Landscape & Irrigation System

5. Perimeter Fence Replacement
Chain-Link Fence Removal and Replacement Sometimes in New Locations, Some New Retaining Curbs. 10' Section at OH Area.

1. New Entry Plaza and Fence
Path of Travel Upgrades, Partial Berm Removal, New Concrete Walk, New Planters, New Retaining Curbs, New Ornamental Fence and Gates, New Flagpoles, New Exterior Path Lights, and Emergency Exit Lighting

2. New Restroom/Snack/Ticket Bldg

11. Re-Surface All-Weather Track
Remove Existing Rubberized Surface and Replace with New and Stripe

8. Seal Coat Home Asphalt Paving
Repair Extreme Cracks and Apply New Emulsion Seal Coat To Asphalt

13. Over-sized Bowl Name Signage

7. Team Entry Tunnel Replacement
Demo Existing Tunnel, Partial Berm Removal, Construct New Concrete Tunnel Twice as Wide as Previous, Add New Chain Link Gates


	Large River Cobble		Concrete Walk
	Natural Turf		Planter
	Gunite		All-Weather Track
	Artificial Turf		Asphalt Paving



Hanford Joint Union High School District

Floor Plan

2,132 S.F.



Hanford Joint Union
High School District

06/2022



Hanford Joint Union High School District

Main Entrance
Aerial Perspective



Hanford Joint Union High School District

Main Entrance



Hanford Joint Union High School District

Snack Bar & Restrooms




Hanford Joint Union
High School District

Snack Bar




Hanford Joint Union High School District

Snack Bar Stadium Perspective



Hanford Joint Union
High School District

Team Entry Tunnel



Hanford Joint Union
High School District

Over-sized Bowl Name Signage



Neighbor Bowl

New Entrance & Remodel
Schematic Design Presentation

