

Lead in Water Testing Results
 South Washington County Schools
Grey Cloud Elementary School – 9525 Indian Blvd S, Cottage Grove, MN 55016

On March 8th, 2024, Grey Cloud Elementary School’s drinking water was tested for the concentration of lead.

The following water sources tested less than our action level of 5 parts-per-billion (ppb), no action will be taken to these water sources at this time.

LOCATION	SOURCE	RESULT (ppb)
Room 005	SINK	1.86
Room 006	SINK	1.51
Room 101	SINK	2.10
Room 102	SINK	2.51
Room 115	SINK	< 1.00
Room 116	SINK	< 1.00
Room 117	SINK	1.03
Room 118	SINK	< 1.00
Room 120	SINK	< 1.00
Room 121	SINK	1.20
Room 122	SINK	1.18
Room 123	SINK	1.31
Room 125	SINK	< 1.00
Room 126	SINK	3.03
Room 128	SINK	1.20
Room 129	SINK	1.35
Room 130	SINK	1.12
Room 131	SINK	1.06
Room 132	SINK	< 1.00
Room 133	SINK	1.13
Room 134	SINK	< 1.00
Room 135	SINK	1.07
Room 136	SINK	1.21
Room 137	SINK	1.12
Room 138	SINK	1.25
Room 200	SINK (by bathroom)	2.34
Room 301	SINK	3.35
Room 302	SINK	2.29
Room 303	SINK	4.35
Room 304	SINK	4.62
Room 305	SINK	3.31
Room 306	SINK	4.52

Hallway, north	BOTTLE FILLER	< 1.00
Gym C	BOTTLE FILLER	< 1.00
Hallway, outside 117	SINK	< 1.00
Hallway, outside 118	SINK	1.92
Hallway, outside 123	SINK	2.23
Hallway, outside 124	SINK	1.87
Hallway, outside 129	SINK	3.70
Hallway, outside 130	SINK	1.58
Hallway, outside 135	SINK	2.17
Hallway, outside 136	SINK	2.82
Hallway, by gym	BOTTLE FILLERq	< 1.00
Hallway, by gym	FOUNTAIN	< 1.00
Hallway, north	FOUNTAIN (left)	< 1.00
Hallway, north	FOUNTAIN (right)	< 1.00
Hallway, northeast	FOUNTAIN	< 1.00
Hallway, south	FOUNTAIN (left)	< 1.00
Hallway, south	FOUNTAIN (right)	< 1.00
Hallway, southeast	FOUNTAIN	< 1.00
Hallway, southwest	FOUNTAIN (left)	< 1.00
Hallway, southwest	FOUNTAIN (right)	< 1.00
Kitchen	SINK	1.25
Media Center Workroom	SINK (left)	2.85
Nurse's Office	SINK	< 1.00
Staff Dining	SINK	< 1.00
Office Workroom	SINK	< 1.00

The following water sources tested above the action level of 5 parts-per-billion (ppb) for the concentration of lead. These sources will not be used for consumption without remediation and re-testing. Actions taken are listed below.

LOCATION	SOURCE	RESULT	ACTION
Room 119	SINK	9.29	Identified and labeled as handwashing sink only
Room 124	SINK	13.4	Identified and labeled as handwashing sink only
Room 200	SINK	7.50	Identified and labeled as handwashing sink only
Room 201	SINK (bath)	7.08	Identified and labeled as handwashing sink only
Room 201	SINK	11.3	Identified and labeled as handwashing sink only
Kitchen	SPRAYER	7.71	Identified and labeled as handwashing sink only

