

Lead in Water Testing Results  
 South Washington County Schools  
**Lake Middle School – 3133 Pioneer Drive, Woodbury, MN 55125**

On March 5<sup>th</sup>, 2024, Lake Middle School’s drinking water was tested for the concentration of lead.

The following water sources tested less than our action level of 5 parts-per-billion (ppb), no action will be taken to these water sources at this time.

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULT (ppb)</b>
Room A 141	SINK	< 1.00
Hallway, A pod	FOUNTAIN (right)	< 1.00
Hallway, B pod	FOUNTAIN (left)	< 1.00
Room B115	SINK	< 1.00
Room A114	SINK (left)	1.55
Room C125	BOTTLE FILLER	< 1.00
Room G103	SINK	1.03
Hallway, A pod	BOTTLE FILLER	< 1.00
Hallway, A pod	FOUNTAIN (left)	< 1.00
Hallway, B pod	FOUNTAIN (right)	< 1.00
Hallway, C pod	BOTTLE FILLER	< 1.00
Hallway, C pod	FOUNTAIN	< 1.00
Hallway, by E129	FOUNTAIN (left)	< 1.00
Hallway, by E129	FOUNTAIN (right)	< 1.00
Hallway, by Gym A	FOUNTAIN	< 1.00
Hallway, by Gym B	BOTTLE FILLER	< 1.00
Hallway, by Gym B	FOUNTAIN (right)	< 1.00
Hallway, by Gym B	FOUNTAIN (left)	< 1.00
Hallway, by main door	FOUNTAIN	< 1.00
Kitchen	SPRAYER	< 1.00
Lobby	FOUNTAIN (left)	< 1.00
Lobby	FOUNTAIN (right)	< 1.00
Nurse’s Office	SINK	< 1.00
Office Workroom	SINK	4.84
Lobby	BOTTLE FILLER	< 1.00

The following water sources tested above the action level of 5 parts-per-billion (ppb) for the concentration of lead. These sources will not be used for consumption without remediation and re-testing. Actions taken are listed below.

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULT</b>	<b>ACTION</b>
Concessions	SINK	5.61	Identified and labeled as handwashing sink only
Room A114	SINK (right)	11.3	Identified and labeled as handwashing sink only
Kitchen	SINK	7.70	Identified and labeled as handwashing sink only