

Lead in Water Testing Results
 South Washington County Schools
Woodbury Middle School – 1425 School Drive, Woodbury, MN 55125

On March 5th, 2024 Woodbury Middle School’s drinking water was tested for the concentration of lead.

The following water sources tested less than our action level of 5 parts-per-billion (ppb), no action will be taken to these water sources at this time.

LOCATION	SOURCE	RESULT (ppb)
A109	SINK	2.52
Hallway, by B113	SINK	1.34
Hallway, by B113	BOTTLE FILLER	< 1.00
Cafeteria	BOTTLE FILLER	< 1.00
Cafeteria	FOUNTAIN	< 1.00
Hallway, D	FOUNTAIN	< 1.00
Hallway, F	BOTTLE FILLER	< 1.00
Hallway, G	BOTTLE FILLER	< 1.00
Hallway, G	FOUNTAIN (left)	< 1.00
Hallway, G	FOUNTAIN (right)	< 1.00
Hallway, Gym B	FOUNTAIN (left)	2.21
Hallway, Gym B	FOUNTAIN (right)	1.67
Hallway, Gym C	FOUNTAIN (left)	2.13
Hallway, Gym C	FOUNTAIN (right)	1.74
Hallway, H	FOUNTAIN (left)	< 1.00
Hallway, H	FOUNTAIN (right)	< 1.00
Hallway, by pool	FOUNTAIN	1.48
Hallway, by pool	BOTTLE FILLER	1.58
Hallway, by F218	FOUNTAIN	1.76
Hallway, by F212	FOUNTAIN	1.71
Hallway, by E202	FOUNTAIN	1.21
Kitchen	SINK	< 1.00
Kitchen	SPRAYER	< 1.00
Lobby	BOTTLE FILLER	< 1.00
Lobby	FOUNTAIN	< 1.00
Staff Dining	BRIO BOTTLE FILLER	< 1.00

The following water sources tested above the action level of 5 parts-per-billion (ppb) for the concentration of lead. These sources will not be used for consumption without remediation and re-testing. Actions taken are listed below.

LOCATION	SOURCE	RESULT (ppb)	ACTION
Nurse's Office	SINK	6.72	Identified and labeled as handwashing sink only
Staff Workroom	SINK	8.25	Identified and labeled as handwashing sink only
Hallway, by E207	FOUNTAIN	8.62	Shut off