Jamestown CSD

CAPITAL PROJECT PLANNING




HIGH SCHOOL

Essential Upgrades at **Old Gym** – Bleachers, Floors, Scoreboards, Etc.




Essential Upgrades at **Auditorium** – Ceiling, Sound Panels, Stage Floor




| _ | | |
|--|---|---|
| Scope Description | Sum | of Cost Repla |
| | | 1,712,000 |
| | | |
| ■ Roofs | \$ | 3,869,000 |
| ∀indows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | | 5,590,000 |
| ⊕ Fire Alarm | \$ | 1,247,000 |
| ● I.T Clocks | \$ | 104,000 |
| ■ I.T Data Wiring | \$ | 2,315,000 |
| ■ I.T Generator | \$ | 417,000 |
| I.T IS Office Renovation | \$ | 588,000 |
| ⊕ I.T PA | \$ | 520,000 |
| | \$ | 150,000 |
| ⊕ITWAN | \$ | 249,000 |
| ■ Interior Renovations | \$ | 20,210,000 |
| Auditorium Essential Upgrades (| \$ | 500,000 |
| ■ Basement & 2nd Floor Classrm, | \$ | 14,771,000 |
| Cafeteria & Kitchen Renovation | \$ | 3,873,000 |
| ■ Create Secure Vestibule @ Mair | \$ | 167,000 |
| ■ Old Gym Essential Upgrades (Bl- | \$ | 799,000 |
| Structural Repair - Joist Below F | \$ | 100,000 |
| ■ Mechanical Systems | \$ | 4,907,000 |
| Energy Recovery Unit | \$ | 124,000 |
| | | |
| ■ Exhaust Fans | \$ | 99,000 |
| ● Exhaust Fans● HVAC - IT | \$ | 99,000 252,000 |
| | | |
| ⊕ HVAC - IT | \$ | 252,000 |
| HVAC - IT HVAC Cafeteria | \$ | 252,000 347,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom | \$ \$ \$ | 252,000 347,000 4,043,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems | \$ \$ \$ \$ \$ \$ | 252,000 347,000 4,043,000 42,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems | \$ | 252,000 347,000 4,043,000 42,000 754,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems Backflow Prevention | \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems Backflow Prevention Fire Department Connections | \$ \$ \$ \$ \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems Backflow Prevention Fire Department Connections Pool Systems | \$ \$ \$ \$ \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 16,000 327,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems Backflow Prevention Fire Department Connections Pool Systems Water Fountains | \$ \$ \$ \$ \$ \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 16,000 327,000 290,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Plumbing Systems Backflow Prevention Fire Department Connections Pool Systems Water Fountains Site | \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 16,000 327,000 290,000 2,371,000 |
| HVAC - IT HVAC Cafeteria HVAC Classroom Pool Systems Backflow Prevention Fire Department Connections Pool Systems Water Fountains Site Parking Lots & Roadways | \$ | 252,000 347,000 4,043,000 42,000 754,000 121,000 327,000 290,000 2,371,000 1,508,000 |





Cafeteria







| Scope Description | Sun | m of Cost Replac |
|---|-----|------------------|
| ■ 2021 Capital Project | | 41,712,000 |
| | | |
| Boofs | \$ | 3,869,000 |
| ⊕ Windows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | 8 | 5,590,000 |
| ⊕ Fire Alarm | \$ | 1,247,000 |
| ® I.T Clocks | \$ | 104,000 |
| ® I.T Data Wiring | \$ | 2,315,000 |
| ● I.T Generator | \$ | 417.000 |
| ® I.T IS Office Renovation | \$ | 588,000 |
| ® I.T PA | \$ | 520,000 |
| ® I.T UPS | \$ | 150,000 |
| ⊕ I.T WAN | \$ | 249,000 |
| ■ Interior Renovations | | |
| Auditorium Essential Upgrades (| \$ | 500,000 |
| ■ Basement & 2nd Floor Classrm, | \$ | 14,771,000 |
| ⊕ Cafeteria & Kitchen Renovation | \$ | 3,873,000 |
| | \$ | 167,000 |
| Old Gym Essential Upgrades (Bl- | \$ | 799,000 |
| Structural Repair - Joist Below F | \$ | 100,000 |
| | | |
| ■ Energy Recovery Unit | \$ | 124,000 |
| | \$ | 99,000 |
| ⊕ HVAC - IT | \$ | 252,000 |
| ■ HVAC Cafeteria | \$ | 347,000 |
| ⊕ HVAC Classroom | \$ | 4,043,000 |
| ● Pool Systems | \$ | 42,000 |
| | | |
| ■ Backflow Prevention | \$ | 121,000 |
| ● Fire Department Connections | \$ | 16,000 |
| ● Pool Systems | \$ | 327,000 |
| Water Fountains | \$ | 290,000 |
| ■ Site | \$ | 2,371,000 |
| ⊛ Parking Lots & Roadways | \$ | 1,508,000 |
| ■ Retaining Wall - Allowance | \$ | 517,000 |
| ■ Sidewalks | \$ | 346,000 |
| | | |

Replace Out of Warranty **Roofs** – 25 Years Old



Replace Leaky, Difficult to Open, Windows – 35+ Years Old



HIGH SCHOOL

| Scope Description | Sum | of Cost Replac |
|---|------|----------------|
| ■ 2021 Capital Project | \$ 4 | 11.712.000 |
| Building Envelope | \$ | 7,880,000 |
| ■ Roofs | \$ | 3,869,000 |
| ■ Windows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | \$ | 5,590,000 |
| ● Fire Alarm | \$ | 1,247,000 |
| ● I.T Clocks | \$ | 104,000 |
| ⊕ I.T Data Wiring | \$ | 2,315,000 |
| ■ I.T Generator | \$ | 417,000 |
| ■ I.T IS Office Renovation | \$ | 588,000 |
| ⊕ I.T PA | \$ | 520,000 |
| ● I.T UPS | \$ | 150,000 |
| ● I.T WAN | \$ | 249,000 |
| ■ Interior Renovations | \$ | 20,210,000 |
| Auditorium Essential Upgrades (| \$ | 500,000 |
| ⊕ Basement & 2nd Floor Classrm, | \$ | 14,771,000 |
| ■ Cafeteria & Kitchen Renovation | \$ | 3,873,000 |
| ® Create Secure Vestibule @ Mair | \$ | 167,000 |
| ■ Old Gym Essential Upgrades (Bl- | \$ | 799,000 |
| Structural Repair - Joist Below F | \$ | 100,000 |
| ■ Mechanical Systems | | 4,907,000 |
| Energy Recovery Unit | \$ | 124,000 |
| ■ Exhaust Fans | \$ | 99,000 |
| ⊕ HVAC - IT | \$ | 252,000 |
| ■ HVAC Cafeteria | \$ | 347,000 |
| ■ HVAC Classroom | \$ | 4,043,000 |
| ■ Pool Systems | \$ | 42,000 |
| | | |
| Backflow Prevention | \$ | 121,000 |
| ● Fire Department Connections | \$ | 16,000 |
| ⊕ Pool Systems | \$ | 327,000 |
| Water Fountains | \$ | 290,000 |
| ■ Site | \$ | 2,371,000 |
| ■ Parking Lots & Roadways | \$ | 1,508,000 |
| ■ Retaining Wall - Allowance | \$ | 517,000 |
| Sidewalks | \$ | 346,000 |
| Grand Total | \$ | 41,712,000 |

ELECTRICAL SYSTEMS

Replace Failing **Clocks**



Provide Code Compliant **Fire Alarm** System



Provide 21st Century

Classroom IT



Building Wide **PA** System



Replace Old **Generator** to Power Building Systems



Faster & More Reliable **Data Wiring**



| Scope Description | Sum | of Cost Repla |
|-----------------------------------|-----|---------------|
| | | 11,712,000 |
| | | |
| ® Roofs | \$ | 3,869,000 |
| Windows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | \$ | 5,590,000 |
| ⊕ Fire Alarm | \$ | 1,247,000 |
| I.T Clocks | \$ | 104,000 |
| ■ I.T Data Wiring | \$ | 2,315,000 |
| ■ I.T Generator | \$ | 417,000 |
| ■ I.T IS Office Renovation | \$ | 588,000 |
| ● I.T PA | \$ | 520,000 |
| | \$ | 150,000 |
| ■ I.T WAN | \$ | 249,000 |
| Interior Renovations | \$ | 20,210,000 |
| Auditorium Essential Upgrades (| \$ | 500,000 |
| Basement & 2nd Floor Classrm, | \$ | 14,771,000 |
| ⊕ Cafeteria & Kitchen Renovation | \$ | 3,873,000 |
| ⊕ Create Secure Vestibule @ Mair | \$ | 167,000 |
| ■ Old Gym Essential Upgrades (Bl- | \$ | 799,000 |
| Structural Repair - Joist Below F | \$ | 100,000 |
| ■ Mechanical Systems | \$ | 4,907,000 |
| | \$ | 124,000 |
| | \$ | 99,000 |
| ⊕ HVAC - IT | \$ | 252,000 |
| ⊕ HVAC Cafeteria | \$ | 347,000 |
| ■ HVAC Classroom | \$ | 4,043,000 |
| ● Pool Systems | \$ | 42,000 |
| | | |
| Backflow Prevention | \$ | 121,000 |
| ⊕ Fire Department Connections | \$ | 16,000 |
| ⊕ Pool Systems | \$ | 327,000 |
| Water Fountains | \$ | 290,000 |
| ■ Site | \$ | 2,371,000 |
| ■ Parking Lots & Roadways | \$ | 1,508,000 |
| ■ Retaining Wall - Allowance | \$ | 517,000 |
| Sidewalks | \$ | 346,000 |
| Grand Total | \$ | 41,712,000 |

MECHANICAL SYSTEMS





| Scope Description | Sui | m of Cost Replac |
|---|-----|------------------|
| | | 41,712,000 |
| | | |
| ⊕ Roofs | \$ | 3,869,000 |
| ■ Windows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | | |
| ⊕ Fire Alarm | \$ | 1,247,000 |
| I.T Clocks | \$ | 104,000 |
| ■ I.T Data Wiring | \$ | 2,315,000 |
| I.T Generator | \$ | 417,000 |
| ■ I.T IS Office Renovation | \$ | 588,000 |
| ® I.T PA | \$ | 520,000 |
| ® I.T UPS | \$ | 150,000 |
| ⊕ I.T VAN | \$ | 249,000 |
| ☐ Interior Renovations | \$ | 20,210,000 |
| Auditorium Essential Upgrades (| \$ | 500,000 |
| ■ Basement & 2nd Floor Classrm, | \$ | 14,771,000 |
| ⊕ Cafeteria & Kitchen Renovation | \$ | 3,873,000 |
| | \$ | 167,000 |
| ■ Old Gym Essential Upgrades (Bl- | \$ | 799,000 |
| ® Structural Repair - Joist Below F | \$ | 100,000 |
| ■ Mechanical Systems | \$ | 4,907,000 |
| Energy Recovery Unit | \$ | 124,000 |
| ■ Exhaust Fans | \$ | 99,000 |
| ● HVAC - IT | \$ | 252,000 |
| ■ HVAC Cafeteria | \$ | 347,000 |
| ⊕ HVAC Classroom | \$ | 4,043,000 |
| ■ Pool Systems | \$ | 42,000 |
| ■ Plumbing Systems | \$ | 754,000 |
| ■ Backflow Prevention | \$ | 121,000 |
| ● Fire Department Connections | \$ | 16,000 |
| | \$ | 327,000 |
| Water Fountains | \$ | 290,000 |
| ■ Site | \$ | 2,371,000 |
| ■ Parking Lots & Roadways | \$ | 1,508,000 |
| ■ Retaining Wall - Allowance | \$ | 517,000 |
| ■ Sidewalks | \$ | 346,000 |

\$ 41,712,000

Grand Total

PLUMBING SYSTEMS

Replace Original, 70 Year Old Plumbing



Provide Bottle Filler **Drinking Fountains**



Replace **Failing** Pool Systems



Replace Failing **Pool Piping**



HIGH SCHOOL

| Scope Description | ■ Sum | of Cost Repla |
|---------------------------------|--------|---------------|
| | | 1,712,000 |
| | | |
| ■ Roofs | \$ | 3,869,000 |
| Windows (1935) | \$ | 4,011,000 |
| ■ Electrical Systems | | 5,590,000 |
| ● Fire Alarm | \$ | 1,247,000 |
| I.T Clocks | \$ | 104,000 |
| ■ I.T Data Wiring | \$ | 2,315,000 |
| ■ I.T Generator | \$ | 417,000 |
| I.T IS Office Renovation | \$ | 588,000 |
| ⊕ I.T PA | \$ | 520,000 |
| ⊕ I.T UPS | \$ | 150,000 |
| ⊕ I.T WAN | \$ | 249,000 |
| ■ Interior Renovations | | 20,210,000 |
| Auditorium Essential Upgrade | s(\$ | 500,000 |
| Basement & 2nd Floor Classr | m, \$ | 14,771,000 |
| 🖲 Cafeteria & Kitchen Renovatio | on \$ | 3,873,000 |
| ® Create Secure Vestibule @ M. | air \$ | 167,000 |
| Old Gym Essential Upgrades (I | Bl- \$ | 799,000 |
| Structural Repair - Joist Below | /F \$ | 100,000 |
| | | |
| ■ Energy Recovery Unit | \$ | 124,000 |
| ■ Exhaust Fans | \$ | 99,000 |
| ● HVAC - IT | \$ | 252,000 |
| ■ HVAC Cafeteria | \$ | 347,000 |
| ■ HVAC Classroom | \$ | 4,043,000 |
| ■ Pool Systems | \$ | 42,000 |
| ■ Plumbing Systems | \$ | 754,000 |
| Backflow Prevention | \$ | 121,000 |
| Fire Department Connections | \$ | 16,000 |
| ● Pool Systems | \$ | 327,000 |
| ■ Water Fountains | \$ | 290,000 |
| □ Site | \$ | 2,371,000 |
| ■ Parking Lots & Roadways | \$ | 1,508,000 |
| ⊕ Retaining Wall - Allowance | \$ | 517,000 |
| Sidewalks | \$ | 346,000 |
| Grand Total | | 41,712,000 |

PERSELL MIDDLE SCHOOL

INTERIOR RENOVATIONS





Renovate **Music** Rooms




■ Sum of Cost Replac Scope Description Building Mounted Lighting ⊞ I.T. - PA ☐ Interior Renovations 2,533,000 ⊕ Gym s 388,000 **⊞** Locker Rooms \$ 632,000 \$ 711,000 **⊞ Music Rooms** 802,000 Air Handling Units ■ Radiant Floor Heating 97,000 ■ Replace Galvanized Piping ■ Water Heater ■ Water Service ■ Parking Lots

Grand Total

PERSELL MS

SITE WORK

Repair Track



PERSELL MS

| Scope Description | ΨT Sur | n of Cost Replac |
|-----------------------------|--------|------------------|
| | | 12,151,000 |
| | | |
| ⊕ Roof | \$ | 2,593,000 |
| · Windows | \$ | 1,247,000 |
| | | |
| Auditorium Lighting | S | 178,000 |
| Auditorium Sound | \$ | 223,000 |
| Building Mounted Lighting | \$ | 20,000 |
| Exit Lighting | \$ | 167,000 |
| ⊕ I.T PA | \$ | 167,000 |
| | \$ | 9,000 |
| ☐ Interior Renovations | | 2,533,000 |
| ⊕ Gym | \$ | 388,000 |
| | \$ | 632,000 |
| ⊕ Restrooms | 1.5 | 711,000 |
| ⊕ Music Rooms | \$ | 802,000 |
| ■ Mechanical Systems | | |
| Air Cooled Condensing Units | \$ | 178,000 |
| ⊕ Air Handling Units | \$ | 848,000 |
| ⊕ Dust Collector | \$ | 297,000 |
| Exhaust Fans | \$ | 39,000 |
| | \$ | 111,000 |
| ⊕ Hoods for Gas Ranges | S | 165,000 |
| Provide Ventilation | S | 30,000 |
| ⊕ Pumps | S | 30,000 |
| Radiant Floor Heating | S | 1,545,000 |
| ⊕ Relief Hoods | S | 16,000 |
| ⊕ Roof Top Units | \$ | 97,000 |
| ⊕ Unit Ventilators | \$ | 757,000 |
| Plumbing Systems | | |
| Replace Galvanized Piping | ş | 185,000 |
| ⊕ Water Heater | \$ | 15,000 |
| ⊕ Water Service | \$ | 37,000 |
| ■ Site | \$ | 664,000 |
| ⊕ Flagpole | \$ | 5,000 |
| ⊕ Parking Lots | \$ | 436,000 |
| ⊕ Cinder Track | \$ | 223,000 |
| Grand Total | S | 12,151,000 |

BUILDING ENVELOPE

PERSELL MS



| Scope Description | √ Sum | of Cost Replac |
|-----------------------------|--------------|----------------|
| | | 2,151,000 |
| ■ Building Envelope | \$ | 3,840,000 |
| ⊕ Roof | \$ | 2,593,000 |
| ⊕ Windows | \$ | 1,247,000 |
| Electrical Systems | \$ | 764,000 |
| Auditorium Lighting | \$ | 178,000 |
| Auditorium Sound | \$ | 223,000 |
| Building Mounted Lighting | \$ | 20,000 |
| ⊕ Exit Lighting | \$ | 167,000 |
| ⊞ I.T PA | \$ | 167,000 |
| Parking Lot LED Lighting | \$ | 9,000 |
| ☐ Interior Renovations | | 2,533,000 |
| ⊕ Gym | \$ | 388,000 |
| ⊕ Locker Rooms | \$ | 632,000 |
| ⊕ Restrooms | \$ | 711,000 |
| ⊕ Music Rooms | \$ | 802,000 |
| ☐ Mechanical Systems | | |
| Air Cooled Condensing Units | \$ | 178,000 |
| Air Handling Units | \$ | 848,000 |
| ⊕ Dust Collector | \$ | 297,000 |
| | \$ | 39,000 |
| ⊕ Exhaust Kitchen | S | 111,000 |
| ⊕ Hoods for Gas Ranges | s | 165,000 |
| ⊕ Provide Ventilation | \$ | 30,000 |
| ⊕ Pumps | S | 30,000 |
| Radiant Floor Heating | S | 1,545,000 |
| ⊕ Relief Hoods | \$ | 16,000 |
| ■ Roof Top Units | \$ | 97,000 |
| ■ Unit Ventilators | \$ | 757,000 |
| ■ Plumbing Systems | | |
| Replace Galvanized Piping | S | 185,000 |
| ⊕ Water Heater | \$ | 15,000 |
| | \$ | 37,000 |
| ■ Site | \$ | 664,000 |
| ⊕ Flagpole | \$ | 5,000 |
| ⊕ Parking Lots | \$ | 436,000 |
| ⊕ Cinder Track | \$ | 223,000 |
| Grand Total | \$ | 12,151,000 |

BUILDING SYSTEMS

Auditorium Lighting & Sound Upgrades



Emergency Exit Lighting Replacement



Replace **Roof Top**Ventilation Units



Replace Classroom Heating & Ventilation



Old **Plumbing** & Storm Water **Upgrades**



| Scope Description | ↓T Sum | of Cost Repla |
|-----------------------------|---------------|---------------|
| | | 12,151,000 |
| | | |
| ⊕ Roof | S | 2,593,000 |
| ⊞ Windows | s | 1,247,000 |
| Electrical Systems | s | 764,000 |
| Auditorium Lighting | \$ | 178,000 |
| Auditorium Sound | \$ | 223,000 |
| Building Mounted Lighting | \$ | 20,000 |
| Exit Lighting | \$ | 167,000 |
| ⊞ I.T PA | \$ | 167,000 |
| → Parking Lot LED Lighting | s | 9,000 |
| ☐ Interior Renovations | S | 2,533,000 |
| ⊕ Gym | S | 388,000 |
| | S | 632,000 |
| ⊕ Restrooms | \$ | 711,000 |
| ⊕ Music Rooms | \$ | 802,000 |
| ■ Mechanical Systems | \$ | 4,113,000 |
| Air Cooled Condensing Units | \$ | 178,000 |
| ⊕ Air Handling Units | \$ | 848,000 |
| ■ Dust Collector | \$ | 297,000 |
| | \$ | 39,000 |
| ⊕ Exhaust Kitchen | \$ | 111,000 |
| | s | 165,000 |
| Provide Ventilation | \$ | 30,000 |
| ⊕ Pumps | \$ | 30,000 |
| ■ Radiant Floor Heating | s | 1,545,000 |
| Relief Hoods | \$ | 16,000 |
| ■ RoofTop Units | s | 97,000 |
| ⊞ Unit Ventilators | \$ | 757,000 |
| ☐ Plumbing Systems | \$ | 237,000 |
| | \$ | 185,000 |
| ⊞ Water Heater | \$ | 15,000 |
| Maria A. C. | \$ | 37,000 |
| ■ Water Service | | |
| ■ Water Service | 5 | 664,000 |
| | \$ \$ | 5,000 |

FLETCHER ELEMENTARY

BUILDING ENVELOPE & SITE WORK



FLETCHER ELEM.

| Scope Description | Sum | of Cost Replac |
|---------------------------------|-----|----------------|
| = 2021 Capital Project | ė | 11 299 000 |
| B Duilding Fruiters | s | 1,100,000 |
| ■ Building Envelope | S | 53,000 |
| Masonry Repointing | s | 22,000 |
| Boof | s | 1,025,000 |
| ■ Building Structure | 5 | 74,000 |
| Cafeteria Water Issue | S | 74,000 |
| Electrical Systems | - | 430,000 |
| + I.T Generator | \$ | 245,000 |
| B.T PA | S | 185,000 |
| ☐ Interior Renovations | s | 297,000 |
| Crawlspace Remediation | s | 297,000 |
| ■ Mechanical Systems | S | 5,707,000 |
| Add Cooling | S | 1,486,000 |
| Air Handling Unit | S | 111,000 |
| | | |
| ⊕ Boilers | \$ | 1,759,000 |
| ⊕ Cabinet Heaters | Ş | 37,000 |
| ■ Exhaust Fans | \$ | 45,000 |
| ➡ Provide Ventilation | \$ | 90,000 |
| ■ Relief Fans | \$ | 245,000 |
| ■ Roof Top Units | \$ | 415,000 |
| ■ Rooftop Ductwork | \$ | 51,000 |
| ⊕ Unit Ventilators | \$ | 1,468,000 |
| Plumbing Systems | | 3,600,000 |
| Asbestos Piping Replacement | \$ | 372,000 |
| d Cast Iron Pipe Replacement | \$ | 1,410,000 |
| → Drinking Fountains | \$ | 119,000 |
| ⊕ Galvanized Piping Replacement | \$ | 1,188,000 |
| ⊕ Hot Water Heater | \$ | 126,000 |
| → Plumbing Valve Replacements | \$ | 372,000 |
| Sump Pump | \$ | 13,000 |
| ■ Site | \$ | 91,000 |
| ± Sidewalks | S | 91,000 |
| Grand Total | \$ | 11,299,000 |

BUILDING SYSTEMS

FLETCHER ELEM.

Add Cooling to 1936 Wing







Replace End of Life **Boilers**



Provide **Drinking Fountains** with Bottle Fillers

| Scope Description | -T Sur | m of Cost Replac |
|-------------------------------|----------|--------------------|
| 2021 Capital Project | d Sul | 11,299,000 |
| | | |
| Building Envelope | 5 | 1,100,000 |
| Masonry Rebuilding | \$ | 53,000 |
| | S | 22,000 |
| | Ş | 1,025,000 |
| Building Structure | 9 | 74,000 |
| | S | 74,000 |
| Electrical Systems | | 430,000 |
| | \$ \$ | 245,000 185,000 |
| ■ I.IPA Interior Renovations | • | |
| Trawlspace Remediation | S | 297,000 297,000 |
| ■ Mechanical Systems | \$ | 5,707,000 |
| Add Cooling | S | 1,486,000 |
| Air Handling Unit | s | 111,000 |
| _ | | 111,000 |
| ⊕ Boilers | \$ | 1,759,000 |
| ⊕ Cabinet Heaters | \$ | 37,000 |
| | \$ | 45,000 |
| Provide Ventilation | \$ | 90,000 |
| Relief Fans | \$ | 245,000 |
| ■ Roof Top Units | \$ | 415,000 |
| ■ Rooftop Ductwork | \$ | 51,000 |
| ⊕ Unit Ventilators | s | 1,468,000 |
| ■ Plumbing Systems | \$ | 3,600,000 |
| Asbestos Piping Replacement | | 372,000 |
| | \$ | 1,410,000 |
| Drinking Fountains | \$ | 119,000 |
| ■ Galvanized Piping Replaceme | nt \$ | 1,188,000 |
| Hot Water Heater | \$ | 126,000 |
| Plumbing Valve Replacement: | s \$ | 372,000 |
| ⊞ Sump Pump | \$ | 13,000 |
| Site | 5 | 91,000 |
| ± Sidewalks | \$ | 91,000 |
| Grand Total | \$ | 11,299,000 |

CC RING ELEMENTARY

BUILDING ENVELOPE & SITE WORK



Energy Efficient Windows
& Repair Exterior Walls



Secure **Exterior Doors**



CC RING ELEM. 22

| Scope Description | Sum | of Cost Replace |
|--|-----|-----------------|
| ■ 2021 Capital Project | | 6,860,000 |
| ■ Building Envelope | \$ | 1,488,000 |
| ■ EIFS Replacement | \$ | 562,000 |
| ⊕ Exterior Doors | \$ | 181,000 |
| | \$ | 17,000 |
| ± Windows | \$ | 728,000 |
| ■ Building Interior | 5 | 1,294,000 |
| ⊕ Fire Rated Glazing | \$ | 575,000 |
| ■ Interior Stairs - Treads/Risers/Rail | \$ | 67,000 |
| | \$ | 652,000 |
| ■ Electrical Systems | \$ | 1,283,000 |
| Auditorium Lighting (Could be Prio | \$ | 223,000 |
| Auditorium Sound | \$ | 119,000 |
| 🕏 Fire Alarm | \$ | 557,000 |
| 🖶 I.T Generator | \$ | 245,000 |
| ⊞ I.T PA | \$ | 139,000 |
| ☐ Interior Renovations | | 1,741,000 |
| ⊕ Auditorium - Seats & Flooring | \$ | 182,000 |
| ⊕ Auditorium - Stage Rigging | \$ | 360,000 |
| ⊕ Cafeteria - Expand & Renovate Exi: | \$ | 552,000 |
| ■ Replace Classroom Coat Closets | \$ | 647,000 |
| ■ Mechanical Systems | | 120,000 |
| ⊕ Data Room Cooling | \$ | 30,000 |
| Provide Ventilation | \$ | 90,000 |
| ☐ Plumbing Systems | | 785,000 |
| ⊕ Drinking Fountains | \$ | 48,000 |
| ⊕ Galvanized Piping Replacement | \$ | 609,000 |
| ⊕ Sediment Interceptor | \$ | 4,000 |
| Sump Pump | \$ | 13,000 |
| ⊕ Valve Replacements | \$ | 111,000 |
| ■ Site | \$ | 149,000 |
| | \$ | 149,000 |
| Grand Total | \$ | 6,860,000 |

INTERIOR RENOVATIONS



Modernize Classrooms: Flooring & Coat Closets



Replace Stair Railings for **Student Safety**





CC RING ELEM. 23

| Scope Description | Sun | n of Cost Repla |
|--------------------------------------|-----|-----------------|
| | | 6,860,000 |
| | | |
| ■ EIFS Replacement (Could be Priorit | S | 562,000 |
| ■ Exterior Doors | \$ | 181,000 |
| ⊞ Masonry | \$ | 17,000 |
| ⊕ Windows | S | 728,000 |
| Building Interior | \$ | 1,294,000 |
| | \$ | 575,000 |
| | \$ | 67,000 |
| | \$ | 652,000 |
| ■ Electrical Systems | 5 | 1,283,000 |
| Auditorium Lighting (Could be Prior) | \$ | 223,000 |
| Auditorium Sound | \$ | 119,000 |
| ⊕ Fire Alarm | \$ | 557,000 |
| 🛨 I.T Generator | \$ | 245,000 |
| ⊞ I.T PA | \$ | 139,000 |
| ☐ Interior Renovations | \$ | 1,741,000 |
| ⊕ Auditorium - Seats & Flooring | \$ | 182,000 |
| ⊕ Auditorium - Stage Rigging | \$ | 360,000 |
| | \$ | 552,000 |
| ⊞ Replace Classroom Coat Closets | \$ | 647,000 |
| ■ Mechanical Systems | 5 | 120,000 |
| ⊞ Data Room Cooling | \$ | 30,000 |
| Provide Ventilation | \$ | 90,000 |
| ☐ Plumbing Systems | | 785,000 |
| Drinking Fountains | \$ | 48,000 |
| ⊕ Galvanized Piping Replacement | \$ | 609,000 |
| ■ Sediment Interceptor | \$ | 4,000 |
| ⊕ Sump Pump | \$ | 13,000 |
| | \$ | 111,000 |
| ■ Site | \$ | 149,000 |
| 🛨 Sidewalks (Perimeter & Back of Bu | S | 149,000 |
| Grand Total | S | 6,860,000 |

BUILDING SYSTEMS



Provide **Drinking**Fountains with
Bottle Fillers





CC RING ELEM. 24

| Scope Description | Sum | of Cost Replac |
|--|----------------------|--|
| 2021 Capital Project | \$ | 6,860,000 |
| | | |
| ⊞ EIFS Replacement (Could be Priorit | Ş | 562,000 |
| ⊕ Exterior Doors | \$ | 181,000 |
| ⊕ Masonry | \$ | 17,000 |
| ⊕ Windows | S | 728,000 |
| | | |
| ⊕ Fire Rated Glazing | \$ | 575,000 |
| ⊕ Interior Stairs - Treads/Risers/Rail | \$ | 67,000 |
| H VAT Flooring - Classrooms 3-8, 10, | \$ | 652,000 |
| Electrical Systems | \$ | 1,283,000 |
| Auditorium Lighting . | \$ | 223,000 |
| Auditorium Sound | \$ | 119,000 |
| Fire Alarm | \$ | 557,000 |
| ∄ I.T Generator | \$ | 245,000 |
| ± I.T PA | \$ | 139,000 |
| ■ Interior Renovations | 5 | 1,741,000 |
| ⊕ Auditorium - Seats & Flooring | \$ | 182,000 |
| | \$ | 360,000 |
| ⊕ Cafeteria - Expand & Renovate Exi: | \$ | 552,000 |
| ■ Replace Classroom Coat Closets | \$ | 647,000 |
| ■ Mechanical Systems | \$ | 120,000 |
| Data Room Cooling | \$ | 30,000 |
| | | |
| Provide Ventilation | \$ | 90,000 |
| | \$ | 90,000 785,000 |
| ⊕ Provide Ventilation | _ | , |
| Provide Ventilation Plumbing Systems | \$ | 785,000 |
| Provide Ventilation Plumbing Systems Drinking Fountains | \$ | 785,000 48,000 |
| Provide Ventilation Plumbing Systems Drinking Fountains Galvanized Piping Replacement | \$ \$ \$ | 785,000 48,000 609,000 |
| Provide Ventilation Plumbing Systems Drinking Fountains Galvanized Piping Replacement Sediment Interceptor | \$ \$ \$ \$ | 785,000 48,000 609,000 4,000 |
| Provide Ventilation Plumbing Systems Drinking Fountains Galvanized Piping Replacement Sediment Interceptor Sump Pump | \$ \$ \$ \$ | 785,000 48,000 609,000 4,000 13,000 |
| Provide Ventilation Plumbing Systems Drinking Fountains Galvanized Piping Replacement Sediment Interceptor Sump Pump | \$ \$ \$ \$ | 785,000 48,000 609,000 4,000 13,000 111,000 |

TECHNICAL ACADEMY

INTERIOR RENOVATIONS & SITE WORK



Modernize Classrooms

Sink Replacements





Stair, Parking Lot & Sidewalk **Safe Paths**

TECH ACADEMY26

| Scope Description | Sun | n of Cost Repla |
|-----------------------------------|------|-----------------|
| | | 3,561,000 |
| | | |
| ⊕ Exterior Doors | \$ | 42,000 |
| ⊕ Masonry | \$ | 289,000 |
| ⊕ Secure Entry | \$ | 133,000 |
| · Windows | \$ | 406,000 |
| ☐ Building Structure | \$ | 34,000 |
| ⊕ Foundation Repair | \$ | 4,000 |
| Structural Floors | \$ | 30,000 |
| ■ Electrical Systems | | |
| ⊕ Exterior Building Lighting | \$ | 6,000 |
| Fire Alarm | \$ | 133,000 |
| ∃ I.T. – Generator | \$ | 245,000 |
| ⊕ I.T PA | \$ | 33,000 |
| | \$ | 133,000 |
| ☐ Interior Renovations | \$ | 763,000 |
| ⊕ General Classrooms - Renovate 5 | 51\$ | 741,000 |
| | \$ | 22,000 |
| ■ Mechanical Systems | - 5 | 1,172,000 |
| Air Handling Unit | \$ | 97,000 |
| ⊕ Chiller | \$ | 223,000 |
| ⊕ Data Room Cooling | \$ | 34,000 |
| ⊕ Dust Collector | \$ | 111,000 |
| ⊞ Exhaust Fans | \$ | 67,000 |
| ⊕ Fan Coil Units | \$ | 505,000 |
| Hot Water Pumps | \$ | 45,000 |
| 1 Unit Ventilators | \$ | 90,000 |
| | | |
| ⊕ Drinking Fountains | \$ | 12,000 |
| 🖶 Gas Service Meter & Regulator | \$ | 15,000 |
| Elumbing Fixtures | S | 2.000 |
| □ Site | \$ | 143,000 |
| Exterior Stairs | \$ | 25,000 |
| Parking Lots | \$ | 37,000 |
| ± Sidewalks | Ś | 81,000 |
| Conned Tested | Ċ | 2 564 000 |

BUILDING ENVELOPE & STRUCTURAL





Repair **Structural** Cracks



TECH ACADEMY2

| Scope Description | Sun | n of Cost Repla |
|-----------------------------------|-----|-----------------|
| | | 3,561,000 |
| ■ Building Envelope | \$ | 870,000 |
| Exterior Doors | \$ | 42,000 |
| Masonry | \$ | 289,000 |
| Secure Entry | \$ | 133,000 |
| ⊕ Windows | \$ | 406,000 |
| ■ Building Structure | \$ | 34,000 |
| ⊕ Foundation Repair | \$ | 4,000 |
| Structural Floors | \$ | 30,000 |
| Electrical Systems | 5 | 550,000 |
| ⊕ Exterior Building Lighting | \$ | 6,000 |
| ⊕ Fire Alarm | \$ | 133,000 |
| ⊞ I.T. – Generator | \$ | 245,000 |
| ⊞ I.T PA | \$ | 33,000 |
| | \$ | 133,000 |
| | | |
| 🕀 General Classrooms - Renovate 5 | \$ | 741,000 |
| | \$ | 22,000 |
| ■ Mechanical Systems | \$ | 1,172,000 |
| ∄ Air Handling Unit | \$ | 97,000 |
| ⊕ Chiller | \$ | 223,000 |
| ⊕ Data Room Cooling | \$ | 34,000 |
| ⊕ Dust Collector | \$ | 111,000 |
| ⊕ Exhaust Fans | Ş | 67,000 |
| ⊕ Fan Coil Units | \$ | 505,000 |
| Hot Water Pumps | \$ | 45,000 |
| ⊕ Unit Ventilators | \$ | 90,000 |
| ☐ Plumbing Systems | | |
| □ Drinking Fountains | \$ | 12,000 |
| 🕀 Gas Service Meter & Regulator | \$ | 15,000 |
| Plumbing Fixtures | \$ | 2,000 |
| ■ Site | | |
| ⊕ Exterior Stairs | \$ | 25,000 |
| Parking Lots | \$ | 37,000 |
| ⊞ Sidewalks | \$ | 81,000 |
| Grand Total | S | 3,561,000 |

BUILDING SYSTEMS

Provide Code
Compliant
Fire Alarm
System





Provide **Drinking**Fountains with
Bottle Fillers

TECH ACADEMY28

| Scope Description | Description Sum of Cost Replac | |
|---------------------------------|--------------------------------|-----------|
| | | 3,561,000 |
| | | |
| Exterior Doors | \$ | 42,000 |
| ⊕ Masonry | \$ | 289,000 |
| ⊕ Secure Entry | \$ | 133,000 |
| ⊕ Windows | \$ | 406,000 |
| | | |
| | \$ | 4,000 |
| ■ Structural Floors | S | 30,000 |
| Electrical Systems | \$ | 550,000 |
| ⊕ Exterior Building Lighting | \$ | 6,000 |
| ⊕ Fire Alarm | \$ | 133,000 |
| ∃ I.T. – Generator | \$ | 245,000 |
| ⊞ I.T PA | \$ | 33,000 |
| | \$ | 133,000 |
| ☐ Interior Renovations | \$ | 763,000 |
| deneral Classrooms - Renovate | e51\$ | 741,000 |
| Plumbing Fixtures | S | 22.000 |
| ■ Mechanical Systems | \$ | 1,172,000 |
| ∄ Air Handling Unit | \$ | 97,000 |
| ⊕ Chiller | \$ | 223,000 |
| ⊕ Data Room Cooling | \$ | 34,000 |
| ■ Dust Collector | \$ | 111,000 |
| | \$ | 67,000 |
| | \$ | 505,000 |
| ⊞ Hot Water Pumps | \$ | 45,000 |
| | \$ | 90,000 |
| ■ Plumbing Systems | \$ | 29,000 |
| Drinking Fountains | \$ | 12,000 |
| ⊕ Gas Service Meter & Regulator | \$ | 15,000 |
| Plumbing Fixtures | s | 2.000 |
| □ Site | \$ | 143,000 |
| ⊕ Exterior Stairs | \$ | 25,000 |
| ⊕ Parking Lots | \$ | 37,000 |
| ⊕ Sidewalks | \$ | 81,000 |
| Grand Total | S | 3,561,000 |

BUS GARAGE

SITE WORK

BUS GARAGE



| Scope Description | ₃ Sun | n of Cost Replac |
|-------------------------------------|--------|------------------|
| | | 1,344,000 |
| | | |
| 🖽 I.T Generator | \$ | 74,000 |
| | | |
| ⊞ Fire Department Connection | \$ | 22,000 |
| ☐ Plumbing Systems | | |
| ⊞ Interior Bus Bay Drainage System | & F \$ | 312,000 |
| □ Site | \$ | 936,000 |
| ⊞ Catch Basin Replacement | \$ | 201,000 |
| ⊕ Parking Lots & Roadways | \$ | 622,000 |
| 🕀 Parking Lots & Roadways - Retaini | ng¹\$ | 6,000 |
| ∃ Sidewalks - Bollards Around Bldg | \$ | 13,000 |
| 🕀 Sidewalks - Concrete Apron Aroun | dB\$ | 94,000 |
| Grand Total | \$ | 1,344,000 |

INTERIOR WORK

BUS GARAGE



| Scope Description | ₹ Sun | n of Cost Replac |
|--------------------------------------|--------|------------------|
| | \$ | 1,344,000 |
| | | |
| 🖽 I.T Generator | \$ | 74,000 |
| Fire Suppression | \$ | 22,000 |
| ⊞ Fire Department Connection | \$ | 22,000 |
| ■ Plumbing Systems | \$ | 312,000 |
| ⊞ Interior Bus Bay Drainage System & | kF\$ | 312,000 |
| □ Site | \$ | 936,000 |
| E Catch Basin Replacement | \$ | 201,000 |
| ⊞ Parking Lots & Roadways | \$ | 622,000 |
| 🕀 Parking Lots & Roadways - Retainin | ng '\$ | 6,000 |
| ⊞ Sidewalks - Bollards Around Bldg | \$ | 13,000 |
| ⊞ Sidewalks - Concrete Apron Around | 1B\$ | 94,000 |
| Grand Total | \$ | 1,344,000 |

Provide Code Compliant Fire Department Connections

DISTRICT WIDE I.T.

All Buildings

- Interior & Exterior Cameras
- Wiring & Data Closets
- Uninterrupted Power Supply (UPS)
- Wide Area Network (WAN)
 - If HS goes down, all other buildings can stay online

LINCOLN ELEMENTARY

INTERIOR WORK



Replace Flooring and Subflooring

LINCOLN ELEM.34

| Row Labels | | Replace |
|-------------------------------|-----------|---------|
| ■ 2021 Capital Project | \$ 2,582, | .000 |
| ■ Building Interior | \$ 2,58 | 82,000 |
| ⊕ Flooring | \$ 1,09 | 96,000 |
| ⊞ Flooring Subfloor Allowance | \$ 1,48 | 86,000 |
| Grand Total | \$ 2,58 | 82,000 |