Consultants - Engineers - Scientists

SIX MONTH PERIODIC SURVEILLANCE

Performed for:

LINCOLNSHIRE-PRAIRIE VIEW SCHOOL DISTRICT #103

1370 N. Riverwoods Road Lincolnshire, IL 60069

Project Location:



LAURA B. SPRAGUE ELEMENTARY SCHOOL

2425 Riverwoods Road Lincolnshire, IL 60069

March 12, 2019

MEC PROJECT #: 19-03-132-INSP

Yorkville Location

2551 N. Bridge St. Yorkville, IL 60560

P: (630) 553-3989 F: (630) 553-3990

Peoria Location

3100 N. Knoxville Ave. Suite 204

Peoria, IL 61603 P: (309) 621-4680 F: (309) 621-4690

LINCOLNSHIRE-PRAIRIE VIEW SCHOOL DISTRICT #103

Laura B. Sprague Elementary School 2425 Riverwoods Road Lincolnshire, IL 60069

Table of Contents
MEC Project #: 19-03-132-INSP

| Inspector & Designated Person Compliance Statement | Section 1 |
|--|-----------|
| Six Month Periodic Surveillance Report | Section 2 |
| Section 855.300 - Local Education Agency (LEA) Requirements | Section 3 |
| Certifications | Section 4 |

Six Month Periodic Surveillance Compliance Statement

Inspector's Compliance Statement

I hereby certify that I have conducted a six-month periodic surveillance of known and assumed asbestos-containing building materials (ACBM) according to AHERA regulations contained in the Federal Register 40 CFR 763.93(b).

Asbestos Building Inspector

Steven R. Szeredy

IDPH License # 100-09766

3/(2/(9 Date

Designated Person's Compliance Statement

I hereby accept responsibility for implementing the current Management Plan on behalf of Lincolnshire-Prairieview School District #103 and for maintaining Laura B. Sprague Elementary School in full compliance with EPA, IDPH, and all applicable OSHA requirements with respect to asbestos-containing materials.

Designated Person

Scott Gaunky

Director of Building and Grounds

<u>4/3/2019</u> Date

Lincolnshire-Prairieview School District #103 1370 N. Riverwoods Road Lincolnshire, IL 60069

Laura B. Sprague Elementary School 2425 N. Riverwoods Road Lincolnshire, IL 60069 MEC Project #: 19-03-132-INSP



Reassessment Date: March 12, 2019

MEC Project #: 19-03-132-INSP School District: Lincolnshire-Prairie View School District #103 School ID #: 34-049-1030-2002

Building: Laura B. Sprague Elementary School

Address: 2425 Riverwoods Road

Lincolnshire, IL 60069

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street

Yorkville, IL 60560

Inspector: Steven R. Szeredy **IDPH #:** 100-09766

| HSA | Material Description | Location Previous Present Condition Condition | | Comments | |
|-----|-------------------------------------|---|------|----------|--|
| | | | | | , |
| FD | Fire Doors | Boiler Room, Maintenance Rooms | Good | Good | N/A |
| TJA | Pipe Fitting Insulation | Above Ceilings and in Inaccessible Wall & Pipe Chases | Good | Good | N/A |
| SFA | Spray-On Fireproofing Insulation | Library, Boiler Room, Gym 103 | Good | Good | In Boiler Room, above exterior doors only. |
| MBA | 3" Baseboard & Glue – Black | Rooms 7, 11, 12, 13, 22, 23, 24, 25A, 25B, 26, 101, 102, 1964 Wing Hallways, 1967 Wing Hallways | Good | Good | N/A |
| MBB | 3" Baseboard & Glue – Gray | Library (Room 46), Rooms 46A, 46B, 46C, 46D, 46E, 46F | Good | Good | N/A |
| MBC | 3" Baseboard & Glue – Beige | Rooms 11, 123, 123A, 124, 125 | Good | Good | N/A |
| MBD | 3" Baseboard & Glue – Brown | Rooms 120, 121 | Good | Good | N/A |
| MBE | 3" Baseboard & Glue – Gray | Room 103 (Gym Storage) | Good | Good | N/A |
| MBF | 6" Baseboard & Glue – Black | Room 106 | Good | Good | N/A |
| MBG | 3" Baseboard & Glue – Brown | Rooms 103, 105, 106B, & Storage | Good | Good | N/A |
| МВН | 3" Baseboard & Glue – Black | Room 106A (Stage) | Good | Good | N/A |
| MBI | 3" Baseboard & Glue – Blue | Room 104 | Good | Good | N/A |



Reassessment Date: March 12, 2019

School District: Lincolnshire-Prairie View School District #103 School ID #:

Building: Laura B. Sprague Elementary School

Address: 2425 Riverwoods Road

Lincolnshire, IL 60069

MEC Project #: <u>19-03-132-INSP</u> School ID #: <u>34-049-1030-2002</u>

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street

Yorkville, IL 60560

Inspector: Steven R. Szeredy IDPH #: 100-09766

| HSA | Material Description | Location P Co | | Present Condition | Comments |
|-----|--|---|---|-------------------|-----------------------|
| | | | | | |
| MFA | 1"x1" Ceramic Floor Tile & Grout – Peach | 1967 Wing Faculty Restroom, Room 17 Restroom | | | N/A |
| MFB | 2"x2" Ceramic Floor Tile & Grout – Gray w/Black Specks | 1964 Wing - Small Men's & Women's Faculty Restrooms, 1964 Wing Boys' & Girls' Restrooms, 1967 Wing Boys' & Girls' Restrooms | 1964 Wing Boys' & Girls' Restrooms, 1967 Wing Boys' & Good Good | | N/A |
| MFC | 1"x1" Ceramic Floor Tile & Grout – Blue | Phone Room, Room 14 Restroom | Phone Room, Room 14 Restroom Good Good | | N/A |
| MFD | 1"x1" Ceramic Floor Tile & Grout – Green | Room 15 Restroom Good Good | | N/A | |
| MFE | 1"x1" Ceramic Floor Tile & Grout – Yellow | Room 16 Restroom | Good | Good | N/A |
| MFF | Vinyl Stair Tread & Glue – Gray | Library (Room 46) | Good | Good N/A | |
| MFG | 12"x12" Floor Tile & Mastic – Blue/Gray w/Speckled Pattern | Poom (/ Library Resource Room) (food (food | | N/A | |
| MFH | 12"x12" Floor Tile & Mastic – White w/Tan Specks | Room 12 Restroom | Good | Good | N/A |
| MFI | 1"x1" Ceramic Floor Tile & Grout – Light Blue w/Yellow & Blue Accent Tiles | Rooms 8, 10, 11 Restrooms | Good | Good | N/A |
| MFJ | 6"x6" Ceramic Floor Tile & Grout – Brown | Main Entrance Foyer | Good | Good | Under carpet squares. |



Reassessment Date: March 12, 2019

School District: Lincolnshire-Prairie View School District #103 School ID #: 34-049-1030-2002

Building: Laura B. Sprague Elementary School

Address: 2425 Riverwoods Road

Lincolnshire, IL 60069

MEC Project #: <u>19-03-132-INSP</u>

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street

Yorkville, IL 60560

Inspector: Steven R. Szeredy IDPH #: 100-09766

| HSA | Material Description | Location | | Present Condition | Comments |
|-----|---|---|---|-------------------|---------------------------|
| | | | | | |
| MFK | 12"x12" Floor Tile & Mastic – Light Gray w/Dark Gray & White Specks | Room 124 | Good | Good | N/A |
| MFL | 12"x12" Floor Tile & Mastic – Tan w/Brown & White Specks | Main Entrance Hall, Room 103 Hallway, Rooms 120, 121 | Good | Good | Under carpet in hallways. |
| MFM | 2"x2" Ceramic Floor Tiles & Grout – Tan | Room 120 Restroom | Good | Good | N/A |
| MFN | 12"x12" Floor Tile & Mastic – Solid Beige w/White Streaks | Room 103 Hallway, Vestibules for the 1964 Wing Restrooms | Good | Good | N/A |
| MFO | 12"x12" Floor Tile & Mastic – Gray w/Brown & White Specks | 1964 Wing West Center Vestibule | 1964 Wing West Center Vestibule Good Good | | N/A |
| MFP | 12"x12" Floor Tile & Mastic – Cream w/White & Beige Streaks | Room 103 (Gym) Good Good | | N/A | |
| MFQ | 12"x12" Floor Tile & Mastic – Tan w/Brown & White Specks | 1990 Wing Hallway, Maintenance Office, Room 103A (Gym Storage), Rooms 104, 105, 106B | | Good | N/A |
| MFR | 12"x12" Floor Tile & Mastic – Solid Beige w/White Streaks | 1990 Wing Hallway by West Vestibule | Good | Good | N/A |
| MFS | 2"x2" Ceramic Floor Tile & Grout – Yellow | Girls Locker Room | Good | Good | N/A |
| MFT | 12"x12" Floor Tile & Mastic – White w/Blue Specks | Room 106A (Stage) | Good | Good | N/A |
| MFU | 2"x2" Ceramic Floor Tile & Grout – Beige | Boys Locker Room | Good | Good | N/A |



Reassessment Date: March 12, 2019

School District: Lincolnshire-Prairie View School District #103 School ID #: 34-049-1030-2002

Building: Laura B. Sprague Elementary School

Address: 2425 Riverwoods Road

Lincolnshire, IL 60069

MEC Project #: 19-03-132-INSP

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street

Yorkville, IL 60560
Inspector: Steven R. Szeredy IDPH #: 100-09766

| HSA | Material Description | Location Pro Con | | Present Condition | Comments |
|-----|--|---|------|-------------------|----------|
| | | | | | |
| MCA | 2'x4' White Acoustical Ceiling Tile – Pinholes & Fissures | Throughout 1964 Wing & 1967 Wing | Good | Good | N/A |
| MCB | 2'x2' White Acoustical Ceiling Tile – Pinholes & Fissures | Rooms 123, 123A, 103 (NE Room) | Good | Good | N/A |
| MCC | 2'x4' White Acoustical Ceiling Tile – Pinholes & Fissures | Throughout 1990 Wing | Good | Good | N/A |
| MDA | Drywall, Tape, & Joint Compound | Walls in Library (Rooms 46, 46A, 46B, 46C, 46D, 46E, 46F), Rooms 101, 102, 120, 121, 123A, 124, 125 Columns & Soffits in Rooms 1, 2, 3, 4, 5, 6, 7, 8, 9, 11, 12, 14, 15, 16, 17, 18, 19, 20, 21, 27, 28, 29, 30, 31, 32, 33, 34 | Good | Good | N/A |
| ММА | Wallboard Soundproofing | Gym 103 | Good | Good | N/A |
| MMB | Black Chalkboard/ Tackboard Adhesive | Throughout 1964 Wing Classrooms | Good | Good | N/A |
| MMC | Green Chalkboard/ Tackboard Adhesive | Throughout 1967 Wing Classrooms | Good | Good | N/A |
| MMD | Brown Chalkboard/ Tackboard Adhesive | Throughout 1990 Wing Classrooms | Good | Good | N/A |
| MME | White Floor Matting | Main Gym | Good | Good | N/A |
| MFW | 12"x12" Ceramic Floor Tile/Grout – Light Brown w/ Mesh Pattern | 1967 Wing Faculty Restroom – Room 17 Restroom | Good | Good | N/A |



Reassessment Date: March 12, 2019

School District: Lincolnshire-Prairie View School District #103 School ID #: 34-049-1030-2002

Building: Laura B. Sprague Elementary School

Address: 2425 Riverwoods Road

Lincolnshire, IL 60069

MEC Project #: 19-03-132-INSP School ID #: 34-049-1030-2002

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street Yorkville, IL 60560

Inspector: Steven R. Szeredy IDPH #: 100-09766

| HSA | Material Description | Location | | Present Condition | Comments |
|-----|---|---|------|-------------------|----------|
| MCD | 2'x2' Lay-In Ceiling Tile – Solid White | 1967 Wing Faculty Restroom – Room 17 Restroom | Good | Good | N/A |
| MWA | 12x12 Ceramic Wall Tile/Grout – Beige w/Accent Strip | 1967 Wing Faculty Restroom – Room 17 Restroom | Good | Good | N/A |

ASBESTOS ABATEMENT FOR PUBLIC AND PRIVATE SCHOOLS AND COMMERCIAL AND PUBLIC BUILDINGS IN ILLINOIS (77 ILL. ADM. CODE 855)

SUBPART E: LOCAL EDUCATIONAL AGENCY RESPONSIBILITIES AND STANDARDS FOR ABATEMENT

SECTION 855.300 LOCAL EDUCATION AGENCY (LEA) REQUIREMENTS

- a. Each LEA shall:
 - **1.** Ensure that any persons who perform inspections and reinspections, develop and update management plans, develop and implement response actions, including operations and maintenance or repair, are licensed in accordance with Section 855.100.
 - **2.** Ensure that all custodial and maintenance employees are properly trained as required by the Asbestos Hazard Emergency Response Act (AHERA), the Asbestos Abatement Act, and this Part.
 - **3.** Ensure that parents, teachers, and employee organizations are notified in writing at least once each school year of inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. The LEA shall include in the management plan a description of the steps taken to notify such organizations and a dated copy of the notification.
 - **4.** The LEA shall designate a person to oversee all management plan activities and ensure that the designated person receives adequate training to perform the assigned duties of the local education agency. Such training shall include:
 - **A.** Health effects of asbestos.
 - **B.** Detection, identification and assessment of ACBM.
 - **C.** Options for controlling ACBM.
 - **D.** Asbestos management programs.
 - **E.** Relevant federal and State regulations concerning asbestos, including those of the Occupational Safety and Health Administration, U.S. Department of Labor, the U.S. Department of Transportation, the U.S. Environmental Protection Agency and the Department.

- **5.** Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of asbestoscontaining building materials (ACBM) and/or assumed ACBM.
- **6.** Ensure that warning labels are posted in accordance with the following:
 - **A.** The LEA shall attach a warning label immediately adjacent to any ACBM and suspected ACBM assumed to be ACBM located in a routine maintenance area (such as boiler rooms) at each school building.
 - **B.** All labels shall be prominently displayed in readily visible locations and shall remain posted until the ACBM is removed.
 - **C.** The warning label shall state in print which is readily visible: Caution; Asbestos. Hazardous. Do Not Disturb Without Proper Training and Equipment.
- **7.** Ensure that the management plans are available for inspection and notification of such availability has been provided as specified in the management plan.
- **8.** Keep a copy of the plan in each school and district administrative office. Management plans shall be available for inspection by workers before work begins in any area of a school building. The management plans shall be available during normal business office hours, without cost or restriction, for inspection by representatives of the USEPA, the Department, teachers, other school personnel, parents and the general public. The LEA may charge a reasonable cost to make copies of management plans.
- **9.** Maintain records as part of the management plan.
- **10.** Ensure that each management plan contains a statement, signed by the individual designated by the LEA, which certifies that the LEA responsibilities have been met or will be met.
- **11.** Ensure that three year reinspections are conducted in accordance with this Part and Section 855.310(m).
- **12.** Ensure that the three year school reinspection information form provided by the Department is submitted to the Department within 30 days from the reinspection.

b. Recordkeeping

- 1. Records required under this Section shall be maintained in a centralized location in the administrative office of both the school and the LEA as part of the management plan. For each homogeneous area where all ACBM has been removed, the LEA shall ensure that such records are retained for six years after completion of removal.
- **2.** For each preventive measure and response action taken for ACBM and suspected ACBM assumed to be ACBM, the LEA shall provide:
 - **A.** A detailed written description of the response action and methods used, the location where the response action was taken, the reasons for selecting the response action, the start and completion dates of the work, the names and addresses of all contractors involved, and if applicable, their IDPH license I.D. number, and if ACBM is removed, the name and location of the disposal site of the ACBM.
 - **B.** The name, signature, and Department-issued license I.D. number of any person collecting any air samples required to be collected at the completion of certain response actions, the locations where samples were collected, date of collection, the name and address of the laboratory analyzing the samples, the date of analysis, the results of the analysis, the method of analysis, the name and signature of the person performing the analysis, and a statement that the laboratory meets the applicable requirements of the National Bureau of Standards TEM laboratory accreditation.
 - **C.** For each time that periodic surveillance is performed, the LEA shall record the name of each person performing the surveillance, the date of the surveillance, and any changes in the conditions of the materials.
 - **D.** For each time that asbestos cleaning is performed, the LEA shall record the name of each person performing the cleaning, the IDPH licensed worker I.D. number, the date of such cleaning, the locations cleaned, and the methods used to perform such cleaning.

- **E.** For each time that operations and maintenance activities are performed, the LEA shall record the name of each person performing the activity, the Department-issued licensed worker I.D. number, the start and completion dates of the activity, the locations where such activity occurred, a description of the activity including preventive measures used, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.
- **F.** For each time that major response action is performed, the local education agency shall provide the name, signature and Department-issued license I.D. number of each person performing the activity, the start and completion dates of the response action, the locations where such response action occurred, a description of the activity, including preventive measures used, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.
- **G.** For each fiber release episode, the LEA shall provide the date and location of the episode, the method of repair, preventive measures or response action taken, the name of each person performing the work, the IDPH license ID number, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.



525-535 West Jefferson Street · Springfield, Illinois 62761-0001 · www.dph.illinois.gov

STEVEN R SZEREDY660 COCHISE CIRCLE
BOLINGBROOK, IL 60440

1/16/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

09766

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| TIT | tunes | S PROVIDE | tors of th | ohe ha | 1111 |
|------|-------|-----------|------------|--------|------|
| - 39 | 1 | 1 | D | 1 | ı |
| 100 | Д., | | L | JL | IL. |

ASBESTOS PROFESSIONAL LICENSE

ISE ISE INSPECTOR

ENDORSEMENTS

AIR SAMPLING PROFESSIONAL

TC EXPIRES 8/3/2019

ID NUMBER 100 - 09766 ISSUED 1/16/2019

EXPIRES 05/15/2020

MANAGEMENT PLANNER
PROJECT MANAGER

7/16/2019 8/4/2019

STEVEN R SZEREDY 660 COCHISE CIRCLE BOLINGBROOK, IL 60440

Environmental Health

0

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid training course certificate.

St R-

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos EMAIL Address: dph.asbestos@illinois.gov



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street + Willowbrook, IL 60527 + (630) 655-3900 + www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Steven Szeredy

70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II. has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of

Course Date: 8/3/2018

Exam Date: 8/3/2018

Expiration Date: 8/3/2019

Certificate Number: BIR1808032230

Weth De Salva Kathy Desalvo, Director