Arduino DC Motor with Ultrasonic Sensor

By: Matthew Jourden Brighton High School Brighton, MI

> Navigate to TinkerCAD > Create the following circuit > Circuit > Create a New Circuit > Rename to DC Motor w/Ultrasonic

DC Motor


- 2. DC Motor has two wires
 - a. Red Wire: Voltage wire that can be
 - i. wired into the 5V turning the motor on with no off switch unless a switch is wired in front of it
 - ii. wired to a digital port, allowing the user to turn the motor on and off using
 - b. Black Wire: Ground Wire

Motor Movement: DC Motor states

High: Full SpeedLow: Stopped

- Variable: With a transistor, diode and potentiometer DC motors can be variable speed and direction

3. Wire the following circuit



4. Write the following code

```
int button = 8;
int motor = 3;

void setup()
{
  pinMode(button , INPUT);
  pinMode(motor , OUTPUT);
}

void loop()
{
  int buttonstate = digitalRead(button);
  if (buttonstate == 1)
  {
    digitalWrite(motor , LOW);
    } else {
    digitalWrite(motor , HIGH);
  }
}
```

5. Run the Simulation Test > Test the motor turning it On and Off

Ultrasonic Sensor

Ultrasonic Sensor is designed to send out a sound wave signal called the Trigger; and receive the bounced back sound wave into the Echo port. The sound wave will pulsate the Trigger on and off so the sound wave returning from the contacted object will be able to pass between the pulses. If the Trigger was constantly on the returning sound wave would be distorted.


Trigger Sound Wave will be a conical shape and can be distorted from ambient noise and materials that absorb sound (i.e cardboard, tennis ball, etc.)



Sound Calculation Formula: Distance $L = 1/2 \times T \times C$

where L is the distance, T is the time between the emission and reception, and C is the sonic speed. (The value is multiplied by 1/2 because T is the time for go-and-return distance.)

2. Add the Ultrasonic Sensor to the Circuit as shown



3. Write the following Program

Function: The following program will also use a function to help consolidate the code that will be used to turn the ultrasonic sensor on/off and convert the sound wave value to measureable unit in inches.

Function Example (See Reference Document Function for more details.)

Tutorial Program Function:

```
void setup() {
inches = ultrasonic (x);
}
long ultrasonic (long microseconds)

Variable x is passed to Function
ultrasonic

Ultrasonic Sensor Code

return microseconds

Microseconds is returned back to Void Setup
where the function was called and overwrite the
variable x to what microseconds equals
```


```
#include <Servo.h>
int button = 8;
int motor = 3;
int trigpin = 11;
int echopin = 10;
void setup()
  pinMode(button , INPUT);
  pinMode(motor , OUTPUT);
  pinMode (trigpin, OUTPUT);
  Serial.begin (9600);
void loop()
  long x, inches;
  int buttonstate = digitalRead(button);
  while (buttonstate == 1)
   // microsecondsToInches sends variable x to the function. Senses distances using sound
    //calculate sound wave distance to inches and sends the value back to the void loop function
    inches = microsecondsToInches(x);
   delay (1000);
    Serial.print ("Inches= ");
    Serial.println (inches);
   // Turning the motor on/off
   // High = On, Low = Off
   if (inches > 10)
     digitalWrite (motor, HIGH);
   e1se
     digitalWrite(motor, LOW);
 }
```

```
double microsecondsToInches(long duration)
{
    // Function is a sub program that can be utilized
    // in many parts of the program without rewriting the code.
    // The Return Function returns a value of microseconds to
    // the main program body

    //Next four lines of code pulsate a single out then in for defined time
    //calulates the duration the sound wave takes to come back to sensor
    digitalWrite(trigpin, LOW);
    delayMicroseconds(2);
    digitalWrite(trigpin, HIGH);
    delayMicroseconds(10);
    digitalWrite(trigpin, LOW);

    // converts duration (Sound) to inches
    duration = pulseIn(echopin, HIGH);
    return duration / 74 / 2;
}
```

3. Run the Simulation Test button and the ultrasonic sensor How to Work the Ultrasonic Sensor > Select Ultrasonic Sensor > Drag the blue location dot that represents an object



- 1. Add a push button that represents Emergency Stop
 - a. Activated only when in the Object is out of range with the ultrasonic sensor
 - b. When pressed Motor will stop
 - c. Attach a Speaker (See Reference Document Piezo) Will sound error sound; use Piezo Speaker (NOTE: noTone ("DIGITAL PORT#"); will turn off the piezo speaker
- 2. Distance Reactions
 - a. Object: Less than 8in and greater 125"
 - i. RGB LED: RED Color
 - ii. Output in Serial Monitor: Error! Out of Range NOTE: Only output 1 time
 - iii. Sound Piezo speaker until Emergency Button is pressed then turn off piezo speaker
 - iv. Stop Motor
 - b. Object: Object< = 15 or Object>=100
 - i. RGB LED: Yellow Color
 - ii. Output in Serial Monitor: Caution!!
 - iii. Motor Runs
 - c. Object: Object > 15 and Object < 100
 - i. RGB LED: Green Color
 - ii. Output in Serial Monitor: Within Operating Range
 - iii. Motor Runs

Submission: To Submit TinkerCAD Tutorials and Assignments: Select Share Icon (Top Right Corner) > Select Invite People > Copy URL > Navigate to Student Email Account > Compose a New Email > To: jourdem@brightonk12.com > Fill Subject Heading TinkerCAD "Tutorial or Assignment" "Tutorial/Assignment Name" > Send