



315 Commerce Blvd.  
 Liverpool, New York  
 Phone: 1-315-457-0181  
 Parts Fax: 1-800-950-4342  
 Office Fax: 1-315-457-0312

892-898 Troy Schenectady Rd Latham, New York  
 Phone: 1-518-785-5841  
 Parts Fax: 1-800-950-4342  
 Office Fax: 1-518-785-5740

Date:	6/15/2012
Inquiry Date:	
Prices Good Until:	
Estimated Delivery:	
Terms:	
F.O.B.	Delivered
Shipped Via:	Truck
Height of Cut:	
Purchase Order #	

To: Customer Name: Eden Central School  
 Address: 3150 Schoolview Rd  
 City State Zip: Eden, NY 14051  
 Phone: (716)992-3630  
 Attn: Dave Martin

Salesman	Gary Hughes
Cell Phone	716-570-2267
Email	ghughes@grasslandcorp.com

In Response to your inquiry, we submit the following Quotation

Qty	Model Number	Description	Sugg. 2011 Retail Price	Unit Price	Extension
<a href="#">In PDF version- Click on Image to link to Product Information on the web</a>					
1	30856-240000740	2004 Groundsmaster 4500-D,60HP Kubota, 9FT WOC, 2250 hours	\$9,247.14	\$9,247.14	\$9,247.14
1		Less trade-in of Toro Groundsmaster 455-D	#N/A		(\$1,000.00)

NOTES	TOTALS
	Total @ MSRP \$9,247.14
	Discount (\$1,000.00)
	<b>Total \$8,247.14</b>
	Toro Protection + \$ -
	Trade Ins \$ -
	Set Up \$ -
	Delivery Charges \$ -
	Fuel & Frt Surcharge
	<b>Subtotal \$8,247.14</b>
	Tax Rate
	Sales Tax
	<b>Total with Tax \$8,247.14</b>



Distributor of  
Power Equipment & Golf Course Supplies

802-808 Troy-Schenectady Road  
Latham, New York 12110  
PHONE: 518-786-6841  
FAX: 518-786-0740

315 Commerce Boulevard  
Liverpool, New York 13088  
PHONE: 315-457-0181  
FAX: 315-457-0312

C 3574  
U EDEN CENTRAL SCHOOL  
S 3150 SCHOOLVIEW RD  
T EDEN NY 14057  
992-3613/716-208-5601  
Attn: DAVE MARTIN

E MAKE: 30455  
Q MODEL: 30455  
U SERIAL #: 40307  
I GM 455D MOWER  
P SCHEDULED:  
TECH: 789

SERVICE WORK ORDER #119703  
DATE CALL PLACED 29 JUN 12  
PAGE 1 OF 3

Visit our web site at [www.grasslandcorp.com](http://www.grasslandcorp.com)

**\*\* COMMERCIAL CUSTOMER CHARGE \*\***

HOUR	METER	ENGINE	MODEL	SPEC.#	SERIAL.CODE	MECH	EST.TOTAL	EST.HOURS
2972							\$8,247.14	26.00
CODE	DESCRIPTION				QTY	UNIT.PRICE	EXT.AMOUNT	
<p>PROBLEM: THIS IS AN ESTIMAE FOR REPAIRS TO CORRECT STEERING PROBLEMS AND ADDRESS THE OIL LEAKS. WE WILL ALSO CHANGE THE ENGINE TIMING BELT WHICH IS WAY OVERDUE. THERE MAY BE MORE REPAIRS NEEDED BUT THESE ARE THE REPAIRS THAT WE KNOW OF RIGHT NOW WITHOUT TEARING THE WHOLE UNIT DOWN. ANY ADDITIONAL REPAIRS WILL BE QUOTED SEPARATELY FROM THIS ESTIMATE.</p> <p>Customer Signature: _____</p>								
101-99-7566	TRANSAXLE-2 SPEED				1 EA	1801.06	1801.06	
101-32151-62	RING				1 EA	1.53	1.53	
101-237-167	SEAL				1 EA	3.26	3.26	
101-237-79	O-RING				10 EA	3.29	32.90	
101-237-30	O-RING				10 EA	1.51	15.10	
101-237-65	O-RING				10 EA	1.51	15.10	
101-289-50	PIPE NIPPLE				1 EA	5.78	5.78	
101-72-4320	SEAT SWITCH				1 EA	65.43	65.43	
101-2812-11	BUSHING				1 EA	8.32	8.32	
101-302-14	VENT [M]				1 EA	4.01	4.01	
101-2813-14	ELBOW				1 EA	20.28	20.28	
101-289-44	PIPE NIPPLE				1 EA	5.78	5.78	
101-27-3710	DIPSTICK				1 EA	19.48	19.48	
101-76-4260	BUSHING				0	12.94	12.94	
101-94-5603	BUSHING				1 EA	39.50	39.50	
101-76-7580	O RING				2 EA	8.39	16.78	
101-92-6584	CYLINDER				1 EA	747.81	747.81	

C 3574  
 U EDEN CENTRAL SCHOOL  
 S 3150 SCHOOLVIEW RD  
 T EDEN NY 14057  
 992-3613/716-208-5601  
 Attn: DAVE MARTIN



692-898 Troy Schenectady Road 315 Commerce Boulevard  
 Latham, New York 12110 Liverpool, New York 13088  
 PHONE: 518-786-5841 PHONE: 315-497-0181  
 FAX: 818-786-6740 FAX: 315-487-0312

E MAKE: 30455  
 Q MODEL: 30455  
 U SERIAL #: 40307  
 I GM 455D MOWER  
 P SCHEDULED:  
 TECH: 789

SERVICE WORK ORDER #119703  
 DATE CALL PLACED 29 JUN 12  
 PAGE 2 OF 3

Visit our web site at [www.grasslandcorp.com](http://www.grasslandcorp.com)

**\*\* COMMERCIAL CUSTOMER CHARGE \*\***

CODE	DESCRIPTION	QTY	UNIT PRICE	EXT. AMOUNT
2972			\$8,247.14	26.00
101-32151-104	SNAP RING	2 EA	4.24	8.48
101-302-5	FITTING-GREASE [M]	3 EA	1.78	5.34
101-106-6774	JOINT-BALL	1 EA	45.82	45.82
101-92-5839	BALLJOINT	1 EA	104.14	104.14
101-92-5833	SPACER	2 EA	17.48	34.96
101-32136-14	NUT	2 EA	3.86	7.72
101-3272-12	PIN-COTTER [M]	2 EA	0.61	1.22
101-76-6570	WASHER	4 EA	3.11	12.44
101-74-5250	PIVOT PIN WA	1 EA	62.20	62.20
101-32144-11	SCREW	1 EA	3.34	3.34
101-76-7830	SHAFT	2 EA	707.14	1414.28
101-76-7870	SEAL	2 EA	43.68	87.36
101-76-7810	HOLDER	2 EA	234.73	469.46
101-76-7930	RING	2 EA	9.36	18.72
101-76-7890	LINER	2 EA	2.28	4.56
101-94-5643	BEARING	2 EA	85.43	170.86
101-76-7860	BEARING	2 EA	95.90	191.80
101-77-8830	RETAINER	2 EA	5.17	10.34
101-74-8830	BELT-TIMING [M]	1 EA	70.04	70.04
LBR		30.00 HRS	82.00	2460.00
PU	PICK-UP &			200.00



Distributor of  
Power Equipment & Golf Course Supplies

892-898 Troy-Schenectady Road 315 Commerce Boulevard  
Latham, New York 12110 Liverpool, New York 13088  
PHONE: 518-786-6641 PHONE: 315-457-0181  
FAX: 518-786-6740 FAX: 315-457-0312

C 3574  
U EDEN CENTRAL SCHOOL  
S 3150 SCHOOLVIEW RD  
T EDEN NY 14057  
992-3613/716-208-5601  
Attn: DAVE MARTIN

E MAKE: 30455  
Q MODEL: 30455  
U SERIAL #: 40307  
I GM 455D MOWER  
P SCHEDULED:  
TECH: 789

SERVICE WORK ORDER #119703  
DATE CALL PLACED 29 JUN 12  
PAGE 1 OF 3

Visit our web site at [www.grasslandcorp.com](http://www.grasslandcorp.com)

\*\* COMMERCIAL CUSTOMER CHARGE \*\*

HOUR.	METER	ENGINE	MODEL	SPEC.#	SERIAL.CODE	MECH	EST.TOTAL	EST.HOURS
2972							\$8,247.14	26.00
CODE	DESCRIPTION				QTY	UNIT PRICE	EXT.AMOUNT	
<p>PROBLEM: THIS IS AN ESTIMAE FOR REPAIRS TO CORRECT STEERING PROBLEMS AND ADDRESS THE OIL LEAKS. WE WILL ALSO CHANGE THE ENGINE TIMING BELT WHICH IS WAY OVERDUE. THERE MAY BE MORE REPAIRS NEEDED BUT THESE ARE THE REPAIRS THAT WE KNOW OF RIGHT NOW WITHOUT TEARING THE WHOLE UNIT DOWN. ANY ADDITIONAL REPAIRS WILL BE QUOTED SEPARATELY FROM THIS ESTIMATE.</p> <p>Customer Signature: _____</p>								
101-99-7566	TRANSAXLE-2 SPEED				1 EA	1801.06	1801.06	
101-32151-62	RING				1 EA	1.53	1.53	
101-237-167	SEAL				1 EA	3.26	3.26	
101-237-79	O-RING				10 EA	3.29	32.90	
101-237-30	O-RING				10 EA	1.51	15.10	
101-237-65	O-RING				10 EA	1.51	15.10	
101-289-50	PIPE NIPPLE				1 EA	5.78	5.78	
101-72-4320	SEAT SWITCH				1 EA	65.43	65.43	
101-2812-11	BUSHING				1 EA	8.32	8.32	
101-302-14	VENT [M]				1 EA	4.01	4.01	
101-2813-14	ELBOW				1 EA	20.28	20.28	
101-289-44	PIPE NIPPLE				1 EA	5.78	5.78	
101-27-3710	DIPSTICK				1 EA	19.48	19.48	
101-76-4260	BUSHING				0	12.94	12.94	
101-94-5603	BUSHING				1 EA	39.50	39.50	
101-76-7580	O RING				2 EA	8.39	16.78	
101-92-6584	CYLINDER				1 EA	747.81	747.81	

T EDEN NY 14057  
 992-3613/716-208-5601  
 Attn: DAVE MARTIN

892-898 Troy Schwanctedy Road 315 Commerce Boulevard  
 Latham, New York 12110 Liverpool, New York 13088  
 PHONE: 518-786-5841 PHONE: 315-457-0181  
 FAX: 518-786-6740 FAX: 315-457-0312

E MAKE: 30455  
 Q MODEL: 30455  
 U SERIAL #: 40307  
 I GM 455D MOWER  
 P SCHEDULED:  
 TECH: 789

SERVICE WORK ORDER #119703  
 DATE CALL PLACED 29 JUN 12  
 PAGE 2 OF 3

Visit our web site at [www.grasslandcorp.com](http://www.grasslandcorp.com)

**\*\* COMMERCIAL CUSTOMER CHARGE \*\***

CODE	DESCRIPTION	QTY	UNIT PRICE	EXT. AMOUNT
2972			\$8,247.14	26.00
101-32151-104	SNAP RING	2 EA	4.24	8.48
101-302-5	FITTING-GREASE [M]	3 EA	1.78	5.34
101-106-6774	JOINT-BALL	1 EA	45.82	45.82
101-92-5839	BALLJOINT	1 EA	104.14	104.14
101-92-5833	SPACER	2 EA	17.48	34.96
101-32136-14	NUT	2 EA	3.86	7.72
101-3272-12	PIN-COTTER [M]	2 EA	0.61	1.22
101-76-6570	WASHER	4 EA	3.11	12.44
101-74-5250	PIVOT PIN WA	1 EA	62.20	62.20
101-32144-11	SCREW	1 EA	3.34	3.34
101-76-7830	SHAFT	2 EA	707.14	1414.28
101-76-7870	SEAL	2 EA	43.68	87.36
101-76-7810	HOLDER	2 EA	234.73	469.46
101-76-7930	RING	2 EA	9.36	18.72
101-76-7890	LINER	2 EA	2.28	4.56
101-94-5643	BEARING	2 EA	85.43	170.86
101-76-7860	BEARING	2 EA	95.90	191.80
101-77-8830	RETAINER	2 EA	5.17	10.34
101-74-8830	BELT-TIMING [M]	1 EA	70.04	70.04
LBR		30.00 HRS	82.00	2460.00
PU	PICK-UP &			200.00

C 3574  
 U EDEN CENTRAL SCHOOL  
 S 3150 SCHOOLVIEW RD  
 T EDEN NY 14057  
 992-3613/716-208-5601  
 Attn: DAVE MARTIN



*Distributor of  
 Power Equipment & Golf Course Supplies*

882-888 Troy Schenectady Road 315 Commerce Boulevard  
 Latham, New York 12110 Liverpool, New York 13000  
 PHONE: 518-785-5841 PHONE: 315-457-0181  
 FAX: 518-785-0740 FAX: 315-457-0512

E MAKE: 30455  
 Q MODEL: 30455  
 U SERIAL #: 40307  
 I GM 455D MOWER  
 P SCHEDULED:  
 TECH: 789

SERVICE WORK ORDER #119703  
 DATE CALL PLACED 29 JUN 12  
 PAGE 3 OF 3

Visit our web site at [www.grasslandcorp.com](http://www.grasslandcorp.com)

**\*\* COMMERCIAL CUSTOMER CHARGE \*\***

HOUR	METER	ENGINE	MODEL SPEC.#	SERIAL.CODE	MECH	EST.TOTAL	EST.HOURS
2972						\$8,247.14	26.00
CODE	DESCRIPTION				QTY	UNIT.PRICE	EXT.AMOUNT
OL	DELIVERY/SERVICE DEPT.						21.00
OL	ENGINE OIL						28.00
	HYD FLUID AND LUBES						

**EDEN CENTRAL SCHOOL TRANSPORTATION DEPARTMENT**

Date: 8/08/2012

Dear Mr. Buggs:

I am recommending that we surplus bus #167 with a 66 passenger capacity. It is a 2002 Freightliner. The VIN. # is 4UZAAXAK62CJ74842. The bus has 125,954 miles on it. I am recommending this due to the declining condition of the bus' interior and exterior body and not enough money in the budget to fix it.

Please advise.

Thank You!

Rose M. Heckathorn  
Transportation Supervisor

cc. Lisa Almasi  
Barbara Thomasulo

# MORRIS MASONRY RESTORATION

441 Bailey Ave  
Buffalo, NY 14210

Phone: (716) 894-0102  
Fax: (716) 894-8194

TO: Charles W Moore, RA LEEP AP  
Trautman Associates

DATE: 08/01/12

Re: **Eden CSD**  
**Additional Masonry Repointing 12012**  
RFP #: MMR-01

---

We propose to furnish all labor, materials, tools & equipment to perform the following scope:

**Castle Parapet**

- Cut out deteriorated mortar joints & repoint (100 SF).
- Cut out existing joint sealant at stone band on all 4 sides of castle parapet and repoint with mortar (264 LF).
- Roof protection & scaffold.
- Man lift.

<b>Quotation:</b>	<b>\$9,065.00</b>
-------------------	-------------------

---

**Decorative Stone/Brick Pier**

- Cut out deteriorated mortar joints & repoint (20 SF).
- Cut out existing joint sealant in stone joints & repoint with mortar.
- Roof protection & scaffold.
- Man lift.

<b>Quotation:</b>	<b>\$3,775.00</b>
-------------------	-------------------

---

Excludes: Sales tax  
Permits  
Removal, handling and/or disposal of hazardous materials.

This pricing will be held firm for 45 days.