

February 20, 2025

Molly Howell Project Coordinator Beaverton School District

Via email: molly_howell@beaverton.k12.or.us

Regarding: Short-Term Radon Testing Beaverton School District, District Support Center Out Buildings 16550 SW Merlo Road Beaverton, Oregon 97003

Ms. Howell:

From January 27 to January 30, 2025, PBS Engineering and Environmental Inc. (PBS) performed short-term radon testing at Beaverton School District's District Support Center Out Buildings located at 16550 SW Merlo Road in Beaverton, Oregon.

The out buildings included 10 modular and portable structures located at the District Support Center.

METHODOLOGY

The Environmental Protection Agency (EPA) recommends, and the Oregon Health Authority (OHA) requires, that school buildings be tested for radon, and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. PBS used Radonova, Inc., brand single-use, short-term radon test kits to measure radon levels in frequently occupied rooms that are in contact with the ground or above unoccupied basements or crawlspaces. These rooms include classrooms, offices, break rooms, conference rooms, gyms, and cafeterias. Restrooms, hallways, stairwells, storage rooms, and closets are not tested. Testing was completed during the winter heating season and during a regular school week when building use and operations are normal.

PBS endeavored to use sample location names based on existing room numbers or common-sense descriptions. In buildings or areas where no room number or other designation was available, PBS assigned names or numbers to the rooms. In some circumstances, small numbers of test kits go missing during the testing period and those locations are not tested. PBS will evaluate whether or not the missing area should be retested based on the results of surrounding areas.

RESULTS

Laboratory results found concentrations below the EPA action level of 4 pCi/L in all tested locations in the building. Please see the attached laboratory analysis report for more details and testing locations.

In addition to the EPA recommendation that radon concentrations be maintained below 4.0 pCi/L, OHA recommends the following steps based on the results of a room's initial short-term test:

• If the result is less than 2.0 pCi/L, school districts are required to test again every 10 years, per Oregon Revised Statute 332.166-167.

Beaverton School District Short-Term Radon Testing Report – District Support Center Out Buildings February 20, 2025 Page 2 of 2

- If the result is between 2.0 pCi/L and 4.0 pCi/L, consider fixing (i.e., lowering) the radon in that room.
- If the result is from 4.0 pCi/L to 8.0 pCi/L, perform a follow-up measurement of that room using a long-term test. This test should be conducted over as much of a nine-month school year as possible, when the room is likely to be occupied. If that result is equal to or greater than 4.0 pCi/L, the radon in the room should be fixed (i.e., lowered).
- If the initial short-term test result is equal to or greater than 8.0 pCi/L, conduct a second short-term test and average its result with the initial short-term test result. If the average of the two is equal to or greater than 4.0 pCi/L, radon in the room should be fixed (i.e., lowered).

Note: A great difference in the results of the short-term tests may indicate a flaw in the testing process. Investigate and consider retesting. For situations in which one of the test results is equal to or greater than 4.0 pCi/L, if the higher result is two or more times the lower result, repeat the test.

LIMITATIONS OF SCOPE

This study was limited to the tests and locations as previously indicated. The site as a whole may have other environmental concerns that will not be characterized by this study. The findings and conclusions of this work are not scientific certainties, but probabilities based on professional judgment concerning the significance of the data gathered during the course of this investigation. PBS is not able to represent conditions on the site or adjoining sites beyond those detected or observed by PBS.

Please feel free to contact me at 503.417.7603 or rich@pbsusa.com with any questions or comments.

Sincerely,

Rich Dufresne Senior Project Manager

Attachment: Radonova Laboratory Analysis Report



> REPORT PAGE 1 of 3

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

Property data and address

MEASURE SITE ADDRESS DSC Out Buildings

BUILDING ID

Test results

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|---|------------------------|------------|--------------|
| RK151447 [QuickScreen] | 02/10/2025 10:34 AM – 02/13/2025 08:45 AM | P1, Standard | | < 0.6 pCi/L |
| RK151469 [QuickScreen] | 02/10/2025 10:35 AM – 02/13/2025 08:46 AM | P2, Standard | | < 0.6 pCi/L |
| RK151429 [QuickScreen] | 02/10/2025 10:37 AM – 02/13/2025 09:54 AM | P3, Standard | | < 0.6 pCi/L |
| RK151456 [QuickScreen] | 02/10/2025 10:38 AM – 02/13/2025 09:55 AM | P4, Standard | | < 0.6 pCi/L |
| RK151434 [QuickScreen] | 02/10/2025 10:41 AM – 02/13/2025 09:55 AM | P5A, Standard | | < 0.6 pCi/L |
| RK151430 [QuickScreen] | 02/10/2025 10:41 AM – 02/13/2025 09:56 AM | P5B, Standard | | < 0.6 pCi/L |
| RK151426 [QuickScreen] | 02/10/2025 10:41 AM – 02/13/2025 09:56 AM | P5B DUP, Duplicate | | < 0.6 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.



> REPORT PAGE 2 of 3

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|---|--------------------------|------------|--------------|
| RK151464 [QuickScreen] | 02/10/2025 10:43 AM – 02/13/2025 09:57 AM | P6B, Standard | | < 0.6 pCi/L |
| RK151448 [QuickScreen] | 02/10/2025 10:43 AM – 02/13/2025 09:57 AM | P6A, Standard | | < 0.6 pCi/L |
| RK151441 [QuickScreen] | 02/10/2025 10:46 AM – 02/13/2025 09:58 AM | P7A, Standard | | < 0.6 pCi/L |
| RK152816 [QuickScreen] | 02/10/2025 10:46 AM – 02/13/2025 09:58 AM | P7B, Standard | | < 0.7 pCi/L |
| RK152346 [QuickScreen] | 02/10/2025 11:01 AM – 02/13/2025 08:50 AM | Modular 1, Standard | | < 0.7 pCi/L |
| RK152388 [QuickScreen] | 02/10/2025 10:51 AM – 02/13/2025 08:50 AM | Modular 2, Standard | | < 0.7 pCi/L |
| RK151455 [QuickScreen] | 02/10/2025 10:53 AM – 02/13/2025 08:50 AM | Modular 3, Standard | | 0.6 pCi/L |
| RK151439 [QuickScreen] | 02/10/2025 10:53 AM – 02/13/2025 08:50 AM | Modular 3 DUP, Duplicate | | < 0.7 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS DSC Out Buildings



 REPORT NUMBER
 REPORT DATE

 6689307:1
 02/19/2025

 REPORT PAGE
 PRINT DATE

3 of 3

PRINT DATE 02/19/2025

OWN ID 24010915

What Does My Result Mean?

The United States Environmental Protection Agency (EPA) recommends remediation if the results of one long-term test (greater than 90 days) or one short-term test with a continuous monitor or the average of two passive short-term (less than 90 days) tests* conducted in the lowest lived-in level of the home report at or above 4.0 pCi/L. *If an initial short-term test result is less than 4 pCi/L, a follow-up measurement is probably not needed. If an initial short-term test result is between 4 pCi/L and 8 pCi/L, a long-term or a short-term follow-up measurement is recommended. If an initial short-term test result is greater than 8 pCi/L, a short-term follow-up measurement is recommended. For more information, or to find a certified mitigation professional, contact your state radon office, the National Radon Proficiency Program (www.nrpp.info) or the National Radon Safety Board (www.nrsb.org).

Result (pCi/L) Recommended Action

Less than 2.0 Retest the building at least every 5 years

2.0 - 3.9 Consider Mitigation, retest the building at least every 5 years

4.0 or Higher Mitigate, test again at least every 2 years to ensure that the system remains effective

Measurement method: Activated Charcoal Adsorption

For this method using the QuickScreen detector, the airtight container with activated charcoal is opened in the area to be sampled and radon in the air adsorbs onto the charcoal granules. At the end of the sampling period, the container is sealed and may be sent to a laboratory for analysis. The gamma decay from the radon adsorbed to the charcoal is counted on a scintillation detector and a calculation based on calibration information is used to calculate the radon concentration at the sample site.

Measured radon concentrations

For each detector, the measured value of the radon concentration is provided. For each value an uncertainty associated with the measurement to a 95% confidence level is also provided. For example a measurement result of 4.0 ± 0.5 pCi/L means that the radon concentration is most likely contained in the range 3.5 - 4.5 pCi/L. If the start or end date of the measurement has not been provided, the radon concentration cannot be calculated. In such cases, the total exposure in pCi*days/L will be reported. The reported measured values are related to the detectors as received by Radonova Laboratories. Detector deployment is not performed by Radonova Laboratories. Measurement information such as monitoring period (dates) and placement location is provided to Radonova Laboratories by the end user. The presented result applies only to the sample tested as received by the laboratory.

Codes on non-reportable detectors

| DNR | Not Reported – Detector Not Returned |
|-----|--------------------------------------|
| ERR | Not Reported – See comment |

Measurement method versions used when the report was created

ANSI/AARST MAH-2023, Protocol for Conducting Measurements of Radon and Radon Decay Products in Homes ANSI/AARST MA-MFLB-2023, Protocol for Measurements of Radon in Multifamily, School, Commercial and Mixed-Use Buildings

Radon measurements in the US

The United States Environmental Protection Agency (EPA) recommends remediation if the results of one long-term test or the average of two short-term tests conducted in the lowest lived-in level of the home report at or above 4.0 pCi/L. The average yearly residential indoor radon level in the US is estimated to be around 1.3 pCi/L. Long-term tests are conducted for more than 90 days. Short-term tests are conducted between 2 and 90 days and should be per-formed under closed building conditions. If an initial short-term test result is less than 4 pCi/L, a follow-up measurement is probably not needed. If an initial short-term test result is greater than 10 pCi/L, a short-term follow-up measurement is recommended in order to get a fast result. If an initial short-term test result is between 4 pCi/L and 10 pCi/L, a long-term or a short-term follow-up measurement is recommended. For more information about the interpretation of your test results or about other radon related issues we suggest contacting your state radon office.

Your state radon office should have the available EPA publications:

- A Citizen's Guide to Radon
- Home Buyer's and Seller's Guide to Radon
- Consumer's Guide to Radon Reduction

Signature on the report

With the signature on the report, the Measurement specialist at Radonova Laboratories certifies that the quality control procedures follows the guidance in accordance with the AARST/ANSI Measurement Protocols. Measurement information displayed in italics on report has been provided by the customer.

Certification no:

101132-AL, 107830-RMP, NY ELAP ID: 11430

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.



February 20, 2025

Molly Howell Project Coordinator Beaverton School District

Via email: molly_howell@beaverton.k12.or.us

Regarding: Short-Term Radon Testing Beaverton School District, District Support Center 16550 SW Merlo Road Beaverton, Oregon 97003

Ms. Howell:

From January 27 to January 30, 2025, PBS Engineering and Environmental Inc. (PBS) performed short-term radon testing at Beaverton School District's District Support Center located at 16550 SW Merlo Road in Beaverton, Oregon.

METHODOLOGY

The Environmental Protection Agency (EPA) recommends, and the Oregon Health Authority (OHA) requires, that school buildings be tested for radon, and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. PBS used Radonova, Inc., brand single-use, short-term radon test kits to measure radon levels in frequently occupied rooms that are in contact with the ground or above unoccupied basements or crawlspaces. These rooms include classrooms, offices, break rooms, conference rooms, gyms, and cafeterias. Restrooms, hallways, stairwells, storage rooms, and closets are not tested. Testing was completed during the winter heating season and during a regular school week when building use and operations are normal.

PBS endeavored to use sample location names based on existing room numbers or common-sense descriptions. In buildings or areas where no room number or other designation was available, PBS assigned names or numbers to the rooms. In some circumstances, small numbers of test kits go missing during the testing period and those locations are not tested. PBS will evaluate whether or not the missing area should be retested based on the results of surrounding areas.

RESULTS

Laboratory results found concentrations below the EPA action level of 4 pCi/L in all tested locations in the building. Please see the attached laboratory analysis report for more details and testing locations.

In addition to the EPA recommendation that radon concentrations be maintained below 4.0 pCi/L, OHA recommends the following steps based on the results of a room's initial short-term test:

- If the result is less than 2.0 pCi/L, school districts are required to test again every 10 years, per Oregon Revised Statute 332.166-167.
- If the result is between 2.0 pCi/L and 4.0 pCi/L, consider fixing (i.e., lowering) the radon in that room.

Beaverton School District Short-Term Radon Testing Report – District Support Center February 20, 2025 Page 2 of 2

- If the result is from 4.0 pCi/L to 8.0 pCi/L, perform a follow-up measurement of that room using a long-term test. This test should be conducted over as much of a nine-month school year as possible, when the room is likely to be occupied. If that result is equal to or greater than 4.0 pCi/L, the radon in the room should be fixed (i.e., lowered).
- If the initial short-term test result is equal to or greater than 8.0 pCi/L, conduct a second short-term test and average its result with the initial short-term test result. If the average of the two is equal to or greater than 4.0 pCi/L, radon in the room should be fixed (i.e., lowered).

Note: A great difference in the results of the short-term tests may indicate a flaw in the testing process. Investigate and consider retesting. For situations in which one of the test results is equal to or greater than 4.0 pCi/L, if the higher result is two or more times the lower result, repeat the test.

LIMITATIONS OF SCOPE

This study was limited to the tests and locations as previously indicated. The site as a whole may have other environmental concerns that will not be characterized by this study. The findings and conclusions of this work are not scientific certainties, but probabilities based on professional judgment concerning the significance of the data gathered during the course of this investigation. PBS is not able to represent conditions on the site or adjoining sites beyond those detected or observed by PBS.

Please feel free to contact me at 503.417.7603 or rich@pbsusa.com with any questions or comments.

Sincerely,

Rich Dufresne Senior Project Manager

Attachment: Radonova Laboratory Analysis Report



> REPORT PAGE 1 of 8

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

Property data and address

MEASURE SITE ADDRESS District Support Center

BUILDING ID

Test results

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|---|------------------------------------|------------|--------------|
| RK151892 [QuickScreen] | 02/10/2025 09:12 AM – 02/13/2025 08:57 AM | A107, Standard | | < 0.6 pCi/L |
| RK151869 [QuickScreen] | 02/10/2025 09:23 AM – 02/13/2025 08:57 AM | A101 Crater Lake room, Standard | | < 0.7 pCi/L |
| RK152204 [QuickScreen] | 02/10/2025 09:23 AM – 02/13/2025 08:57 AM | A101 Crater Lake room, Standard | | < 0.6 pCi/L |
| RK151699 [QuickScreen] | 02/10/2025 09:28 AM – 02/13/2025 08:58 AM | A108, Standard | | < 0.7 pCi/L |
| RK151651 [QuickScreen] | 02/10/2025 09:29 AM – 02/13/2025 09:02 AM | B100 staff, Standard | | < 0.6 pCi/L |
| RK150705 [QuickScreen] | 02/10/2025 09:31 AM – 02/13/2025 09:03 AM | B102 Klamath Lake room 1, Standard | | < 0.7 pCi/L |
| RK150782 [QuickScreen] | 02/10/2025 09:31 AM – 02/13/2025 09:03 AM | B104 Klamath Lake room 2, Standard | | 0.7 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.



> REPORT PAGE 2 of 8

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|--|--|------------|--------------|
| RK150718 [QuickScreen] | 02/10/2025 09:33 AM – 02/13/2025 09:04 | AM B106 Klamath Lake room 3, Standard | | 0.7 pCi/L |
| RK150698 [QuickScreen] | 02/10/2025 09:34 AM – 02/13/2025 09:05 | AMB110 Klamath Lake room 4, Standard | | < 0.6 pCi/L |
| RK150748 [QuickScreen] | 02/10/2025 09:37 AM – 02/13/2025 09:06 | AMC101 Wallowa Lake room north, Standard | | 0.7 pCi/L |
| RK150723 [QuickScreen] | 02/10/2025 09:37 AM – 02/13/2025 09:06 | AMC101 Wallowa Lake room center, Standard | | 0.7 pCi/L |
| RK150759 [QuickScreen] | 02/10/2025 09:37 AM – 02/13/2025 09:06 | AMC101 Wallowa Lake room south, Standard | | < 0.6 pCi/L |
| RK150711 [QuickScreen] | 02/10/2025 09:37 AM – 02/13/2025 09:06 | AMC101 Wallowa Lake room DUP, Duplicate | | 0.7 pCi/L |
| RK150702 [QuickScreen] | 02/10/2025 09:39 AM – 02/13/2025 09:08 | AM Facility development entrance, Standard | | 1.5 pCi/L |
| RK150357 [QuickScreen] | 02/10/2025 09:41 AM – 02/13/2025 09:08 | AM D140, Standard | | < 0.7 pCi/L |
| RK150365 [QuickScreen] | 02/10/2025 09:41 AM – 02/13/2025 09:08 | AM D142, Standard | | < 0.7 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS District Support Center



REPORT PAGE 3 of 8 REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM | FLOOR | RADON RESULT |
|------------------------|---|--|------|-------|--------------|
| RK150366 [QuickScreen] | 02/10/2025 09:41 AM – 02/13/2025 09:09 AM | Facilities development foyer, Standard | | | 1.1 pCi/L |
| RK150747 [QuickScreen] | 02/10/2025 09:42 AM – 02/13/2025 09:11 AM | D136, Standard | | | 2.6 pCi/L |
| RK150760 [QuickScreen] | 02/10/2025 09:43 AM – 02/13/2025 09:11 AM | D134, Standard | | | 1.9 pCi/L |
| RK150375 [QuickScreen] | 02/10/2025 09:44 AM – 02/13/2025 09:11 AM | D132, Standard | | | 1.1 pCi/L |
| RK151700 [QuickScreen] | 02/10/2025 09:45 AM – 02/13/2025 09:12 AM | D130, Standard | | | 1.2 pCi/L |
| RK151629 [QuickScreen] | 02/10/2025 09:45 AM – 02/13/2025 09:12 AM | D124, Standard | | | 0.7 pCi/L |
| RK152183 [QuickScreen] | 02/10/2025 09:47 AM – 02/13/2025 09:13 AM | D122, Standard | | | 1.2 pCi/L |
| RK152115 [QuickScreen] | 02/10/2025 09:48 AM – 02/13/2025 09:13 AM | D120, Standard | | | 1.4 pCi/L |
| RK150793 [QuickScreen] | 02/10/2025 09:48 AM – 02/13/2025 09:13 AM | D120 DUP, Duplicate | | | 1.3 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS District Support Center



REPORT PAGE 4 of 8 REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|---|-------------------------|------------|--------------|
| RK151663 [QuickScreen] | 02/10/2025 09:48 AM – 02/13/2025 09:14 AM | D118, Standard | | 1.6 pCi/L |
| RK151814 [QuickScreen] | 02/10/2025 09:49 AM – 02/13/2025 09:14 AM | D116, Standard | | 1.4 pCi/L |
| RK152146 [QuickScreen] | 02/10/2025 09:49 AM – 02/13/2025 09:18 AM | D101, Standard | | 1.5 pCi/L |
| RK151619 [QuickScreen] | 02/10/2025 09:52 AM – 02/13/2025 09:18 AM | D103, Standard | | 1.5 pCi/L |
| RK150749 [QuickScreen] | 02/10/2025 09:53 AM – 02/13/2025 09:15 AM | D114, Standard | | 0.7 pCi/L |
| RK150389 [QuickScreen] | 02/10/2025 09:53 AM – 02/13/2025 09:16 AM | D114 DUP, Duplicate | | 0.7 pCi/L |
| RK147738 [QuickScreen] | 02/10/2025 09:54 AM – 02/13/2025 09:16 AM | D105 cubicles, Standard | | 0.8 pCi/L |
| RK150797 [QuickScreen] | 02/10/2025 09:55 AM – 02/13/2025 09:17 AM | D106, Standard | | 1.0 pCi/L |
| RK150360 [QuickScreen] | 02/10/2025 09:56 AM – 02/13/2025 09:17 AM | D104, Standard | | 1.0 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address MEASURE SITE ADDRESS

District Support Center



REPORT PAGE 5 of 8 REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM FLOOR | RADON RESULT |
|------------------------|---|--------------------------------|------------|--------------|
| RK152158 [QuickScreen] | 02/10/2025 09:56 AM – 02/13/2025 09:17 AM | D102, Standard | | 1.0 pCi/L |
| RK151875 [QuickScreen] | 02/10/2025 09:57 AM – 02/13/2025 09:24 AM | E100 huddle room, Standard | | < 0.7 pCi/L |
| RK152186 [QuickScreen] | 02/10/2025 09:59 AM – 02/13/2025 09:24 AM | E116 office, Standard | | < 0.6 pCi/L |
| RK151694 [QuickScreen] | 02/10/2025 10:00 AM – 02/13/2025 09:24 AM | E116 purchasing, Standard | | < 0.5 pCi/L |
| RK152127 [QuickScreen] | 02/10/2025 10:02 AM – 02/13/2025 09:24 AM | E116 purchasing, Standard | | < 0.5 pCi/L |
| RK152190 [QuickScreen] | 02/10/2025 10:04 AM – 02/13/2025 09:25 AM | E109, Standard | | < 0.7 pCi/L |
| RK151635 [QuickScreen] | 02/10/2025 10:04 AM – 02/13/2025 09:31 AM | IT training lab, Standard | | < 0.7 pCi/L |
| RK152119 [QuickScreen] | 02/10/2025 10:05 AM – 02/13/2025 09:31 AM | IT training lab DUP, Duplicate | | < 0.6 pCi/L |
| RK151664 [QuickScreen] | 02/10/2025 10:06 AM – 02/13/2025 09:33 AM | Repair room, Standard | | < 0.7 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS District Support Center



> REPORT PAGE 6 of 8

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM | FLOOR | RADON RESULT |
|------------------------|---|----------------------------------|------|-------|--------------|
| RK150750 [QuickScreen] | 02/10/2025 10:07 AM – 02/13/2025 09:33 AM | DSC south meeting room, Standard | | | 1.4 pCi/L |
| RK150710 [QuickScreen] | 02/10/2025 10:07 AM – 02/13/2025 09:33 AM | F102 staff room, Standard | | | 0.7 pCi/L |
| RK150779 [QuickScreen] | 02/10/2025 10:08 AM – 02/13/2025 09:35 AM | F136, Standard | | | < 0.6 pCi/L |
| RK150755 [QuickScreen] | 02/10/2025 10:09 AM – 02/13/2025 09:35 AM | Reception, Standard | | | 0.7 pCi/L |
| RK150752 [QuickScreen] | 02/10/2025 10:09 AM – 02/13/2025 09:35 AM | Work room, Standard | | | < 0.6 pCi/L |
| RK150562 [QuickScreen] | 02/10/2025 10:10 AM – 02/13/2025 09:36 AM | F134, Standard | | | < 0.6 pCi/L |
| RK150545 [QuickScreen] | 02/10/2025 10:11 AM – 02/13/2025 09:36 AM | F132, Standard | | | 0.6 pCi/L |
| RK150568 [QuickScreen] | 02/10/2025 10:11 AM – 02/13/2025 09:38 AM | F130, Standard | | | 0.8 pCi/L |
| RK149063 [QuickScreen] | 02/10/2025 10:12 AM – 02/13/2025 09:38 AM | F128, Standard | | | < 0.7 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS District Support Center



> REPORT PAGE 7 of 8

REPORT DATE 02/19/2025

PRINT DATE 02/19/2025

OWN ID 24010915

BY

Apex Companies LLC (Portland)

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with Activated Charcoal Adsorption by Alpha Energy Laboratories (NRPP ID: 101132 AL).

The detector(s) arrived to Alpha Energy Laboratories, Inc. **02/17/2025**. They were measured **02/17/2025**.

No person has signed the record card and verified that the instructions have been followed.

| DETECTOR | MEASUREMENT PERIOD | DESCRIPTION / LOCATION | ROOM | FLOOR | RADON RESULT |
|------------------------|---|--------------------------|------|-------|--------------|
| RK149046 [QuickScreen] | 02/10/2025 10:12 AM – 02/13/2025 09:38 AM | F128 DUP, Duplicate | | | 0.9 pCi/L |
| RK146971 [QuickScreen] | 02/10/2025 10:13 AM – 02/13/2025 09:39 AM | F126, Standard | | | < 0.4 pCi/L |
| RK147023 [QuickScreen] | 02/10/2025 10:14 AM – 02/13/2025 09:39 AM | F124, Standard | | | 0.7 pCi/L |
| RK146979 [QuickScreen] | 02/10/2025 10:16 AM – 02/13/2025 09:24 AM | F111, Standard | | | < 0.5 pCi/L |
| RK146987 [QuickScreen] | 02/10/2025 10:16 AM – 02/13/2025 09:42 AM | F111, Standard | | | < 0.5 pCi/L |
| RK147011 [QuickScreen] | 02/10/2025 10:18 AM – 02/13/2025 09:42 AM | IT common area, Standard | | | < 0.5 pCi/L |
| RK147055 [QuickScreen] | 02/10/2025 10:20 AM – 02/13/2025 09:42 AM | F138, Standard | | | < 0.6 pCi/L |

Comment to the results

Steve Leslie (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.

RADONOVA INC. 1 EAST 22nd STREET, SUITE 200 LOMBARD, IL 60148 331.814.2200, help@radonova.com

Property data and address

MEASURE SITE ADDRESS District Support Center



 REPORT NUMBER
 REPORT DATE

 6689306:1
 02/19/2025

REPORT PAGE

8 of 8

PRINT DATE 02/19/2025

OWN ID 24010915

What Does My Result Mean?

The United States Environmental Protection Agency (EPA) recommends remediation if the results of one long-term test (greater than 90 days) or one short-term test with a continuous monitor or the average of two passive short-term (less than 90 days) tests* conducted in the lowest lived-in level of the home report at or above 4.0 pCi/L. *If an initial short-term test result is less than 4 pCi/L, a follow-up measurement is probably not needed. If an initial short-term test result is between 4 pCi/L and 8 pCi/L, a long-term or a short-term follow-up measurement is recommended. If an initial short-term test result is greater than 8 pCi/L, a short-term follow-up measurement is recommended. For more information, or to find a certified mitigation professional, contact your state radon office, the National Radon Proficiency Program (www.nrpp.info) or the National Radon Safety Board (www.nrsb.org).

Result (pCi/L) Recommended Action

Less than 2.0 Retest the building at least every 5 years

2.0 - 3.9 Consider Mitigation, retest the building at least every 5 years

4.0 or Higher Mitigate, test again at least every 2 years to ensure that the system remains effective

Measurement method: Activated Charcoal Adsorption

For this method using the QuickScreen detector, the airtight container with activated charcoal is opened in the area to be sampled and radon in the air adsorbs onto the charcoal granules. At the end of the sampling period, the container is sealed and may be sent to a laboratory for analysis. The gamma decay from the radon adsorbed to the charcoal is counted on a scintillation detector and a calculation based on calibration information is used to calculate the radon concentration at the sample site.

Measured radon concentrations

For each detector, the measured value of the radon concentration is provided. For each value an uncertainty associated with the measurement to a 95% confidence level is also provided. For example a measurement result of 4.0 ± 0.5 pCi/L means that the radon concentration is most likely contained in the range 3.5 - 4.5 pCi/L. If the start or end date of the measurement has not been provided, the radon concentration cannot be calculated. In such cases, the total exposure in pCi*days/L will be reported. The reported measured values are related to the detectors as received by Radonova Laboratories. Detector deployment is not performed by Radonova Laboratories. Measurement information such as monitoring period (dates) and placement location is provided to Radonova Laboratories by the end user. The presented result applies only to the sample tested as received by the laboratory.

Codes on non-reportable detectors

| DNR | Not Reported – Detector Not Returned |
|-----|--------------------------------------|
| ERR | Not Reported – See comment |

Measurement method versions used when the report was created

ANSI/AARST MAH-2023, Protocol for Conducting Measurements of Radon and Radon Decay Products in Homes ANSI/AARST MA-MFLB-2023, Protocol for Measurements of Radon in Multifamily, School, Commercial and Mixed-Use Buildings

Radon measurements in the US

The United States Environmental Protection Agency (EPA) recommends remediation if the results of one long-term test or the average of two short-term tests conducted in the lowest lived-in level of the home report at or above 4.0 pCi/L. The average yearly residential indoor radon level in the US is estimated to be around 1.3 pCi/L. Long-term tests are conducted for more than 90 days. Short-term tests are conducted between 2 and 90 days and should be per-formed under closed building conditions. If an initial short-term test result is less than 4 pCi/L, a follow-up measurement is probably not needed. If an initial short-term test result is greater than 10 pCi/L, a short-term follow-up measurement is recommended in order to get a fast result. If an initial short-term test result is between 4 pCi/L and 10 pCi/L, a long-term or a short-term follow-up measurement is recommended. For more information about the interpretation of your test results or about other radon related issues we suggest contacting your state radon office.

Your state radon office should have the available EPA publications:

- A Citizen's Guide to Radon
- Home Buyer's and Seller's Guide to Radon
- Consumer's Guide to Radon Reduction

Signature on the report

With the signature on the report, the Measurement specialist at Radonova Laboratories certifies that the quality control procedures follows the guidance in accordance with the AARST/ANSI Measurement Protocols. Measurement information displayed in italics on report has been provided by the customer.

Certification no:

101132-AL, 107830-RMP, NY ELAP ID: 11430

DISCLAIMER

Radonova Inc. makes no warranty of any kind, express or implied, as regard to the use, operation or analysis of any Radonova Inc. monitor. Radonova Inc. specifically disclaims implied warranties of merchantability and fitness for a particular purpose. Radonova Inc. is not responsible for any damage, including consequential damages, to persons or property resulting from the use of the monitor or the resulting data.