

WOOSTER CITY SCHOOLS

Cornerstone Elementary: Facility Assessment

Based on the recently updated OFCC Facilities Assessment for Cornerstone Elementary School, Fanning Howey prepared a report summarizing the minimum investment required if the school was to be kept for an extended period of time.

The total recommendation budget is \$36,212,824.17. With the region cost factor added the total comes to \$37,262,996.07. Priority building upgrades are tagged with arrows, amounting to \$25,974,669.65.

Facility Assessment Cost Set: 2024	Rating	Dollar Assessment
Heating System	3	\$7,723,421.53
Roofing	3	\$1,188,716.40
Ventilation/Air Conditioning	2	\$6,478.25
Electrical Systems	3	\$4,441,652.82
Plumbing and Fixtures	3	\$1,476,923.02
Windows	3	\$1,121,634.25
Structure: Foundation	1	\$0.00
Structure: Walls and Chimneys	2	\$489,171.32
Structure: Floors and Roofs	2	\$126,840.00
General Finishes	3	\$5,355,321.29
Interior Lighting	3	\$1,003,722.94
Security Systems	3	\$594,842.93
Emergency/Egress Lighting	3	\$154,969.10
Fire Alarm	3	\$463,715.23
Handicapped Access	2	\$503,259.89
Site Condition	3	\$569,709.81
Sewage System	1	\$0.00
Water Supply	1	\$0.00
Exterior Doors	3	\$103,651.84
Hazardous Material	3	\$148,106.42
Life Safety	3	\$948,605.17
Loose Furnishings	3	\$848,753.84
Technology	3	\$1,833,403.66
Construction Contingency/ Non-Construction Cost	3	\$7,109,925.46
Total Recommended Budg	Total Recommended Budget	
Total Recommended Budg + Region Cost Factor	Total Recommended Budget + Region Cost Factor	
Total Suggested Improvem	Total Suggested Improvements	
Total Suggested Improvements + Region Cost Factor		\$25,974,669.65

For more information and to view the full report, visit woostercityschools.org/district-info/facilities-master-plan