

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
MAIN OFFICE AND CLOSET	CARPET ON 9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	560 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
NURSES OFFICE	12" WHITE WITH BLUE SPEC & 12" YELLOW FLOOR TILE AND MASTIC		480 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
BOILER ROOM	BREECHING	1		ABATED 2004	ABATED 2004	ABATED 2004	ABATED 2004
	HOT WATER TANK	2		ABATED 2004	ABATED 2004	ABATED 2004	ABATED 2004
	FIRE DOOR	8	35 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	TROWLED ON CEILING	11	600 FT2	SEVERE- 12 FT2 WATER DAMAGED/ LOOSE DEBRIS ON FLOOR	SEVERE- 12 FT2 WATER DAMAGED/ LOOSE DEBRIS ON FLOOR	SAMPLE/REPAIR	SAMPLE/REPAIR
	INSIDE BOILER MORTAR	12		ABATED 2004	ABATED 2004	ABATED 2004	ABATED 2004
	INTERIOR BOILER BRICK	13		ABATED 2004	ABATED 2004	ABATED 2004	ABATED 2004
	EVTS	3		ABATED 2004	ABATED 2004	ABATED 2004	ABATED 2004
STORAGE ROOM ACROSS FROM BOILER ROOM	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	520 FT2	MODERATE- 1 DAMAGED	MODERATE- 1 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	EVTS	3	4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
CST CONFERENCE ROOM	NEW FLOOR TILE AND MASTIC	04A	240 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	EVTS	3	1	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
BATH	CEILING PLASTER	10	30 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
CST	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	480 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	EVTS	3		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
CST BATH	CEILING PLASTER	10	25 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
KITCHEN	9" GREEN FLOOR TILE AND MASTIC	04B	300 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	CEILING PLASTER	10	300 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	3	3	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
KITCHEN STORAGE @ EXIT	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	130 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	EVTS	3	7	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
KITCHEN STORAGE BY SINK	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	104 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
ALL PURPOSE ROOM	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	2,000 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
STAGE	VIBRATION COLLAR	9	6 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	FIRE DOOR	8	35 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	3	26	SEVERE- 2 DAMAGED CENTER STAGE BACK WALL/ 1 DAMAGED STAGE RT AT LIGHT SWITCHES	SEVERE- 3 DAMAGED CENTER STAGE BACK WALL/ 1 DAMAGED STAGE RT AT LIGHT SWITCHES	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
STAGE ENTERANCE	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	16 FT2	MODERATE- 2 DAMAGED	MODERATE- 2 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
ROOM 251 WORK ROOM	NEW FLOOR TILE AND MASTIC		268 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
ROOM 109	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	720 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	SILLS		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
JANITOR CLOSET	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	150 FT2	MODERATE- 19 DAMAGED	MODERATE- NUMEROUS DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	EVTS	3	2	MODERATE- 1 PUNCTURED IN DUCT TAPE	MODERATE- 1 PUNCTURED IN DUCT TAPE	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
BOYS BATH	CEILING PLASTER	10	200 FT2	MODERATE DAMAGE	MODERATE DAMAGE	SAMPLE/REPAIR	SAMPLE/REPAIR
ROOM 107	NEW FLOOR TILE AND MASTIC	04A	720 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	EVTS	3	6	SEVERE- 2 EVTS WRAP LOOSE	SEVERE- 2 EVTS WRAP LOOSE	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
	SILLS		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 105	NEW FLOOR TILE AND MASTIC	04A	720 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	EVTS	3	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	SILLS		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 108	NEW FLOOR TILE AND MASTIC	04A	660 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	SILLS		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	NEW FLOOR TILE AND MASTIC	04A	660 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
ROOM 106	SILLS		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	3	6	SEVERE- 3 IN DUCT TAPE	SEVERE- 3 IN DUCT TAPE	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
ROOM 103	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	720 FT2	MODERATE- 1MISSING WITH MASTIC EXPOSED	MODERATE- 1 DAMAGED/ 1 MISSING WITH MASTIC EXPOSED	REPLACE 1 TILE * MONITOR/ CONTINUE O+M	REPLACE 1 TILE * MONITOR/ CONTINUE O+M
	EVTS	3	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 100 AND CLOSET	NEW FLOOR TILE AND MASTIC		1,408 FT2	MODERATE- 7 DAMAGED	MODERATE- 7 DAMAGED	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	SILLS		0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 100 - 2 BATHS	CEILING PLASTER		50 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 104	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	660 FT2	ABATED 2019	ABATED 2019	ABATED 2019	ABATED 2019
	SILLS		22 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ART SUPPLY OPP 324	9" ORANGE SPEC FLOOR TILE AND MASTIC	04A	80 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
GO RIGHT AND MAKE 1ST RIGHT							

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
ROOM 117	12" ORANGE FLOOR TILE AND MASTIC	05B	672 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 118	12" ORANGE FLOOR TILE AND MASTIC	05B	672 FT2	MODERATE- 2 DAMAGE WITH MASTIC EXPOSED	MODERATE- 1 DAMAGE WITH MASTIC EXPOSED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 116	12" GREEN WITJWHITE SPEC FLOOR TILE AND MASTIC	05A	672 FT2	MODERATE- 2 DAMAGED	MODERATE- 2 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 119	12" BEIGE WITH BROWN SPEC FLOOR TILE AND MASTIC	05A	672 FT2	MODERATE- 9 DAMAGED	MODERATE- 7 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 120	12" BEIGE WITH BROWN SPEC FLOOR TILE AND MASTIC	05A	720 FT2	MODERATE- 5 DAMAGED	MODERATE- 10 DAMAGED	REPLACE 2 TILES * MONITOR/ CONTINUE O+M	REPLACE 2 TILES * MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
ROOM 115	12" LT. GREEN WITH BEIGE SPEC FLOOR TILE AND MASTIC	05A	720 FT2	MODERATE- 28 DAMAGED	MODERATE- 28 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 114	12" LT. GREEN WITH BEIGE SPEC FLOOR TILE AND MASTIC	05A	720 FT2	MODERATE- 18 DAMAGED	MODERATE- 17 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	SILLS		10 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
BOYS BATH	CEILING PLASTER	10	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
GIRLS BATH	CEILING PLASTER	10	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
JANITOR CLOSET	12" ORANGE WITH BIEGE SPEC FLOOR TILE AND MASTIC	05B	72 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
GIRLS BATH	CEILING PLASTER	10	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM 113	12" ORANGE WITH BIEGE SPEC FLOOR TILE AND MASTIC	05B	1,444 FT2	MODERATE- 2 DAMAGED	MODERATE- 2 DAMAGED	REPLACE 1 TILE * MONITOR/ CONTINUE O+M	REPLACE 1 TILE * MONITOR/ CONTINUE O+M
	12" LT. GREEN FLOOR TILE AND MASTIC	05A					

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
	VIBRATION COLLAR	9	6 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS-CLOSET	3	4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
TURN RIGHT							
ROOM D21	12" CREAM WITH BEIGE SPEC FLOOR TILE AND MASTIC	05A	480 FT2	MODERATE- 1 DAMAGED	MODERATE- 1 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
GIRLS BATH	CEILING PLASTER	10	120 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
HALLWAYS ABOVE DROP CEILINGS							
HALL FROM 107 TO 324	EVTS	3	38	SEVERE- 3 DAMAGED NEAR ROOM 103/ 2 DAMAGED OPP 105-107	SEVERE- 3 DAMAGED NEAR ROOM 103/ 2 DAMAGED OPP 105-107	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
ENTIRE BUILDING	ALL COVE BASE AND MASTIC			NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	BLACK BOARDS/ WALL BOARDS AND MASTIC			NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Authur t. Stanlick Elementary
 Address: 121 E Shawnee Trail
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space 1962	Material	Homo ID #	Amount	Previous Condition	CURRNET DAMAGE	Previous Response	Current Response
	EVTS ABOVE AND BEHIND FIXED WALLS AND CEILNG	3		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.