SUMMARY	TC	TAL (1-4 Only)		Priority 1		Priority 2		Priority 3		Priority 4		Underway
Academy Learning Center	\$	5,548,690	\$	2,663,885	\$	1,825,637	\$	832,018	\$	227,150	\$	675,609
Site	\$	90,860	\$	-	\$	90,860	\$	-	\$	-	\$	151,217
Exterior	\$	177,177	\$	54,516	\$	5,841	\$		\$		\$	
Interior	\$	2,426,351	\$	1,318,508	\$	274,527	\$		\$	179,124	\$	15,576
Educ. Program	\$	2,137,806	\$	623,040	\$	1,405,734	\$	61,006	\$	48,026	\$	-
Mechanical	\$	406,274	\$	406,274	\$	-	\$	-	\$	-	\$	-
Plumbing	\$	204,435	\$	204,435	\$	-	\$		\$		\$	508,816
Electrical	\$	105,787	\$	57,112	\$	48,675	\$	-	\$	-	\$	-
	4				<u>.</u>		L					
Bright Beginnings Learning Center	\$	1,554,874	\$	913,403	\$	475,977	\$	-,	\$	38,940	\$	4,775,861
Site	\$	33,488	\$	33,488	\$		\$		\$	-	\$	-
Exterior	\$	118,118	\$	36,344	\$	3,894	\$	77,880	\$	-	\$	448,329
Interior	\$	31,412	\$	-	\$	24,273	\$	7,139	\$		\$	150,568
Educ. Program	\$	712,472	\$	417,826	\$	214,170	\$	41,536	\$	38,940	\$	506,220
Mechanical	\$	-	\$		\$		\$		\$	-	\$	2,924,394
Plumbing	\$	306,977	\$	268,037	\$	38,940	\$		\$	-	\$	746,350
Electrical	\$	352,407	\$	157,707	\$	194,700	\$	-	\$	-	\$	-
Center for Lifelong Learning	\$	7,742,920	\$	3,756,762	\$	418,281	\$	851.813	\$	2.716.065	\$	13,785,604
Site	\$	171,661	\$	71,390	\$	2,921	\$	97,350	\$	2,: 20,000	\$	1,168,200
Exterior	\$	443.617	\$	374,823	\$	3,894	\$	64,900	\$	-	\$	10.912.026
Interior	\$	744,922	\$	314,023	\$	54,516	\$		\$	9,735	\$	362,791
Educ. Program	\$	3,667,499	\$	734,019	\$	227,150	\$		\$	2,706,330	\$	302,731
Mechanical	\$	1,814,604	\$	1,814,604	\$	221,150	\$		\$	2,700,330	\$	750,698
Plumbing	\$	744,403	\$	744,403	\$	-	\$		\$		\$	591,888
Electrical	\$	156,214	\$	17,523	\$	129,800	\$	8,891	\$		\$	591,000
Electrical	⊅	156,214	Þ	17,523	Þ	129,800	Þ	8,891	⊅		P	-
Future Foundations Academy	\$	8,634,105	\$	4,699,042	\$	579,557	\$	3,068,324	\$	287,183	\$	449,108
Site	\$	24,662	\$		\$	5,192	\$		\$	19,470	\$	-
Exterior	\$	1,613,385	\$	222,856	\$		\$		\$	-	\$	-
Interior	\$	759,460	\$	283,613	\$	12,980	\$		\$	-	\$	32,450
Educ. Program	\$	2,278,250	\$	1,029,249	\$	-	\$	1,214,928	\$	34,073	\$	-
Mechanical	\$	3,258,726	\$	2,697,341	\$	561,385	\$	•	\$	-	\$	-
Plumbing	\$	427,042	\$	193,402	\$	-	\$		\$	233,640	\$	412,764
Electrical	\$	272,580	\$	272,580	\$	-	\$	-	\$	-	\$	3,894
Nuview Academy	\$	2,679,448	\$	1,867,095	\$	290.103	\$	522.250	\$		\$	1,125,204
				1,007,095		290,103				-		, ,
Site	\$	36,344	\$	-	\$	-	\$	36,344	\$	-	\$	12,980
Exterior	\$	1,187,657	\$	1,060,323	\$	-	\$	127,334	\$	-	\$	-
Interior	\$	627,259	\$	103,840	\$	290,103	\$		\$	-	\$	
Educ. Program	\$	411,466	\$	388,102	\$	-	\$	23,364	\$	-	\$	834,452
Mechanical	\$	262,585	\$	165,235	\$	-	\$	97,350	\$	-	\$	-
Plumbing	\$	99,946	\$	99,946	\$	-	\$		\$	-	\$	277,772
Electrical	\$	54,192	\$	49,649	\$	•	\$	4,543	\$	•	\$	-
Piscataway Regional Day School	\$	4,581,116	\$	1,443,960	\$	1,296,929	\$	535,737	\$	1,304,490	\$	422.239
Site	\$	64.900	\$	-	\$	32,450	\$	12,980	\$	19.470	\$	48,675
Exterior	\$	1,544,620	\$	84,370	\$	-	\$	175,230	\$	1,285,020	\$	
Interior	\$	1,047,376	\$	360,195	\$	427,269	\$		\$	-,,	\$	60,746
Educ. Program	\$	1,680,586	\$	794,701	\$	837,210		48,675	\$		\$,
Mechanical	\$	38,940	\$	-	\$	-	\$	38,940	\$		\$	_
Plumbing	\$	127,204	\$	127,204	\$	-	\$		\$		\$	312,818
Electrical	\$	77,491	\$	77,491	\$	-	\$		\$		\$, 520
F-A T-A-15		00.744.454		45.044.445		4.000.400	_	F 000 000		4 570 000		
Est. Total Remaining Budget	\$	30,741,154	\$	15,344,147	\$	4,886,483	\$	5,936,696	\$	4,573,828	_	
Completed or underway	\$	21,233,625									\$	21,233,625

Prevailing wages, public bid


No identification, testing or treatment of hazardous materials is included.

Total Identified Scope \$ 51,974,779

Pricing based on 1st Quarter 2024

Soft costs include 10% and 18% other Soft costs.

*Tariffs have been announced but not quantified; these are expected to impact budgets but the degree of impact is not yet known



		1	ı	n		1			1	2	3	4	Underway
Academy Learning Center	Quantity	Unit	Unit Cost	Priority Code	Hard Cost	Contingency	Soft Costs	Total	Total	Total	Total	Total	Total
Site Work	•	•	•		\$186,500	\$18,650	\$36,927	\$242,077	\$0	\$90,860	\$0	\$0	\$151,217
Sidewalk Replacement	1.000	QE.	\$25	5	\$25,000	\$2,500	\$4 950	\$22,077	\$0 \$0	\$90,860	\$0 \$0	\$0 \$0	\$32,450
Asphalt Repaving (mill and overlay; repairs)	1,000	OF.	\$25 \$15	5	\$60.000	\$2,500	\$4,930 \$11,000	\$32,430 \$77,990	\$0	\$0	\$0	\$0	\$77,880
Install drainage at circulation road around classroom wings (inside edge)	4,000	1 =	φ13 ¢75	5	\$31,500	\$3,150	\$6.237	\$40,887	\$0	\$0	\$0	\$0	\$40,88
0 7	2	EA	\$35,000	2	\$70,000	\$7,000	\$13,860	\$90,860	\$0	\$90,860	\$0	\$0	
Playground: add age appropriate play structures in play areas	2	EA	\$35,000	2	\$70,000	\$1,000	\$13,000	\$90,000	\$0	\$90,000	ΦΟ		\$0
Building Envelope					\$136,500	\$13,650	\$27,027	\$177,177	\$54,516	\$5,841	\$116,820	\$0	\$1
Add gutters, downspouts, snowguards; replace some existing	25	EA	\$1,200	1	\$30,000	\$3,000	\$5,940	\$38,940	\$38,940	\$0	\$0	\$0	\$
Masonry joints: clean and repoint	1,500	SF	\$60	3	\$90,000	\$9,000	\$17,820	\$116,820	\$0	\$0	\$116,820	\$0	\$
Steel lintels: scrap and repaint	300	LF	\$15	2	\$4,500	\$450	\$891	\$5,841	\$0	\$5,841	\$0	\$0	
Adjust, replace weatherstripping @ Exterior Doors	12	EA	\$1,000	1	\$12,000	\$1,200	\$2,376	\$15,576	\$15,576	\$0	\$0	\$0	\$
Interiors					\$1,881,300	\$188,130	\$372,497	\$2,441,927	\$1,318,508	\$274,527	\$654,192	\$179,124	\$15,57
Masonry at Gymnasium (Cracks in Masonry Wall)	1	LS	\$100,000	4	\$1,001,300	\$10,000	\$19,800	\$129.800	\$1,510,500	\$0	\$054,192	\$129,800	\$13,31
Water intrusion damage at Tower entries: repair, mitigate	3	LS	\$250,000	1	\$750,000	\$75,000	\$148,500	\$973,500	\$973,500	\$0	\$0	\$0	
Interior Finishes, Ceiling, Painting, Etc	1	LS	\$150,000	3	\$150,000	\$15,000	\$29,700	\$194,700	\$0	\$0	\$194,700	\$0	9
Entry walk-off mats: replace	3	EA	\$4,000	5	\$12,000	\$1,200	\$2,376	\$15,576	\$0	\$0	\$0	\$0	\$15,57
Entrance control upgrade at Tower Doors (Interior and vestibule)	2	EA	\$25,000	1	\$50,000	\$5,000	\$9,900	\$64,900	\$64,900	\$0	\$0	\$0	\$10,07
Secure vestibule upgrade at main entry (250+/- SF)	1	LS	\$85,000	1	\$85,000	\$8,500	\$16.830	\$110,330	\$110,330	\$0	\$0	\$0	9
Security window film at entries and 1st floor windows	8,400	SF	\$12	1	\$100,800	\$10,080	\$19,958	\$130,838	\$130,838	\$0	\$0	\$0	9
Expand and upgrade camera system allowance (entries, corridors, campus)	1	LS	\$30,000	1	\$30,000	\$3,000	\$5,940	\$38,940	\$38,940	\$0	\$0	\$0	9
Replace corridor flooring	9.000	SF	\$15	2	\$135,000	\$13,500	\$26,730	\$175,230	\$0	\$175,230	\$0	\$0	3
Replace kitchen flooring	300	SF	\$30	2	\$9,000	\$900	\$1,782	\$11,682	\$0	\$11,682	\$0	\$0	
Observation/sensory rooms: replace flooring and padding; blank off electrical	9	EA	\$7,500	2	\$67,500	\$6,750	\$13,365	\$87,615	\$0	\$87,615	\$0	\$0	9
Update PA and WiFi systems in school	59,000	SF	\$6		\$354,000	\$35,400	\$70,092	\$459,492	\$0	\$0	\$459,492	\$0	9
Replace Interior doors and upgrade hardware/access control	10	EA	\$3,800	4	\$38,000	\$3,800	\$7,524	\$49,324	\$0	\$0	\$0	\$49,324	3
		•	•				•						
Program Needs			001.000		\$1,647,000		\$326,106	\$2,137,806	\$623,040	\$1,405,734	\$61,006	\$48,026	\$
Classroom casework/counters: replace with counter and storage cabinets	20	EA	\$24,000	1	\$480,000		\$95,040	\$623,040	\$623,040	\$0	\$0	\$0	
Corridors: install storage in old phone alcoves	2	EA	\$3,500	4	\$7,000	\$700	\$1,386	\$9,086	\$0	\$0	\$0	\$9,086	9
Daily living room/vocational rm (118): upgrade and renovate incl. bathroom	2,100	SF	\$435	2	\$913,500	\$91,350	\$180,873	\$1,185,723	\$0	\$1,185,723	\$0	\$0	
OT/PT space: upgrade and provide storage casework	1	LS	\$9,500	2	\$9,500	\$950	\$1,881	\$12,331	\$0	\$12,331	\$0	\$0	9
Center court: upgrade acoustic panels (ceiling and walls)		LS	\$15,000	3	\$15,000	\$1,500	\$2,970	\$19,470	\$0	\$0	\$19,470	\$0	9
Center court: create storage room for tables/chairs/other	150		\$200	4	\$30,000	* - ,	\$5,940	\$38,940	\$0	\$0	\$0	\$38,940	
Storage casework: add storage casework in multiple spaces	8	EA	\$4,000	3	\$32,000	\$3,200	\$6,336	\$41,536	\$0	\$0	\$41,536	\$0	
Resource center: renovate with new casework/counters	300	LS SF	\$25,000	2	\$25,000 \$135,000	\$2,500 \$13,500	\$4,950 \$26,730	\$32,450 \$175,230	\$0 \$0	\$32,450 \$175,230	\$0 \$0	\$0 \$0	\$
Nurse: renovate; new casework, counters, finishes	300	SF	\$450	2	\$135,000	\$13,500	\$26,730	\$175,230	20	\$175,230	\$0	\$0	-
Mechanical					\$313,000	\$31,300	\$61,974	\$406,274	\$406,274	\$0	\$0	\$0	\$
Daily living/Vocational room: upgrade exhaust venting for kitchen	1	LS	\$18,000	1	\$18,000	\$1,800	\$3,564	\$23,364	\$23,364	\$0	\$0	\$0	(
BMŚ Controls	59,000	SF	\$5	1	\$295,000	\$29,500	\$58,410	\$382,910	\$382,910	\$0	\$0	\$0	\$
Plumbing					\$549,500	\$54,950	\$108,801	\$713,251	\$204,435	\$0	\$0	\$0	\$508,8
Replace urinals w/ hands-free flushometers	1	EA	\$5,000	5	\$5,000	\$500	\$990	\$6,490	\$0	\$0	\$0	\$0	\$6,4
Replace lavatories w/ hands-free faucets	43	EA	\$5,000	5	\$215,000	\$21,500	\$42,570	\$279,070	\$0	\$0	\$0	\$0	\$279,07
Replace water closet w/ hands-free flushometers	26	EA	\$6,000	5	\$156,000	\$15,600	\$30,888	\$202,488	\$0	\$0	\$0	\$0	\$202,48
Replace water cooler with bottle fill type	2	EA	\$8,000	5	\$16,000	\$1,600	\$3,168	\$20,768	\$0	\$0	\$0	\$0	\$20,76
Install thermostatic mixing-valves in sinks and lavatories	45	EA	\$3,500	1	\$157,500	\$15,750	\$31,185	\$204,435	\$204,435	\$0	\$0	\$0	- 5
Electrical					\$81,500	\$8.150	\$16,137	\$105,787	\$57,112	\$48.675	\$0	\$0	
111 11	50	EA	\$750	2	\$37,500		\$7,425	\$48,675	\$0	\$48,675	\$0	\$0	
Install occupancy sensors in classrooms, offices and bathrooms	26	EA	\$750 \$1,500	1	\$37,500	\$3,750 \$3,900	\$7,425 \$7,722	\$48,675	\$50,622	,	\$0 \$0	\$0 \$0	9
Add emergency lighting within the classrooms and bathrooms Electrical requried for mechanical work	26 1	EA	\$1,500 \$5,000	1	\$39,000	\$3,900 \$500	\$7,722 \$990	\$50,622 \$6,490	\$50,622 \$6,490	\$0 \$0	\$0 \$0	\$0 \$0	3
Lieuthear required for medianical work		LA	φυ,000		φυ,000	φ300	φ390	φυ,490	φυ,490	20	20	φυ	
Hard and Soft Cost - Total Budge									\$2,663,885	\$1,825,637	\$832,018	\$227,150	\$675,60
Assumptions													

Assumptions
Prevailing wages, public bid
No identification, testing or treatment of hazardous materials is included.

Pricing based on 1st Quarter 2024

Suitable soil conditions with no rock assumed

Soft costs include 10% and 18% other Soft costs.

*Tariffs have been announced but not quantified; these are expected to impact budgets but the degree of impact is not yet known

		1		Daile aite					1	2	3	4	Underway
Bright Beginnings Learning Center	Quantity	Unit	Unit Cost	Priority Code	Hard Cost	Contingency	Soft Costs	Total	Total	Total	Total	Total	Total
Bright Boginining Contor		<u> </u>	<u> </u>	Oouc		<u> </u>			Total	Total	Total	Iotai	Total
Site Work					\$25.800	\$2,580	\$5,108	\$33,488	\$33,488	\$0	\$0	\$0	\$0
Loading dock masonry and concrete repair	172	SF	\$150	1	\$25,800	\$2,580	\$5,108	\$33,488	\$33,488	\$0	\$0	\$0	\$0
								<u> </u>					<u> </u>
Building Envelope					\$436,400	\$43,640	\$86,407	\$566,447	\$36,344	\$3,894	\$77,880	\$0	\$448,329
Repairs to gutters/downspounts	1	LS	\$18,000	1	\$18,000	\$1,800	\$3,564	\$23,364	\$23,364	\$0	\$0	\$0	\$0
Soffit re-finishing at exterior doors	2	EA	\$1,500	2	\$3,000	\$300	\$594	\$3,894	\$0	\$3,894	\$0	\$0	\$0
Exterior masonry repointing and cleaning	1,000	SF	\$60	3	\$60,000	\$6,000	\$11,880	\$77,880	\$0	\$0	\$77,880	\$0	\$0
Replace Weatherstripping at Exterior Doors	10	EA	\$1,000	1	\$10,000	\$1,000	\$1,980	\$12,980	\$12,980	\$0	\$0	\$0	\$0
Roofing: leaks on the North side of the roof remain - continue repair efforts	1	LS	\$25,000	5	\$25,000	\$2,500	\$4,950	\$32,450	\$0	\$0	\$0	\$0	\$32,450
Security window film at entries and 1st floor windows	7,700	SF	\$12	5	\$92,400	\$9,240	\$18,295	\$119,935	\$0	\$0	\$0	\$0	\$119,935
Board office windows: add tinting to glass; reglaze high units w/panels	2,400	SF	\$95	5	\$228,000	\$22,800	\$45,144	\$295,944	\$0	\$0	\$0	\$0	\$295,944
										404.000	AT 100	•	A 170 - 170
Interiors					\$140,200			\$181,980	\$0	\$24,273	\$7,139	\$0	\$150,568
General finish repairs (walls, ceilings, etc)	748	LS SF	\$5,500	3	\$5,500	\$550	\$1,089	\$7,139 \$24,273	\$0 \$0	\$0 \$24,273	\$7,139	\$0	\$0 \$0
Entry lobby flooring - replace	748	SF	\$25	2	\$18,700	\$1,870	\$3,703				\$0	\$0	
Observation/sensory rooms: replace flooring and padding; blank off electrical Replace flooring: Classroom toilets and corridor individual toilets	20	EA LC	\$7,500	5	\$60,000 \$56,000	\$6,000 \$5,600	\$11,880 \$11.088	\$77,880 \$72.688	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0	\$77,880 \$72,688
Replace flooring. Classroom tollets and comdor individual tollets	20	LS	\$2,000	5	\$50,000	\$5,600	Φ11,000	\$72,000	\$0	Φ0	Φ0	20	\$72,000
Program Needs					\$938.900	\$93.890	\$185,902	\$1,218,692	\$417,826	\$214,170	\$41,536	\$38.940	\$506.220
Sensory room/Art room (F13): renovate, create division, add casework	1 200	SF	\$325	5	\$390,000	\$39.000	\$77.220	\$506.220	\$0	\$0	\$0	\$0	\$506,220
Daily living room (F12): renovation and upgrades incl. bathroom	740	SF	\$435	1	\$321,900	\$32,190	\$63,736	\$417.826	\$417,826	\$0	\$0	\$0	\$0
Multi-purpose/Gym: install acoustic panels on walls, ceiling	2,750	SF	\$60	2	\$165,000	\$16,500	\$32,670	\$214,170	\$0	\$214,170	\$0	\$0	\$0
Replace lunch tables in MP Room	10	EA	\$3,200	3	\$32,000	\$3,200	\$6,336	\$41,536	\$0	\$0	\$41,536	\$0	\$0
Create storage area for MP Room chairs	150	SF	\$200	4	\$30,000	\$3,000	\$5,940	\$38,940	\$0	\$0	\$0	\$38,940	\$0
Mechanical					\$2,253,000	\$225,300	\$446,094	\$2,924,394	\$0	\$0	\$0	\$0	\$2,924,394
Remove and replace HW/CHW AHUs with New	5	EA	\$85,000	5	\$425,000	\$42,500	\$84,150	\$551,650	\$0	\$0	\$0	\$0	\$551,650
Remove and replace HW VAV Boxes with New	25	EA	\$20,000	5	\$500,000	\$50,000	\$99,000	\$649,000	\$0	\$0	\$0	\$0	\$649,000
Remove and replace HW/CHW Blower Coil Units with New	20	EA	\$25,000	5	\$500,000	\$50,000	\$99,000	\$649,000	\$0	\$0	\$0	\$0	\$649,000
Remove and replace HW cabinet unit heaters with New	5	EA	\$10,000	5	\$50,000	\$5,000	\$9,900	\$64,900	\$0	\$0	\$0	\$0	\$64,900
Remove and replace Inline Exhaust fans with New	12	EA	\$10,000	5	\$120,000	\$12,000	\$23,760	\$155,760	\$0	\$0	\$0	\$0	\$155,760
Add exhaust hood and exhaust system in Daily Living Space	1	EA	\$18,000	5	\$18,000	\$1,800	\$3,564	\$23,364	\$0	\$0	\$0	\$0	\$23,364
Remove and replace Chiller Pumps & Glycol Feed Unit with New	1	EA	\$275,000	5	\$275,000	\$27,500	\$54,450	\$356,950	\$0	\$0	\$0	\$0	\$356,950
Remove and replace HW inline pumps	4	EA	\$15,000	5	\$60,000	\$6,000	\$11,880	\$77,880	\$0	\$0	\$0	\$0	\$77,880
BMS Controls	61,000	SF	\$5	5	\$305,000	\$30,500	\$60,390	\$395,890	\$0	\$0	\$0	\$0	\$395,890
Plumbing					\$811,500			\$1,053,327	\$268,037	\$38,940	\$0	\$0	\$746,350
Replace urinals w/ hands-free flushometers	4	EA	\$5,000	5	\$20,000	\$2,000	\$3,960	\$25,960	\$0	\$0	\$0	\$0	\$25,960
Replace lavatories w/ hands-free faucets	56	EA	\$5,000	5	\$280,000	\$28,000	\$55,440	\$363,440	\$0	\$0	\$0	\$0	\$363,440
Replace water cooler with bottle fill type	3	EA	\$8,000	5	\$24,000	\$2,400	\$4,752	\$31,152	\$0	\$0	\$0	\$0	\$31,152
Replace water closet w/ hands-free flushometers	36	EA	\$6,000	5	\$216,000	\$21,600	\$42,768	\$280,368	\$0	\$0	\$0	\$0	\$280,368
Replace gas-fired water heater	1	LS	\$30,000	2	\$30,000	\$3,000	\$5,940	\$38,940	\$0	\$38,940	\$0	\$0	\$0
Install thermostatic mixing-valves in sinks and lavatories	59	EA	\$3,500	1	\$206,500 \$35,000	\$20,650	\$40,887	\$268,037	\$268,037 \$0	\$0	\$0	\$0	\$0
install new sink in Art room F13 (connect to exg under floor lines)	7	EA	\$35,000	5	\$35,000	\$3,500	\$6,930	\$45,430	\$0	\$0	\$0	\$0	\$45,430
Electrical			_		\$271,500	\$27,150	\$53,757	\$352,407	\$157,707	\$194,700	\$0	\$0	\$0
Add additional emergency lighting fixtures within the corridors	10	EA	\$750	1	\$7,500	\$750	\$1,485	\$9,735	\$9,735	\$0	\$0	\$0	\$0
Add emergency lighting within the classrooms and bathrooms	32	EA	\$1,500	1	\$48,000	\$4,800	\$9,504	\$62,304	\$62,304	\$0	\$0	\$0	\$0
Install occupancy sensors in classrooms, storage rooms and bathrooms	78	EA	\$750	1	\$58,500	\$5,850	\$11,583	\$75,933	\$75,933	\$0	\$0	\$0	\$0
Replace fire alarm strobes within the classroom bathrooms	3	EA	\$2,500	1	\$7,500	\$750	\$1,485	\$9,735	\$9,735	\$0	\$0	\$0	\$0
Electrical requried for mechanical work	1	EA	\$150,000	2	\$150,000	\$15,000	\$29,700	\$194,700	\$0	\$194,700	\$0	\$0	\$0
Hard and Soft Cost - Total Budget									\$913,403	\$475,977	\$126,555	\$38,940	\$4,775,861
Hard and Soft Cost - Total Budget									ψ313, 4 03	ψ+10,011	ψ120,333	\$30,340	ψ+,113,001

Ocatan fan Lifelann Lannin a	Quantity	Unit	Unit Cost	Priority	Hard Cost	Contingency	Soft Costs	Total	1	2	3	4
Center for Lifelong Learning	Luummy	0	51.1K 556K	Code		commigancy	00.1 000.0	. o.u.	Total	Total	Total	Total
Site Work					\$1,032,250	\$103,225	\$204,386	\$1,339,861	\$71,390	\$2,921	\$97,350	\$0
Repair exterior walking surfaces (conc; curbs; stairs)	1	LS	\$75,000	3	\$75,000	\$7,500	\$14,850	\$97,350	\$0	\$0	\$97,350	\$0
Asphalt Repaving (mill and overlay; repairs)	150	SF	\$15	2	\$2,250	\$225	\$446	\$2,921	\$0	\$2,921	\$0	\$0
Repair rusted handrail and canopy structure bases	1	LS	\$20,000	1	\$20,000	\$2,000	\$3,960	\$25,960	\$25,960	\$0	\$0	\$0
Parking Upgrades, added parking, drives	30,000	SF	\$30	5	\$900,000	\$90,000	\$178,200	\$1,168,200	\$0	\$0	\$0	\$0
Play areas (exterior): add age appropriate play areas	1	LS	\$35,000	1	\$35,000	\$3,500	\$6,930	\$45,430	\$45,430	\$0	\$0	\$0
Building Envelope					\$8,748,570	\$874,857	\$1,732,217	\$11,355,644	\$374,823	\$3,894	\$64,900	\$0
Roof replacement (low slope; slope/ribbed; joints related to roof)(WTI budgets)	135,800	SF	\$51	5	\$6,925,800	\$692,580	\$1,371,308	\$8,989,688	\$0	\$0	\$0	\$0
Roof: Replace pool skylight (WTI budgets)	1	LS	\$335,000	5	\$335,000	\$33,500	\$66,330	\$434,830	\$0	\$0	\$0	\$0
Vertical joints in EIFS and masonry (WTI budgets)	1	LS	\$396,000	5	\$396,000	\$39,600	\$78,408	\$514,008	\$0	\$0	\$0	\$0
EIFS repair around the exterior and above roof (WTI budgets)	1	LS	\$750,000	5	\$750,000	\$75,000	\$148,500	\$973,500	\$0	\$0	\$0	\$0
Exterior gutter and downspout repairs and replacements		incl abov	е	5	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior steel lintels above windows and doors - strip and refinish	200	LF	\$15	2	\$3,000	\$300	\$594	\$3,894	\$0	\$3,894	\$0	\$0
Exterior doors to court areas: drain, new thresholds and water intrusion repairs	8	EA	\$20,000	1	\$160,000	\$16,000	\$31,680	\$207,680	\$207,680	\$0	\$0	\$0
Secure vestibule upgrade at main entry	250	SF	\$325	1	\$81,250	\$8,125	\$16,088	\$105,463	\$105,463	\$0	\$0	\$0
Security window film at entries and 1st floor windows	2,960	SF	\$12	1	\$35,520	\$3,552	\$7,033	\$46,105	\$46,105	\$0	\$0	\$0
Masonry crack repair	1	LS	\$50,000	3	\$50,000	\$5,000	\$9,900	\$64,900	\$0	\$0	\$64,900	\$0
Replace Weatherstripping & Door Sweeps @ Double Exterior Doors	12	EA	\$1,000	1	\$12,000	\$1,200	\$2,376	\$15,576	\$15,576	\$0	\$0	\$0
nteriors					\$853,400	\$85,340	\$168,973	\$1,107,713	\$0	\$54,516	\$680,671	\$9,735
Reglaze/reseal window wall along pool at school building connection	840	SF	\$50	2	\$42,000	\$4,200	\$8,316	\$54,516	\$0	\$54,516	\$000,071	\$0,755
Cafeteria/Gvm door access controls	1	10	\$4.500	5	\$42,000	\$4,200	\$0,310 \$201	\$54,516 \$5.841	\$0	\$34,316	\$0 \$0	\$0
Interior Finishes, Ceiling, Painting, Etc	1	LS	\$150,000	3	\$150,000	\$15,000	\$29,700	\$194.700	\$0	\$0	\$194,700	\$0
Flooring: kitchen, corridor, and pod common area flooring replacements	21,360	SF	\$150,000	3	\$320,400	\$32,040	\$63,439	\$415,879	\$0	\$0	\$415,879	\$0
Pool duct sock cleaning	1	1.9	\$25,000	5	\$25,000	\$2,500	\$4.950	\$32,450	\$0	\$0	\$0	\$0
Pool duct sock clearing Pool finishes, doors, other improvements	1	1.5	\$25,000	5	\$25,000	\$25,000	\$49.500	\$32,400	\$0	\$0	\$0	\$0
Pool mechanical room: replace railings, doors	1	LS	\$54.000	3	\$54,000	\$5,400	\$10,692	\$70,092	\$0	\$0	\$70,092	\$0
Vinyl base repairs and repalcement (allowance)	1	LS	\$7,500	4	\$7,500	\$750	\$1,485	\$9,735	\$0	\$0	\$0	\$9,735
	=											
Program Needs	1.600	SF	\$25	4	\$2,825,500 \$40,000	\$282,550 \$4,000	\$559,449 \$7,920	\$3,667,499 \$51,920	\$734,019 \$0	\$227,150 \$0	\$0 \$ 0	\$2,706,330 \$51,920
Pod sensory areas: new finishes, padding, new beanbags/etc	1,300	SF	\$435	1	\$565,500	\$4,000 \$56,550	\$111,969	\$734,019	\$734,019	\$0	\$0 \$0	\$51,920
Activities of Daily Living (E122) renovations incl. casework, finishes, configuration, exhaust, toilet Kitchen: renovate to add serving line, reconfigure wall and equipment related to change	1,300	LS	\$175,000	2	\$175,000	\$17,500	\$34,650	\$227,150	\$734,019	\$227,150	\$0 \$0	\$0
Pool entry/party area renovation (finishes, casework, desk and office area)	2.300	SF	\$175,000	4	\$575,000	\$17,500	\$34,650 \$113.850	\$746.350	\$0	\$227,150	\$0 \$0	\$746.350
Pool locker room renovations (finishes, lockers, ADA)	2,800	SF	\$525	4	\$1,470,000	\$147,000	\$291,060	\$1,908,060	\$0	\$0	\$0 \$0	\$1,908,060
Mechanical		,			\$1,976,350	\$197,635	\$391,317	\$2,565,302	\$1,814,604	\$0	\$0	\$0
Remove and replace Gas-Fired Boiler; HW inline primary and secondary Pumps with New	3	EA	\$460,000	11	\$1,380,000	\$138,000	\$273,240	\$1,791,240	\$1,791,240	\$0	\$0	\$0
ADL room exhaust hood and exhaust system BMS Controls	115.670	EA	\$18,000	1 5	\$18,000 \$578.350	\$1,800 \$57.835	\$3,564 \$114.513	\$23,364 \$750.698	\$23,364 \$0	\$0 \$0	\$0 \$0	\$0 \$0
DINO CONTOG	110,010	LA	ΨΟ	0	φονο,σσο	ψ07,000	ψ11 4, 010	φ/00,030	ΨΟ	ψυ	ΨΟ	ΨΟ
Plumbing					\$1,029,500		\$203,841	\$1,336,291	\$744,403	\$0	\$0	\$0
	90	EA	\$3,500	1	\$315,000	\$31,500	\$62,370	\$408,870	\$408,870	\$0	\$0	\$0
			φο,σσσ					\$12.980	\$0	\$0	\$0	\$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov)	2	EA	\$5,000	5	\$10,000	\$1,000	\$1,980	Ψ12,000		ΨΟ	ΨΟ	
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free faucets (locker rooms included under renov)	2 50	EA EA	\$5,000 \$5,000	5 5	\$10,000 \$250,000	\$25,000	\$1,980 \$49,500	\$324,500	\$0	\$0	\$0	\$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace unnals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free faucets (locker rooms included under renov) Replace water closet w/ hands-free flushometers (locker rooms included under renov)	2 50 26	EA EA EA	\$5,000 \$5,000 \$6,000	5 5 5	\$250,000 \$156,000	\$25,000 \$15,600			\$0 \$0	\$0 \$0	\$0 \$0	\$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free faucets (locker rooms included under renov)	2 50 26 5	EA EA EA	\$5,000 \$5,000 \$6,000 \$8,000	5 5 5	\$250,000 \$156,000 \$40,000	\$25,000 \$15,600 \$4,000	\$49,500 \$30,888 \$7,920	\$324,500 \$202,488 \$51,920	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free flaucets (locker rooms included under renov) Replace water closet w/ hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room	2 50 26 5	EA EA EA LS	\$5,000 \$5,000 \$6,000 \$8,000 \$8,500	5 5 5 5	\$250,000 \$156,000 \$40,000 \$8,500	\$25,000 \$15,600 \$4,000 \$850	\$49,500 \$30,888 \$7,920 \$1,683	\$324,500 \$202,488 \$51,920 \$11,033	\$0 \$0 \$0 \$11,033	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free faucets (locker rooms included under renov) Replace water closet w/ hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room	2 50 26 5 1	EA EA EA LS LS	\$5,000 \$5,000 \$6,000 \$8,000	5 5 5 5 1	\$250,000 \$156,000 \$40,000	\$25,000 \$15,600 \$4,000	\$49,500 \$30,888 \$7,920	\$324,500 \$202,488 \$51,920	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals wi hands-free flushometers (locker rooms included under renov) Replace lavatories wi hands-free flushometers (locker rooms included under renov) Replace water closet wi hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair)	2 50 26 5 1		\$5,000 \$5,000 \$6,000 \$8,000 \$8,500	5 5 5 5 1	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000	\$25,000 \$15,600 \$4,000 \$850 \$25,000	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500	\$0 \$0 \$0 \$11,033 \$324,500	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals with ands-free flushometers (locker rooms included under renov) Replace lavatories with ands-free flushometers (locker rooms included under renov) Replace water closet with hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair)	2 50 26 5 1	LS	\$5,000 \$5,000 \$6,000 \$8,000 \$8,500 \$250,000	5 5 5 5 1 1	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000	\$25,000 \$15,600 \$4,000 \$850 \$25,000	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214	\$0 \$0 \$0 \$11,033 \$324,500	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w' hands-free flushometers (locker rooms included under renov) Replace lavatories w' hands-free flushometers (locker rooms included under renov) Replace water closet w' hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Sectrical Install blank off covers in the open breaker positions in panel HP-4.	2 50 26 5 1 1	LS	\$5,000 \$5,000 \$6,000 \$8,000 \$8,500 \$250,000	5 5 5 1 1	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584	\$0 \$0 \$0 \$11,033 \$324,500 \$17,523 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w/ hands-free flushometers (locker rooms included under renov) Replace lavatories w/ hands-free flushometers (locker rooms included under renov) Replace water closet w/ hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office.	2 50 26 5 1	EA EA	\$5,000 \$5,000 \$6,000 \$8,000 \$8,500 \$250,000	5 5 5 1 1 3 3	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$400	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89 \$79	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519	\$0 \$0 \$0 \$11,033 \$324,500 \$17,523 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$5 \$1 \$5 \$4 \$54	\$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals with ands-free flushometers (locker rooms included under renov) Replace lavatories with ands-free flushometers (locker rooms included under renov) Replace lavatories with hands-free flushometers (locker rooms included under renov) Replace water closet with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office. Replace the broken emergency lighting fixture in the gym	2 50 26 5 1 1	EA EA EA	\$5,000 \$5,000 \$6,000 \$8,500 \$250,000 \$450 \$450 \$400 \$1,500	3	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$440 \$1,500	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40 \$150	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89 \$79 \$297	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947	\$0 \$0 \$0 \$11,033 \$324,500 \$17,528 \$0 \$0 \$1,947	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$584 \$519 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals whands-free flushometers (locker rooms included under renov) Replace avanories whands-free flushometers (locker rooms included under renov) Replace water closet whands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office. Replace the broken emergency lighting fixture in the gym Investigate why the site lighting fixtures in the north west corner parking lot are not working (allowance)	2 50 26 5 1 1 1 1 1 3	EA EA EA	\$5,000 \$6,000 \$8,000 \$8,500 \$250,000 \$450 \$450 \$1,500	3 1 1	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$450 \$1,500 \$7,500	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40 \$150 \$750	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89 \$79 \$297 \$1,485	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947 \$9,735	\$0 \$0 \$1,033 \$324,500 \$17,523 \$0 \$0 \$1,947 \$9,735	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$129,800 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$8,891 \$584 \$519 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals with ands-free flushometers (locker rooms included under renov) Replace lavatories with ands-free flushometers (locker rooms included under renov) Replace water closet with hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office. Replace the broken emergency lighting fixture in the gym Investigate why the site lighting fixtures in the north west corner parking lot are not working (allowance) Install an additional receptacle in storage rooms C-20 and C-30	2 50 26 5 1 1	EA EA EA EA EA	\$5,000 \$5,000 \$8,000 \$8,500 \$8,500 \$250,000 \$450 \$450 \$450 \$1,500 \$2,500 \$1,200	3 1 1 3	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$450 \$1,500 \$7,500 \$4,800	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40 \$150 \$750 \$480	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89 \$79 \$297 \$1,485 \$950	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947 \$9,735 \$6,230	\$0 \$0 \$11,033 \$324,500 \$17,523 \$0 \$0 \$1,947 \$9,735	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$3,891 \$584 \$519 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals with ands-free flushometers (locker rooms included under renov) Replace lavatories with ands-free flushometers (locker rooms included under renov) Replace water closet with hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office. Replace the broken emergency lighting fixtures in the north west corner parking lot are not working (allowance) install an additional receptacle in storage rooms C-20 and C-30. Replace the rusted MC wiring and associated junction box in the pool equipment room	2 50 26 5 1 1 1 1 1 1 3 4	EA EA EA EA EA	\$5,000 \$5,000 \$6,000 \$8,500 \$250,000 \$450 \$450 \$450 \$1,500 \$2,550 \$1,200	3 1 1	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$450 \$1,500 \$7,500 \$4,800 \$1,200	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40 \$150 \$750 \$480 \$120	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$79 \$297 \$1,485 \$950 \$238	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947 \$9,735 \$6,230 \$1,558	\$0 \$0 \$0 \$11,033 \$324,500 \$17,523 \$0 \$0 \$1,947 \$9,735 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$5 \$584 \$519 \$0 \$0 \$0 \$1,558	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals w' hands-free flushometers (locker rooms included under renov) Replace lavatories w' hands-free flushometers (locker rooms included under renov) Replace water closet w' hands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace dishwasher equipment in ADL room Cross connection between hot/cold distribution system (diagnose and allowance for repair) Electrical Install blank off covers in the open breaker positions in panel HP-4. Install a blank off cover in the wire tough within the life guard office. Replace the broken emergency lighting fixture in the gym Investigate why the site lighting fixtures in the north west comer parking lot are not working (allowance) Install an additional receptacle in storage rooms C-20 and C-30	2 50 26 5 1 1 1 1 1 3 4	EA EA EA EA EA	\$5,000 \$5,000 \$8,000 \$8,500 \$8,500 \$250,000 \$450 \$450 \$450 \$1,500 \$2,500 \$1,200	3 1 1 3	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$450 \$1,500 \$7,500 \$4,800	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$45 \$40 \$150 \$750 \$480	\$49,500 \$30,888 \$7,920 \$1,683 \$49,500 \$23,829 \$89 \$79 \$297 \$1,485 \$950	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947 \$9,735 \$6,230	\$0 \$0 \$11,033 \$324,500 \$17,523 \$0 \$0 \$1,947 \$9,735	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$3,891 \$584 \$519 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Install thermostatic mixing-valves in sinks and lavatories (locker rooms included under renov) Replace urinals wi hands-free flushometers (locker rooms included under renov) Replace urinals wi hands-free flushometers (locker rooms included under renov) Replace water closet with ands-free flushometers (locker rooms included under renov) Replace water cooler with bottle fill type Replace water cooler with bottle fill type Replace uses and allowance for repair) Pross connection between hot/cold distribution system (diagnose and allowance for repair) Replace the type of the diagnose and allowance for repair) Replace the type of the diagnose and allowance for repair) Replace the type of the diagnose and allowance for repair) Replace the type of the diagnose and allowance for repair) Replace the broken emergency lighting fixture in the ilfe guard office. Replace the broken emergency lighting fixture in the gym Investigate why the site lighting fixtures in the north west corner parking lot are not working (allowance) Replace the rusted MC wiring and associated junction box in the pool equipment room Replace the existing painted over devices located within the media center	2 50 26 5 1 1 1 1 1 1 3 4	EA EA EA EA EA EA	\$5,000 \$6,000 \$8,500 \$8,500 \$250,000 \$450 \$450 \$1,500 \$1,200 \$1,200 \$1,200	3 1 1 3 3	\$250,000 \$156,000 \$40,000 \$8,500 \$250,000 \$120,350 \$450 \$4,500 \$7,500 \$4,800 \$1,200 \$4,500	\$25,000 \$15,600 \$4,000 \$850 \$25,000 \$12,035 \$450 \$150 \$750 \$480 \$150 \$480 \$480 \$480 \$480 \$480 \$480 \$480 \$48	\$49,500 \$30,886 \$7,920 \$1,683 \$49,500 \$23,829 \$79 \$297 \$1,485 \$350 \$238 \$350 \$238 \$350 \$350 \$238 \$350 \$350 \$350 \$350 \$350 \$350 \$350 \$350	\$324,500 \$202,488 \$51,920 \$11,033 \$324,500 \$156,214 \$584 \$519 \$1,947 \$9,735 \$6,230 \$1,558 \$5,841	\$0 \$0 \$11,033 \$324,500 \$17,528 \$0 \$0 \$1,947 \$9,735 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$129,800 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$5,891 \$584 \$519 \$0 \$6,230 \$1,558	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0

	0	11	11-7-0	Priority		0	0.4.0	T. 1.1.1	1	2	3	4	Underwa
Future Foundations Academy	Quantity	Unit	Unit Cost	Code	Hard Cost	Contingency	Soft Costs	Total	Total	Total	Total	Total	Total
Site Work					\$19,000	\$1,900	\$3,762	\$24,662	\$0	\$5,192	\$0	\$19,470	
Drainage areas: clean out downspouts and investigate any further flooding	1	LS	\$15,000	4	\$15,000	\$1,500	\$2,970	\$19,470	\$0	\$0	\$0	\$19,470	
Replace Damaged ADA sidewalk ramps (damaged; lip exceeding 1/2")	1	LS	\$4,000	2	\$4,000	\$400	\$792	\$5,192	\$0	\$5,192	\$0	\$0	
Building Envelope					\$1,242,978	\$124,298	\$246,110	\$1,613,385	\$222,856	\$0	\$1,390,529	\$0	
	50	EA	\$1,000	1	\$50,000	\$5,000	\$9,900	\$64,900	\$64,900	\$0	\$0	\$0	
Replace Weatherstripping & Door Sweeps @ Double Exterior Doors Exterior steel lintels above windows and doors - strip and refinish	350	LF	\$1,000	3	\$5,250	\$5,000 \$525	\$9,900	\$6,815	\$64,900	\$0 \$0	\$6,815	\$0 \$0	
Exterior steer linters above windows and doors - strip and remism Exterior masonry cleaning and joint recaulking	1,000	SF	\$60	3	\$60,000	\$6,000	\$1,880	\$77,880	\$0	\$0	\$77,880	\$0	-
Secure vestibule upgrade at main entry	300	SF	\$325	1	\$97,500	\$9,750	\$19,305	\$126,555	\$126.555	\$0	\$0	\$0	
Security window film at entries and 1st floor windows	2.016	SF	\$12	1	\$24,192	\$2,419	\$4,790	\$31,401	\$31,401	\$0	\$0	\$0	
Roof replacement: shingle, original building (estimated roof surface SF)	105,899	SF	\$10		\$1,006,036	\$100,604	\$199,195	\$1,305,834	\$0	\$0	\$1,305,834	\$0	
Interiors		10	005.000	_	\$610,100	\$61,010 \$2,500	\$120,800	\$791,910	\$283,613	\$12,980	\$462,867	\$0	\$32
Upgrade and expand door control alarm system to report to offices	4 200	LS	\$25,000	5	\$25,000		\$4,950	\$32,450	\$0 \$0	\$0	\$0	\$0 ©0	\$32
Gymnasium flooring: replace	4,200	SF SF	\$48		\$201,600 \$77.000	\$20,160		\$261,677 \$99,946		\$0	\$261,677 \$99,946	\$0 \$0	
Gymnasium stage: replace wood face of apron, and flooring on apron and stage	770		\$100	3	. ,	\$7,700	\$15,246	,	\$0	\$0	* /		-
Gymnasium: replace backboards	6 2,200	EA SF	\$5,000	3	\$30,000 \$187,000	\$3,000 \$18,700	\$5,940 \$37.026	\$38,940	\$0 \$242,726	\$0 \$0	\$38,940 \$0	\$0	-
Install Insulation at Roof Deck Above Lobby & Bathroom	1,000	SF	\$85 \$48	3	\$187,000	\$18,700 \$4,800	\$37,026 \$9,504	\$242,726 \$62,304	\$242,726	\$0 \$0	\$62,304	\$0 \$0	-
Stage Ceiling (Plaster Repair)	1,000	EA	\$2,500	2	\$48,000	\$1,000	\$9,504	\$12,980	\$0 \$0	\$12,980	\$62,304 \$0	\$0 \$0	-
Uneven cleanouts in Hallway Flooring Kitchen bathroom: renovate and upgrade for ADA, finishes	70	SF	\$2,500	_	\$10,000	\$3,150	\$6,237	\$40,887	\$40.887	\$12,980	\$0 \$0	\$0 \$0	
			7.00				,		, ,,,,	7-1	***		
Program Needs					\$1,755,200	\$175,520	\$347,530	\$2,278,250	\$1,029,249	\$0	\$1,214,928	\$34,073	
Office: renovate and reconfigure; connect to secure vestibule for both entries; bathrooms	2,800	SF	\$150	1	\$420,000	\$42,000	\$83,160	\$545,160	\$545,160	\$0	\$0	\$0	
Classrooms/Faculty room casework: repalce casework, counters, and add storage units	39	EA	\$24,000	3	\$936,000	\$93,600	\$185,328	\$1,214,928	\$0	\$0	\$1,214,928	\$0	
Active Daily Living room: renovate, new casework, kitchen, exhaust, stations, bathroom	820	SF	\$435	1	\$356,700	\$35,670	\$70,627	\$462,997	\$462,997	\$0	\$0	\$0	
Crisis/Quiet/observation rooms: replace flooring and upgrade closures	650	SF	\$25	1	\$16,250	\$1,625	\$3,218	\$21,093	\$21,093	\$0	\$0	\$0	
Office manager office: reconfigure existing space	150	SF	\$175	4	\$26,250	\$2,625	\$5,198	\$34,073	\$0	\$0	\$0	\$34,073	
Mechanical					\$2,510,575	\$251,058	\$497,094	\$3,258,726	\$2,697,341	\$561,385	\$0	\$0	
Remove and replace HW/CHW AHUs with New (difficult locations)	q	EA	\$97,750	1	\$879,750	\$87,975	\$174,191	\$1,141,916	\$1,141,916	\$0	\$0	\$0	
Remove and replace HW/CHW Blower Coil Units with New	18	EA	\$25,000	1	\$450,000	\$45,000	\$89,100	\$584,100	\$584,100	\$0	\$0	\$0	
Remove and replace CUH's serving vestibules	8	EA	\$10,000	1	\$80,000	\$8,000	\$15.840	\$103,840	\$103,840	\$0	\$0	\$0	
Remove and replace Inline Exhaust fans with New	8	EA	\$10,000	1	\$80,000	\$8,000	\$15,840	\$103,840	\$103,840	\$0	\$0	\$0	
Remove and replace HW FTR with New	530	LF	\$250	2	\$132,500	\$13,250	\$26,235	\$171,985	\$0	\$171,985	\$0	\$0	
Remove and replace Gas-Fired Boiler with HW base mounted Pumps with New	1	EA	\$300,000	2	\$300,000	\$30,000	\$59,400	\$389,400	\$0	\$389,400	\$0	\$0	
BMS Controls	117,665	EA	\$5		\$588,325	\$58,833	\$116,488	\$763,646	\$763,646	\$0	\$0	\$0	
Plumbing					\$647,000	\$64,700	\$128,106	\$839,806	\$193,402	\$0	\$0	\$233.640	\$41
Replace Domestic Water Heater	1	EA	\$30,000	1	\$30,000	\$3,000	\$5,940	\$38,940	\$38,940	\$0	\$0	\$0	Ψ.
Back-flow prevention device	2	EA	\$9,500	5	\$19,000	\$1,900	\$3,762	\$24,662	\$0	\$0	\$0	\$0	\$2
Replace water cooler with bottle fill type	13	EA	\$8,000	5	\$104,000	\$10,400	\$20,592	\$134,992	\$0	\$0	\$0	\$0	\$13
Replace urinals w/ hands-free flushometers	8	EA	\$5,000	5	\$40,000	\$4,000	\$7,920	\$51,920	\$0	\$0	\$0	\$0	\$5
Replace lavatories w/ hands-free faucets	31	EA	\$5,000	5	\$155,000	\$15,500	\$30,690	\$201,190	\$0	\$0	\$0	\$0	\$2
Replace water closet w/ hands-free flushometers	30	EA	\$6,000	4	\$180,000	\$18,000	\$35,640	\$233,640	\$0	\$0	\$0	\$233,640	
Install thermostatic mixing-valves in sinks and lavatories	34	EA	\$3,500	1	\$119,000	\$11,900	\$23,562	\$154,462	\$154,462	\$0	\$0	\$0	
Electrical					\$213,000	\$21,300	\$42,174	\$276,474	\$272,580	\$0	\$0	\$0	
Add additional emergency lighting fixtures within the Health Suite	1	EA	\$1,500	1	\$1,500	\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0	
Add additional emergency lighting fixture within the Resource Center	1	EA	\$1,500	1	\$1,500 \$1,500	\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0	
	1	SF	\$1,500	1	\$1,500	\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0	
Add additional emergency lighting fixture within the Break Room	1	EA	\$1,500	1	\$1,500	\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0	
		EA	\$1,500	1	\$45,000	\$4,500	\$8.910	\$58,410	\$58,410	\$0	\$0	\$0	
Add additional emergency lighting fixture within the Non-Public Department open office	30					\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0	
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms	30	FA	\$1,500	1	\$1,500				Ψ.,041				H
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room	30 1	EA FA	\$1,500 \$1,500	1	\$1,500 \$1,500				\$1 947	90			
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room Add additional emergency lighting fixture within the Daily Living Life Skills Room 115	1	EA	\$1,500		\$1,500	\$150	\$297	\$1,947	\$1,947 \$77,880	\$0 \$0	\$0	\$0	
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room Add additional emergency lighting fixture within the Daily Living Life Skills Room 115 Install occupancy sensors in classrooms, storage rooms and bathrooms within the original building	1 1 80	EA EA	\$1,500 \$750	1	\$1,500 \$60,000	\$150 \$6,000	\$297 \$11,880	\$1,947 \$77,880	\$77,880	\$0	\$0 \$0	\$0 \$0	
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room Add additional emergency lighting fixture within the Daily Living Life Skills Room 115 Install occupancy sensors in classrooms, storage rooms and bathrooms within the original building Replace broken access doors for the recessed floor boxes in the conference center	1	EA	\$1,500	1	\$1,500	\$150	\$297	\$1,947			\$0	\$0 \$0 \$0	
Add additional emergency lighting fixture within the Break Room Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room Add additional emergency lighting fixture within the Daily Living Life Skills Room 115 Install occupancy sensors in classrooms, storage rooms and bathrooms within the original building Replace broken access doors for the recessed floor boxes in the conference center Install speaker strobe in faculty room, Special Education room Electrical required for mechanical work	1 1 80	EA EA	\$1,500 \$750	1	\$1,500 \$60,000 \$6,000	\$150 \$6,000	\$297 \$11,880	\$1,947 \$77,880 \$7,788	\$77,880 \$7,788	\$0 \$0	\$0 \$0 \$0	\$0 \$0	(
Add additional emergency lighting fixture within the Non-Public Department open office Add additional emergency lighting fixture within the classroom bathrooms Add additional emergency lighting fixture within the Business Office Conference Room Add additional emergency lighting fixture within the Daily Living Life Skills Room 115 Install occupancy sensors in classrooms, storage rooms and bathrooms within the original building Replace broken access doors for the recessed floor boxes in the conference center Install speaker strobe in faculty room, Special Education room	1 1 80	EA EA EA	\$1,500 \$750 \$1,000 \$1,500	1	\$1,500 \$60,000 \$6,000 \$3,000	\$150 \$6,000 \$600 \$300	\$297 \$11,880 \$1,188 \$594	\$1,947 \$77,880 \$7,788 \$3,894	\$77,880 \$7,788 \$0	\$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$4

	Quantity	Unit	Unit Cost Priorit	Hard Cost	Contingency	Soft Costs	Total	1	2	3	4	Underway
Nuview Academy	Quantity	Offic	Code	e Hard Cost	Contingency	3011 60515	Total	Total	Total	Total	Total	Total
Site Work				\$38,000	\$3,800	\$7,524	\$49,324	\$0	\$0	\$36,344	\$0	\$12,9
Exterior surface cleaning and selective repairs	1	LS	\$7,500 5	\$7,500	\$3,800 \$750	\$1,32 4 \$1,485	\$9,735	\$0	\$0 \$0	\$50,544	\$0	\$12,9
Playground equipment: replace with age appropriate	1	LS	\$28,000 3	\$28,000	\$2,800	\$5,544	\$36,344	\$0	\$0	\$36.344	\$0	
Add drive and parking area signage for traffic flow and drop off areas	1	LS	\$2,500 5	\$2,500	\$250	\$495	\$3,245	\$0	\$0	\$0	\$0	\$3,2
			. ,,,,,,,						***	*-1		, , ,
Building Envelope				\$914,990	\$91,499	\$181,168	\$1,187,657	\$1,060,323	\$0	\$127,334	\$0	
Replace Exterior Outlets	5	EA	\$500 1	\$2,500	\$250	\$495	\$3,245	\$3,245	\$0	\$0	\$0	
Green Roof: replace membrane below trays, drainage, and adjacent vertical surfaces	1,500	SF	\$110 1	\$165,000	\$16,500	\$32,670	\$214,170	\$214,170	\$0	\$0	\$0	
Green Roof Gutter replacement	1,650	LF	\$25 1	\$41,250	\$4,125	\$8,168	\$53,543	\$53,543	\$0	\$0	\$0	
Exterior gutter and downspout boots, repairs, and replacements	2.680	LS	\$750 1 \$50 1	\$3,000 \$134,000	\$300 \$13,400	\$594	\$3,894	\$3,894 \$173.932	\$0	\$0	\$0	
Replace Siding Around Green Roof Replace Closer on Door to Green Roof	2,680	SF EA	\$50 1 \$1,500 1	\$1,500	\$13,400 \$150	\$26,532 \$297	\$173,932 \$1,947	\$173,932 \$1,947	\$0 \$0	\$0 \$0	\$0 \$0	-
Structure: investigate and address structural upgrades at sagging balcony	1	LS	\$350,000 1	\$350,000	\$35,000	\$69,300	\$454,300	\$454.300	\$0 \$0	\$0 \$0	\$0 \$0	
Recaulk doors and windows	1	LS	\$12,000 3	\$12,000	\$1,200	\$2,376	\$15,576	\$0	\$0	\$15,576	\$0	
Door hardware replacement (exterior)	14	EA	\$4,500 3	\$63,000	\$6,300	\$12,474	\$81,774	\$0	\$0	\$81,774	\$0	
Secure vestibule upgrade (main entry, office, seating area)	1	LS	\$85,000 1	\$85,000	\$8,500	\$16,830	\$110,330	\$110,330	\$0	\$0	\$0	
Security window film at entries and 1st floor windows	1,720	SF	\$12 1	\$20,640	\$2,064	\$4,087	\$26,791	\$26,791	\$0	\$0	\$0	
Roofing: replace low slope roof areas	330	SF	\$70 3	\$23,100	\$2,310	\$4,574	\$29,984	\$0	\$0	\$29,984	\$0	
Roofing: repair leaks over low-slope kitchen roof area	200	SF	\$70 1	\$14,000	\$1,400	\$2,772	\$18,172	\$18,172	\$0	\$0	\$0	
Interiors				\$483,250	\$48,325	\$95,684	\$627,259	\$103.840	\$290,103	\$233.316		
	300	SF	\$50 3	\$483,250 \$15,000	\$48,325 \$1,500	\$95,684 \$2,970	\$627,259 \$19,470	\$103,840 \$0	\$290,103 \$0	\$233,316 \$19,470	\$0 \$ 0	
Wall repairs with abuse resistant gypsum board Acoustic treatments in MP Room/gymnasium (wall and ceiling)	1,200	SF	\$60 2	\$15,000	\$7,500	\$2,970 \$14,256	\$19,470	\$0 \$0	\$93,456	\$19,470 \$0	\$0 \$0	-
Flooring: replace in common/corridor areas	3.650	SF	\$15 3	\$54,750	\$7,200 \$5,475	\$14,256	\$71.066	\$0	\$93,456	\$71.066	\$0	
Nurse's area: renovate, finishes, casework, bathroom	320	SF	\$450 2	\$144,000	\$14,400	\$28,512	\$186,912	\$0	\$186,912	\$0	\$0	
Main office bathroom: renovate for ADA	1	LS	\$75,000 1	\$75,000	\$7,500	\$14,850	\$97,350	\$97,350	\$0	\$0	\$0	
Quiet room: replace finishes, padding	1	LS	\$7,500 2	\$7,500	\$750	\$1,485	\$9,735	\$0	\$9,735	\$0	\$0	
Stairs: create areas of refuge: add communications, repair walls, etc.	2	EA	\$10,000 3	\$20,000	\$2,000	\$3,960	\$25,960	\$0	\$0	\$25,960	\$0	
Door hardware replacement (interior)	50	EA	\$1,800 3	\$90,000	\$9,000	\$17,820	\$116,820	\$0	\$0	\$116,820	\$0	
Repair Holes in Stairwell Wall	100	SF	\$50 1	\$5,000	\$500	\$990	\$6,490	\$6,490	\$0	\$0	\$0	
December Monda				\$959.875	\$95.988	\$190.055	\$1,245,918	\$388.102	\$0	\$23,364	\$0	\$834.4
Program Needs Active Daily Living (214): reconfigure, add bathroom, finishes, kitchen/exhaust, casework	550	SE.	\$425 E	\$959,675	\$95,966	\$190,055 \$47,372	\$1,245,916	\$366,102 \$0	\$0 \$0	\$23,364 \$0	\$ 0	\$310,5
Active Daily Living (214). reconliquire, and barricolni, linishes, kitchen/exhaust, casework Art room (213): reconfigure for faculty use, add Art storage area	490	SF	\$325 5	\$159,250	\$15.925	\$31.532	\$206,707	\$0	\$0	\$0	\$0	\$206.
Game room/library (201): reconfigure to add eSport; update finishes; add casework	715	SF	\$325 5	\$232,375	\$23,238	\$46.010	\$301.623	\$0	\$0	\$0	\$0	\$301,6
Classroom 103: reconfigure to pre-voc and multi-purpose use; add casework; finishes	620	SF	\$325 1	\$201,500	\$20,150	\$39,897	\$261,547	\$261,547	\$0	\$0	\$0	4001,1
Acoustic: MP Room storefront/glass divider wall separation to corridor	780	SF	\$125 1	\$97,500	\$9,750	\$19,305	\$126,555	\$126,555	\$0	\$0	\$0	
Common corridor seating outside MP Room - replace	12	EA	\$1,500 3	\$18,000	\$1,800	\$3,564	\$23,364	\$0	\$0	\$23,364	\$0	
Corridor bulliten boards: remove, replace with secured or digital displays	1	LS	\$12,000 5	\$12,000	\$1,200	\$2,376	\$15,576	\$0	\$0	\$0	\$0	\$15,5
Madembal				\$200.000	\$00,000	640.055	\$000 F0F	\$40F.00F	\$0	\$07.0F0	¢0	
Mechanical Compared to be in the compared and a value of the compared to the	1	F .	\$75,000 3	\$202,300		\$40,055	\$262,585	\$165,235	\$0	\$97,350	\$0	
Gym: detailed assessment and system modifications allowance	1	EA	4.0,000	\$75,000	\$7,500	\$14,850	\$97,350	\$0		\$97,350	\$0	
ADL Room: add Exhaust Fan and exhaust system BMS Controls	21,860	EA EA	\$18,000 1	\$18,000 \$109,300	\$1,800 \$10,930	\$3,564 \$21,641	\$23,364 \$141,871	\$23,364 \$141,871	\$0 \$0	\$0 \$0	\$0 \$0	
BNG COITEOS	21,800	EA	φυ	\$109,300	\$10,930	φ21,041	\$141,071	φ141,071	\$ 0	\$ 0	ΦΟ	
Plumbing				\$291,000	\$29,100	\$57,618	\$377,718	\$99,946	\$0	\$0	\$0	\$277,
Replace urinals w/ hands-free flushometers	6	EA	\$5,000 5	\$30,000	\$3,000	\$5,940	\$38,940	\$0	\$0	\$0	\$0	\$38,
Replace lavatories w/ hands-free faucets	18	EA	\$5,000 5	\$90,000	\$9,000	\$17,820	\$116,820	\$0	\$0	\$0	\$0	\$116,8
Replace water closet w/ hands-free flushometers	13	EA	\$6,000 5	\$78,000	\$7,800	\$15,444	\$101,244	\$0	\$0	\$0	\$0	\$101,2
Replace water cooler with bottle fill type	2	EA	\$8,000 5	\$16,000	\$1,600	\$3,168	\$20,768	\$0	\$0	\$0	\$0	\$20,
Install thermostatic mixing-valves in sinks and lavatories	22	EA	\$3,500 1	\$77,000	\$7,700	\$15,246	\$99,946	\$99,946	\$0	\$0	\$0	
Electrical				\$41,750	\$4,175	\$8.267	\$54,192	\$49.649	\$0	\$4.543	¢o.	
111 11	1	EA	\$1,500 1	\$41,750 \$1,500	\$4,175 \$150	\$8,267 \$297	\$54,192 \$1,947	\$49,649 \$1,947	\$0	\$4,543 \$0	\$0 \$0	
Repair/replace the lighting fixture in room 201 Install an occupancy sensor switch in the single girls bathroom on the second floor	1	EA	\$1,500 1 \$750 1	\$1,500 \$750	\$150 \$75	\$297 \$149	\$1,947 \$974	\$1,947 \$974	\$0 \$0	\$0 \$0	\$0 \$0	-
Install emergency lighting in the classrooms	15	EA	\$1,500	\$22,500	\$2,250	\$4,455	\$29,205	\$29,205	\$0	\$0	\$0	
Add additional receptacles in room 103, 201, 212	6	EA	\$1,200 1	\$7,200	\$720	\$1,426	\$9,346	\$9,346	\$0	\$0	\$0	
Reinstall the shade controller in the kitchen for the gym shades	1	EA	\$3,500 3	\$3,500	\$350	\$693	\$4,543	\$0	\$0	\$4,543	\$0	
Install a smoke detector in classroom 102	11	EA	\$1,300 1	\$1,300	\$130	\$257	\$1,687	\$1,687	\$0	\$0	\$0	
Electrical requried for mechanical work	1	EA	\$5,000 1	\$5,000	\$500	\$990	\$6,490	\$6,490	\$0	\$0	\$0	
Hard and Soft Cost - Total Budget								\$1,867,095	\$290,103	\$522,250	\$0	\$1,125,
												_
Assumptions												

Piscataway Regional Day School	Quantity	Unit	Unit Cost	Priority	Hard Cost	Contingency	Soft Costs	Total	Tel	2	3	<u>4</u>
Piscataway Regional Day School	•			Code		,			Total	Total	Total	Total
Site Work					\$87,500	\$8,750	\$17,325	\$113,575	\$0	\$32,450	\$12,980	\$19,470
Wood walkways to play areas - replace	2	EA	\$7,500	4	\$15,000	\$1,500	\$2,970	\$19,470	\$0	\$0	\$0	\$19,470
Sidewalk Replacement	400	SF	\$25	3	\$10,000	\$1,000	\$1,980	\$12,980	\$0	\$0	\$12,980	\$0
Asphalt Repaving (mill and overlay; repairs)	2,500	SF	\$15	5	\$37,500	\$3,750	\$7,425	\$48,675	\$0	\$0	\$0	\$0
Playground equipment: replace	1	LS	\$25,000	2	\$25,000	\$2,500	\$4,950	\$32,450	\$0	\$32,450	\$0	\$0
Building Envelope					\$1,190,000	\$119,000	\$235,620	\$1,544,620	\$84,370	\$0	\$175,230	\$1,285,020
Exterior EIFS repair	4,500	SF	\$30	3	\$135,000	\$13,500	\$26,730	\$175,230	\$0	\$0	\$175,230	\$0
Courtyard infill/enclose/roof for additional instruction space	1,800	SF	\$550	4	\$990,000	\$99,000	\$196,020	\$1,285,020	\$0	\$0	\$0	\$1,285,020
Exterior doors and frames: replace and repair, new hardware	10	EA	\$6,500	1	\$65,000	\$6,500	\$12,870	\$84,370	\$84,370	\$0	\$0	\$0
nteriors					\$853.715	\$85,372	\$169,036	\$1,108,122	\$360.195	\$427,269	\$259,912	\$0
	1	LS	\$1,500	3	\$1,500	\$150	\$103,030	\$1,100,122	\$00,195	\$0	\$1,947	\$0
Reinstall Cafeteria Table Bench Framing in Wall of Gym	1							\$1,947 \$2.336				
Clean Corrosion in Cleaning Closet at Gym	1	LS	\$1,800	3	\$1,800	\$180	\$356	* /	\$0	\$0 \$0	\$2,336	\$0
Interior Finishes, Ceiling, Painting, Etc		LS	\$125,000	3	\$125,000	\$12,500	\$24,750	\$162,250	\$0	\$0 \$0	\$162,250	\$0
Entry lobby: create secure vestible; expand office area	700 1.400	SF	\$325	1	\$227,500	\$22,750	\$45,045	\$295,295	\$295,295	\$0	\$0	\$0
Security window film at entries and 1st floor windows	1,400	SF	\$12	5	\$16,800	\$1,680	\$3,326	\$21,806	\$0	\$0	\$0	\$0
Security: upgrade Alyssa law system and door lockdown capability	7	LS	\$25,000	5	\$25,000	\$2,500	\$4,950	\$32,450	\$0 \$0	\$0	\$0 \$0	\$0
Vestibule flooring: replace	765	SF	\$25 \$30	2	\$5,000 \$22,950	\$500 \$2,295	\$990 \$4.544	\$6,490 \$29,789	\$0 \$0	\$0 \$29,789	\$0 \$0	\$0 \$0
Toilet room flooring: replace	765 550	SF	\$30 \$550	2	\$22,950 \$302,500	\$2,295 \$30,250	\$4,544 \$59,895	\$29,789 \$392,645	\$0 \$0	\$29,789 \$392,645	\$0 \$0	\$0 \$0
Toilet rooms: renovate public toilet rooms		SF										
Renovate washer/dryer and storage area near gym; improve exhaust	400		\$125	2	\$50,000	\$5,000	\$9,900	\$64,900	\$64,900	\$0	\$0	\$0
Gymnasium walls: replace panels and repair masonry	1	LS	\$125		\$125	\$13	\$25	\$162	\$0	\$162	\$0	\$0
Replace finishes in Speech Room	80	SF	\$45	2	\$3,600	\$360	\$713	\$4,673	\$0	\$4,673	\$0	\$0
Replace Wire Mesh Glazing in Classroom Doors	33	EA	\$680	3	\$22,440	\$2,244	\$4,443	\$29,127	\$0	\$0	\$29,127	\$0
Jpgrade door hardware; selective replacement and repair of doors	33	EA	\$1,500	3	\$49,500	\$4,950	\$9,801	\$64,251	\$0	\$0	\$64,251	\$0
Program Needs					\$1,294,750	\$129,475	\$256,361	\$1,680,586	\$794,701	\$837,210	\$48,675	\$0
Nurse's area: renovate, finishes, new casework, bathroom	500	SF	\$450	2	\$225,000	\$22,500	\$44,550	\$292,050	\$0	\$292,050	\$0	\$0
Kitchen: renovate, upgrade service line, replace equipment, exhaust	1	LS	\$175,000	1	\$175,000	\$17,500	\$34,650	\$227,150	\$227,150	\$0	\$0	\$0
Classroom casework: replace with new counters, cabs, add tall storage	14	EA	\$24,000	2	\$336,000	\$33,600	\$66,528	\$436,128	\$0	\$436,128	\$0	\$0
Bathroom storage: add cabinets to bathrooms for storage of supplies/equip.	15	EA	\$2,500	3	\$37,500	\$3,750	\$7,425	\$48,675	\$0	\$0	\$48,675	\$0
Active Daily Living: Renovate with new casework, finishes, areas, exhaust and Wash/dryer	950	SF	\$435	1	\$413,250	\$41,325	\$81,824	\$536,399	\$536,399	\$0	\$0	\$0
Pre-voc room: add casework for storage	1	EA	\$24,000	1	\$24,000	\$2,400	\$4,752	\$31,152	\$31,152	\$0	\$0	\$0
Quiet/isolation areas: Upgrade finishes, padding	12	EA	\$7,000	2	\$84,000	\$8,400	\$16,632	\$109,032	\$0	\$109,032	\$0	\$0
Mechanical					\$30,000	\$3,000	\$5,940	\$38,940	\$0	\$0	\$38,940	\$0
Floor mounted CUH's (entry vestibules) from 1997 replacement	3	EA	\$10,000	3	\$30,000	\$3,000	\$5,940	\$38,940	\$0	\$0	\$38,940	\$0
Plumbing					\$339,000	\$33,900	\$67,122	\$440,022	\$127,204	\$0	\$0	\$0
<u> </u>	1	ΕΛ	ØE 000	E		\$53,900 \$500	\$07,122					•
Replace urinals w/ hands-free flushometers	22	EA	\$5,000	5	\$5,000	7000	ψοσο	\$6,490 \$142,780	\$0 \$0	\$0 \$0	\$0 \$0	\$0 \$0
Replace lavatories w/ hands-free faucets	22	EA	\$5,000	5	\$110,000	\$11,000	\$21,780	\$142,780	\$0 \$0	\$0 \$0		
Replace water closet w/ hands-free flushometers	28	EA	\$3,500	1	\$126,000	\$12,600	\$24,948 \$19,404	\$163,548 \$127,204	\$0 \$127.204	\$0 \$0	\$0 \$0	\$0 \$0
nstall thermostatic mixing-valves in sinks and lavatories	28	EA	\$3,500	1	\$98,000	\$9,800	\$19,404	\$127,204	\$127,204	\$0	\$0	\$0
Electrical					\$59,700	\$5,970	\$11,821	\$77,491	\$77,491	\$0	\$0	\$0
nstall an emergency lighting fixture in the girls bathroom located behind the gym	1	EA	\$1,500	1	\$1,500	\$150	\$297	\$1,947	\$1,947	\$0	\$0	\$0
	66	EA	\$750	1	\$49,500	\$4,950	\$9,801	\$64,251	\$64,251	\$0	\$0	\$0
nstall occupancy sensors in classrooms, offices and bathrooms	- 1	EA	\$1,200	1	\$1,200	\$120	\$238	\$1,558	\$1,558	\$0	\$0	\$0
nstall occupancy sensors in classrooms, offices and bathrooms					\$7,500	\$750	\$1,485	\$9,735	\$9,735	\$0	\$0	\$0
nstall occupancy sensors in classrooms, offices and bathrooms nstall an additional receptacle within the speech office	1	EA	\$7,500	1	\$7,500	ψ. σσ	* ,			-		
Install occupancy sensors in classrooms, offices and bathrooms Install an additional receptacle within the speech office Electrical requried for mechanical work Hard and Soft Cost - Total Budget	1	EA	\$7,500	1	\$7,500	4.00	, ,		\$1,443,960	\$1,296,929	\$535,737	\$1,304,490
nstall occupancy sensors in classrooms, offices and bathrooms nstall an additional receptacle within the speech office Electrical requried for mechanical work	1	EA	\$7,500	1	\$7,300	ψ.σσ	,,		\$1,443,960	\$1,296,929	\$535,737	\$1,304,490