

Pb in Water Report - Pelham UFSD - Colonial School																	
First Sample Data						Second Sample Data						Third Sample Data					
Sample ID #	Lab ID #	Sample Location	Date Sampled	Results (mg/L)	Compliant / Non Compliant	Sample ID #	Lab ID #	Date Sampled	Results (mg/L)	Remediation Method Used	Compliant / Non Compliant	Sample ID #	Lab ID #	Date Sampled	Results (mg/L)	Remediation Method Used	Compliant / Non Compliant
1A	2413936	CS - CR 200	3/23/2016	0.034	Non Compliant	22A	2423999	5/7/2016	0.007	INSTALLED WATER FILTER	Compliant						
2A	2413938	CS - CR 201 - Bathroom 1	3/23/2016	0.026	Non Compliant	23A	2424001	5/7/2016	0.001	INSTALLED WATER FILTER	Compliant						
3A	2413940	CS - CR 201 - Bathroom 2	3/23/2016	0.006	Compliant												
4A	2413942	CS - CR 201 - Bathroom 3	3/23/2016	0.004	Compliant												
5A	2413944	CS - CR 204	3/23/2016	0.014	Compliant												
6A	2413946	CS - CR 205	3/23/2016	0.001	Compliant												
7A	2413948	CS - CR 206	3/23/2016	0.005	Compliant												
8A	2413950	CS- Hallway - water fountain	3/23/2016	BDL < .001	Compliant												
9A	2413952	CS - CR 208	3/23/2016	0.006	Compliant												
10A	2413954	CS - CR 207	3/23/2016	0.003	Compliant												
11A	2413956	CS - CR 209	3/23/2016	0.011	Compliant												
12A	2413958	CS - Room 210 bathroom - 1st sink	3/23/2016	0.005	Compliant												
13A	2413960	CS - Room 210 bathroom - 2nd sink	3/23/2016	0.008	Compliant												
14A	2413962	CS - CR 211	3/23/2016	0.003	Compliant												
15A	2413964	CS - CR 102C - Nurse Office	3/23/2016	0.001	Compliant												
16A	2413966	CS - CR 103	3/23/2016	0.002	Compliant												
17A	2413968	CS - CR 104	3/23/2016	0.004	Compliant												
18A	2413970	CS - CR 105	3/23/2016	0.022	Non Compliant	N/A	N/A	N/A	N/A	INSTALL SIGN - NOT DRINKING WATER	COMPLIANT						
19A	2413972	CS - 2nd floor hallway water fountain	3/23/2016	BDL < .001	Compliant												
20A	2413974	CS - CR 106	3/23/2016	0.006	Compliant												
21A	2413976	CS - CR 107	3/23/2016	0.005	Compliant	21A	2423997	5/7/2016	BDL < .001		Compliant						

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

8A	2414806	Annex - Room 252 (science lab) Sink # 2	3/24/2016	0.019	Non Compliant	3	2459689	10/12/2016	0.004	INSTALLED WATER FILTER	Compliant												
9A	2414808	Annex - Room 252 (science lab) Sink # 3	3/24/2016	0.014	Compliant																		
10A	2414810	Annex - Room 252 (science lab) Sink # 4	3/24/2016	0.009	Compliant																		
11A	2414812	Annex - Room 252 (science lab)	3/24/2016	0.008	Compliant																		
12A	2414814	Annex - Room 252 (science lab)	3/24/2016	0.006	Compliant																		
13A	2414816	Annex - Room 254 (science lab) - Sink # 1	3/24/2016	0.037	Non Compliant	4	2459690	10/12/2016	0.091	INSTALLED WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	INSTALLED SIGN - NOT FOR DRINKING	COMPLIANT						
14A	2414818	Annex - Room 254 (science lab) Sink # 2	3/24/2016	0.041	Non Compliant	5	2459691	10/12/2016	0.008	INSTALLED WATER FILTER	Compliant												
15A	2414820	Annex - Room 254 (science lab)	3/24/2016	0.008	Compliant																		
16A	2414822	Annex - Room 254 (science lab) Sink # 4	3/24/2016	0.02	Non Compliant	6	2459692	10/12/2016	0.004	INSTALLED WATER FILTER	Compliant												
17A	2414824	Annex - Room 254 (science lab)	3/24/2016	0.009	Compliant																		
18A	2414826	Annex - Room 254 (science lab)	3/24/2016	0.01	Compliant																		
19A	2414828	Annex - Room 254 (science lab)	3/24/2016	0.011	Compliant																		
20A	2414830	Annex - Room 254 (science lab) Sink # 8	3/24/2016	0.116	Non Compliant	N/A	N/A	N/A	N/A	INSTALLED SIGN - NOT FOR DRINKING	COMPLIANT												
7	2459693	Annex - Room 254 (office) Sink	10/12/2016	0.028	Non Compliant	N/A	N/A	N/A	N/A	INSTALLED SIGN - NOT FOR DRINKING	COMPLIANT												
21A	2414832	Annex - Hallway water fountain next to room 255	3/24/2016	BDL < .001	Compliant																		
22A	2414834	Annex - Room 255 (science lab)	3/24/2016	0.005	Compliant																		
23A	2414836	Annex - Room 255 (science lab)	3/24/2016	0.001	Compliant																		
24A	2414838	Annex - Room 255 (science lab)	3/24/2016	0.007	Compliant																		
25A	2414840	Annex - Room 255 (science lab)	3/24/2016	0.01	Compliant																		
26A	2414842	Annex - Room 255 (science lab)	3/24/2016	0.005	Compliant																		
27A	2414844	Annex - Room 255 (science lab) Sink # 6	3/24/2016	0.016	Non Compliant	8	2459694	10/12/2016	0.019	INSTALLED WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	INSTALLED SIGN - NOT FOR DRINKING	COMPLIANT						

[illegible]

62A	2415104	Annex - water fountain across from band room 053 (elkay)	3/24/2016	BDL < .001	Compliant																		
63A	2415106	Annex - restroom (few feet from water fountain (next to room 056)	3/24/2016	0.001	Compliant																		
64A	2415108	Annex - room 056 art room sink near door	3/24/2016	0.116	Non Compliant	1A	2423957	5/7/2016	BDL < .001	INSTALLED WATER FILTER & NEW FAUCET	Compliant												
65A	2415110	Annex - room 052 art room sink nearest door (1)	3/24/2016	0.001	Compliant																		
66A	2415112	Annex - Room 052 art room sink (2) double sink	3/24/2016	0.011	Compliant																		
67A	2415114	Annex room 156 - sink (1) right side closest to door	3/24/2016	0.004	Compliant																		
68A	2415116	Annex - Room 156 - Sink (2) back right	3/24/2016	BDL < .001	Compliant																		
69A	2415118	Annex - room 156 - Sink (3) back left	3/24/2016	0.003	Compliant																		
70A	2415120	Annex - Area between labs - next to ice machine sink	3/24/2016	0.008	Compliant																		
71A	2415122	Annex- Area between labs - ice machine dispenser	3/24/2016	0.007	Compliant																		
72A	2415124	Annex - Room 154 Back right Sink (1)	3/24/2016	0.002	Compliant																		
73A	2415126	Annex - 154 Back left sink (2)	3/24/2016	0.005	Compliant																		
74A	2415128	Annex - 154 front left sink (3)	3/24/2016	0.002	Compliant																		
75A	2415130	Annex - next to room 155 Lounge area - sink	3/24/2016	0.001	Compliant																		
76A	2415132	Annex - room 157 Bench Top Sink # 1	3/24/2016	0.116	Non Compliant	16	2459702	10/12/2016	0.539	INSTALLED WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	REMOVED SINK & FAUCET	COMPLIANT						
17	2459703	Annex - room 157 - Sink # 2	10/7/2016	0.381	Non Compliant											REMOVED SINK & FAUCET	COMPLIANT						
77A	2415134	Annex - room 155 - bench top sink #1	3/24/2016	0.841	Non Compliant	18	2459704	10/12/2016	1.386	INSTALLED WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	REMOVED SINK & FAUCET	COMPLIANT						
19	2459705	Annex - room 155 - Sink # 2	10/12/2016	1.481	Non Compliant											REMOVED SINK & FAUCET	COMPLIANT						
20	2459706	Annex - room 153 - backroom sink	10/12/2016	0.047	Non Compliant	20	2457706	10/12/2016	0.047	INSTALLED WATER FILTER & NEW FAUCET	NON COMPLIANT	N/A	N/A	N/A	N/A	REMOVED SINK & FAUCET	COMPLIANT						

[illegible]

[illegible]

[illegible]

Pb in Water Report - Pelham UFSD - Hutchinson																	
First Sample Data						Second Sample Data						Third Sample Data					
Sample ID #	Lab ID #	Sample Location	Date Sampled	Results (mg/L)	Compliant / Non Compliant	Sample ID #	Lab ID #	Date Sampled	Results (mg/L)	Remediation Method Used	Compliant / Non Compliant	Sample ID #	Lab ID #	Date Sampled	Results mg/L)	Remediation Method Used	Compliant / Non Compliant
R1A	2414889	Classroom 203 - Sink	3/24/2016	0.002	Compliant												
R2A	2414891	Classroom 201 - Sink	3/24/2016	0.014	Compliant	36A	2424026	5/7/2016	0.06	INSTALLED WATER FILTER & NEW FAUCET	Compliant						
R3A	2414893	Girls room - top sink	3/24/2016	0.012	Compliant												
R4A	2414895	Boys room - top - single lever	3/24/2016	0.007	Compliant												
R5A	2414897	Teachers room - top - single lever	3/24/2016	0.009	Compliant												
R6A	2414899	Water fountain - top	3/24/2016	BDL < .001	Compliant												
R7A	2414901	Classroom 208 - sink	3/24/2016	0.013	Compliant												
R8A	2414903	Classroom 101 - sink	3/24/2016	0.016	Non Compliant	35A	2424025	5/7/2016	0.004	INSTALLED WATER FILTER & NEW FAUCET	Compliant						
R9A	2414905	Nurse office sink - 100A - single lever	3/24/2016	0.004	Compliant												
R10A	2414907	Classroom 102 - sink	3/24/2016	0.002	Compliant												
R11A	2414909	Classroom 119 - sink	3/24/2016	0.009	Compliant												
R12A	2414911	Classroom 103 - sink	3/24/2016	0.007	Compliant												
R13A	2414913	Classroom 118 - sink - single lever	3/24/2016	0.01	Compliant												
R14A	2414915	Classroom 117 - sink	3/24/2016	0.006	Compliant												
R15A	2414917	Classroom 105 - sink	3/24/2016	0.011	Compliant												
R16A	2414919	Classroom 116 - sink	3/24/2016	0.015	Compliant	34	2459720	10/12/2016	0.005		Compliant						
R17A	2414921	Classroom 115 - sink	3/24/2016	0.004	Compliant												
R18A	2414923	Classroom 113 - sink	3/24/2016	0.004	Compliant												
R19A	2414925	Classroom 114 - sink	3/24/2016	0.005	Compliant												
R20A	2414927	Classroom 110 - sink (fountain leaking)	3/24/2016	0.027	Non Compliant	33A	2424021	5/7/2016	0.022	INSTALL WATER FILTER	Non Compliant	35	2459721	10/12/2016	0.004	INSTALLED NEW WATER FAUCET	Compliant
R21A	2414929	Boys Main	3/24/2016	0.005	Compliant												
R22A	2414931	Boys Main	3/24/2016	0.005	Compliant												
R23A	2414933	Boys Main	3/24/2016	0.004	Compliant												
R24A	2414935	Girls Main	3/24/2016	0.005	Compliant												
R25A	2414937	Girls Main	3/24/2016	0.005	Compliant												
R26A	2414939	Girls Main	3/24/2016	0.006	Compliant												
R27A	2414941	Fountain ELK	3/24/2016	0.001	Compliant												
R28A	2414943	Library (01) - Sink (Dripping)	3/24/2016	0.023	Non Compliant	37A	2424029	5/7/2016	0.037	INSTALLED WATER FILTER	Non Compliant	32	2459718	10/12/2016	0.016	REMOVED SINK & FAUCET	Compliant

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

55A	2415090	MS - room 074 restroom - girls locker sink (2) (middle) sink - tempered water	3/24/2016	0.001	Compliant																			
56A	2415092	MS - room 074 restroom - girls locker sink (3) (furthest to door) sink - tempered water	3/24/2016	0.002	Compliant																			
57A	2415094	MS - room 074 - restroom - girls lockers- water fountain outside restroom	3/24/2016	BDL < .001	Compliant																			
58A	2415096	MS - 070A- PE office bathroom sink	3/24/2016	0.001	Compliant																			
5A	2423965	MS - 157 sink	5/7/2016	0.024	Non Compliant	16	2459701	10/12/2016	0.029	INSTALL WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	REMOVED SINK AND FAUCET	COMPLIANT							
6A	2423967	MS - 155 sink	5/7/2016	0.104	Non Compliant	18	704	10/12/2016	1.386	INSTALL WATER FILTER & NEW FAUCET	Non Compliant	N/A	N/A	N/A	N/A	REMOVED SINK AND FAUCET	COMPLIANT							