OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN

COST SUMMARY



455 East Main Ave. Morgan Hill, Ca 95037 eltoro.mhusd.org

Year Built: 1992 Year Modernized: Student Population (2016 - 2017): 450 Number of Classrooms: 25 Number of Portables: 2 Site Acreage: 12.7 acres Building Area: 43,300 square feet Academic Focus: Health Science

PRINCIPAL'S TOP 3 'WANTS'

- 1. New roof
- Front gate security 2.
- 3. New coat of paint for all buildings

Desired Program Support Improvements/Additions

- . Running/fitness track with work out station.
- Improvement to Administration offices for increased . space efficiency.

Functionality of Space

- The Library will move to room 15. Existing Library • space will be converted to a Health Lab (currently in design phases of development).
- Classrooms front on a central guad, which enhances • the opportunity for outdoor learning environments.

ASSESSMENT R	ATING LEGEND:
CATEGORY [0]	No Work
CATEGORY [1]	Minor Work
CATEGORY [2]	Minor Modernization
CATEGORY [3]	Standard Modernization
CATEGORY [4]	Major Modernization /
	Reconfiguration
CATEGORY [5]	Complete Replacement

GENERAL

ADA Compliance

Category [0]

No issues were observed or reported. •

Parking

Category [2]

The parking lot has one entrance for ingress/egress.

Concrete Paving

Category [0]

No issues were observed or reported.

AC paving

Category [2]

- AC paving in the parking lots is in fair to poor condition.
- AC paving at the hardcourts is in good condition. •

Ramps & Stairs

Category [0]

This condition does not exist.



FACILITY CONDITION ASSESSMENT

OVERVIEW

ASSESSMENT RATING LEGEND:

Athletic Fields & Facilities

Category [4]

 The field area at the corner of E Central Ave. and Calle Mazatlan is unimproved.

EXISTING CAMPUS PLAN

Landscape

Category [1]

• Landscaping areas are bare/sparsely planted.

Irrigation

Category [5]

- Irrigation wiring is damaged; new irrigation wiring is desired.
- Poor water pressure was reported.
- . New booster pump and backflow preventer are desired.

Fencing & Gates

Category [1]

• Perimeter fencing/gates are in fair condition.

ASSESSMENT OF BUILDINGS

Exterior

Paint

Category [3]

- Exterior stucco at buildings and covered walkway • columns is damaged at corners and in areas near the base.
- Painting to the exterior is planned for 2017.

Door / Frames / Locks

Category [0]

• Doors, frames, and locks appear to be original to the building.

Windows

Category [0]

Windows are original, single-pane.

Roof

CONCEPTUAL MASTER PLAN

- Category [5]
- Roofing replacement is planned for 2017.

ADA Compliance

Category [0]

No issues were observed or reported. •

Interior

Overall Rating: Category [2]

Building interior finishes and casework appear to be original.

COST SUMMARY

Flooring is in fair condition, replacement should be • considered.

Food Service

- Category [0]
- No issues were observed or reported.

Restrooms

Category [3]

Restrooms are in poor condition; modernization is desired.

ASSESSMENT OF SYSTEMS

Site Utilities

Domestic Water

Category [0]

• No issues were observed or reported.

Fire Protection

Category [0]

• No issues were observed or reported.

Gas

Category [0]

- No issues were observed or reported.



CATEGORY [0] No Work CATEGORY [1] Minor Work CATEGORY [2] Minor Modernization CATEGORY [3] Standard Modernization CATEGORY [4] Major Modernization / Reconfiguration CATEGORY [5] **Complete Replacement**

SITE AMENITIES **Drinking Fountains**

Category [5]

Drinking fountains are in poor condition, replacement ٠ is desired.

Shade Shelter

Bike Area

Category [0]

No issues were observed or reported. •

Covered Walkways

Exterior stucco at covered walkway columns is ٠ damaged in areas near the base.

Play Structures

- Kindergarten play structures are in poor condition; • replacement is desired.
- Play structure for upper grades is in good condition.

Category [0]

This condition does not exist. •

Category [2]

Category [5]

FACILITY CONDITION ASSESSMENT

ASSESSMENT RATING LEGEND:

No Work

Minor Work

Minor Modernization

Major Modernization / Reconfiguration

Standard Modernization

Complete Replacement

CATEGORY [0]

CATEGORY [1]

CATEGORY [2]

CATEGORY [3]

CATEGORY [4]

CATEGORY [5]

Technology

Category [0]

No issues were observed or reported.

Intercom / Clock / Bell

Category [0]

No issues were observed or reported.

Security

Category [-]

• Security fencing at campus entry will be reconfigured in 2017/2018 to increase campus security.

EXISTING CAMPUS PLAN

Lighting

Category [4]

Exterior lighting additions/improvements is desired.

Storm Drain / Drainage Category [0]

Category [0]

Sewer

• No issues were observed or reported.

No issues were observed or reported.

Mechanical

Overall Rating: Category [-]

Mechanical units are original to the building (1992) • and do not provide even heating/cooling.

Plumbing

Category [3]

• Restrooms are in poor condition; modernization is desired.

Electrical

Power

Category [0]

No issues were observed or reported. •

Fire Alarm

Category [3]

Upgrade to the fire alarm system, including the panel • is desired.

CONCEPTUAL MASTER PLAN



COST SUMMARY

OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN COST SUMMARY



Drop-Off Lane



Covered Walkway



Hardcourts







Outdoor Dining



Play Structure



Typical Concrete Paving



Security Fencing



Landscaping



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY



Windows

Exterior Door Hardware



Administration Office



Staff Work Room / Lounge



Multipurpose Room



Kitchen



Food Serving Area



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN CONCEPTUAL MASTER PLAN COST SUMMARY



Drinking Fountain



Media Center



Restroom



Typical Classroom



Health Office



Teacher Prep Room



OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY







OVERVIEW

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

COST SUMMARY





Morgan Hill Unified School District FACILITIES MASTER PLAN



FACILITY CONDITION ASSESSMENT 5.2 FACILITY CONDITION ASSESSMENT EL TORO HEALTH SCIENCE ACADEMY

	OVERVIEW	FACILITY CONDITION ASSESSMENT	EXISTING CAMPUS PLAN		CONCEPTUAL MASTER PLAN		COST SUMMARY
SCOPE OF WORK CATEGORIES			MASTER PLAN COST (2017\$)				
1.	Modernize / Reconfigure Existi	ing Classrooms		\$	3,223,000		
2. Existing Building Systems, Toilets & Improved Energy Efficiency				\$	2,301,000		
3.	3. Site Utilities			\$	27,000		
4.	4. New Construction (Classrooms)			\$	5,782,000		
5.	5. Science, Arts, CTE & Electives Programs			\$	-		
6.	6. Performing Arts Improvements			\$	-		
7.	7. MPR, Student Union & Food Service Improvements			\$	2,957,000		
8.	8. Physical Education Improvements			\$	-		
9.	9. Staff & Parent Support			\$	2,082,000		
10.	10. Media Center & Student Support Services			\$	2,508,000		
11.	11. Safety & Security			\$	723,000		
12.	Parking & Drop-Off			\$	974,000		
13.	Outdoor Learning Courts, Qua	ds & Landscape		\$	800,000		
14.	14. Exterior Play Spaces, Playfields & Hardcourts			\$	2,551,000		
15.	Instructional Design Furniture			\$	788,000		
16.	Technology Infrastructure and	Equipment		\$	257,000	Utility hook-up feOff-site work and	
		Total Construction / Pr	oject Cost (2017\$)	\$	24,973,000	Land acquisitionHazardous mateEscalation (cost	erial surveys, abatement and disposal

