

**Clayton School
Construction Photos
7.12.17**

All utility relocates are completed. Over excavation complete and spread footings cut-ins beginning.



Photo taken from center of the site, looking southeast.



Photo taken from center of the site, looking directly east.



Photo taken from Delaware, looking West.



