

**Clayton School
Construction Photos
7.31.17**

Spread footings cut-ins complete. Crew managing water and drying out site, after it received several inches of rain Wednesday 7/22. ACM removal continues to ensure the full safety of the site.

Photo taken from center of the site, looking east.





