

**Clayton School
Construction Photos
8.14.17**

The Foundation Permit was received and foundations have started at Clayton!

Photo from center of site, looking east. Foundation formed and poured for west side of southwest corner to the east corner of the gym.



Safety fences for recess areas are installed.



**ACM cleanup continues; foundation of building of the ACM discovered 8/4/17.
ACM removal expected to be completed by 3rd week of August.**



Photo from Union at construction entrance, looking north.



Photo from center of site, looking northeast.

