

**Clayton School  
Construction Photos  
9.7.17**

**ACM is complete.**



**Foundation walls complete from SW corner through SE corner of gym w/ damp-proofing.**



**Walls being formed to continue around NE Corner to North to NW Corner**



**Footers being formed and rebar being placed to form North Side of Courtyard**

