

**Clayton – Construction Photos**  
**1.10.18**



**South Wing – Steel Erection and roof continue**



**Center Courtyard – Steel Erection and roof continues**



**North Classroom Wing – view from courtyard. Exterior Wall/Window framing and insulation. Scaffolding be set in place in preparation for brick install 1/16/18.**



**North wing – West view.**






**North Wing – North Wall**




**Interior View at Front Entrance – Looking out under Front Porch Canopy**



**Interior View from Front Entrance – Looking down main hallway and grand staircase. (Did you notice the signed columns from the students?)**





**Interior Duct Work being installed**



**Brick Wall Mock-UP – Brick Installation begins 1/16/18**