

Clayton – Construction Photos
2.2.18

North Wing – South Elevation: Brick is complete on inner courtyard side



Brick being installed by SAM: Semi Automated Mason



Mezzanine above grand stair case



Interior Space of North Classroom Wing



Interior Classroom

