





Front Entrance / Gym – Southeast Elevation; Brick, windows, and frames installation continues



Front Entrance – Southwest Elevation; Brick, roof and parapet installation continues



Main Entrance Patio– Brick and windows to be installed soon






Grand Hall – North Facing View; Framing, mechanical, and drywall install continues



Grand Hall – South Facing View; Framing, mechanical, and drywall install continues

Grand Hall – South Facing View; Framing, mechanical, and drywall install continues








Office Area – West Facing View; Electrical, mechanical, insulation, and drywall being installed




South Classroom Wing (lower level) – West Facing View; Insulation, drywall, mechanical, and electrical install continues



Office Area/Main Entrance – West Facing View; Framing, mechanical, and electrical install continues



Kitchen and Cafeteria – North Facing View – Framing and insulation install continues



Learning Commons – South Facing View – Framing install continues



North Classroom Wing (lower level) – West Facing View; Drywall complete and painting to begin soon





North Classroom Wing (upper level) – West Facing View; Drywall for soffit to begin



South Classroom Wing (upper level) – West Facing View; Framing, mechanical, and electrical install continues