





Front Entrance / Gym – Southeast Elevation; Brick, windows, and frames being installed; roof and parapet installation continues



Front Entrance – Southwest Elevation; Windows and frames installed; Brick install; Roof and parapet installation continues

Plaza Area (Between Classroom Wings) – East Facing View; Windows, frames, and brick being installed



North Classroom Wing – Northwest Elevation; Brick, windows, and frames being installed.

East Elevation – Brick, windows, and frames being installed





Grand Hall – South Facing View; Framing and HVAC being installed

Grand Hall – North Facing View; Framing and drywall being installed



Grand Hall Main Entrance – North Facing View; Framing and HVAC being installed

Grand Hall – South Facing View; Framing and drywall being installed





Gym – North Facing View; Windows and frames being installed



South Classroom Wing (lower level) –West Facing View; Framing, HVAC, and plumbing being installed



Kitchen and Cafeteria – North Facing View – Framing being installed

North Classroom Wing (lower level) –
West Facing View; Drywall and
insulation being installed



North Classroom Wing (lower level) -
Classroom; Drywall being installed



Learning Commons – South Facing View – Framing being installed



North Classroom Wing (upper level) – West Facing View;
Drywall and HVAC installed; Framing for drywall soffit to begin

South Classroom Wing (upper level) –
West Facing View; Framing, HVAC,
and plumbing being installed



North Classroom Wing (upper level) – Classroom; Drywall and
HVAC installed