




Clayton Construction Report
April 16, 2018




Front Entrance – South Elevation; Window install and sitework in progress



West Elevation – Plaza Between Classroom Wings; Windows being installed

Grand Hall – North Facing View Adjacent to Gym; HVAC, electrical, insulation and drywall install continues



Grand Hall – North Facing View; HVAC, electrical, framing, insulation and drywall install continues





Reception Area – HVAC, electrical and drywall install continues

South Classroom Wing
(lower level) – Classroom;
Painting in progress



South Classroom Wing (lower level) – West Facing
View; Painting in progress





Cafeteria – Framing continues



North Classroom Wing (lower level) – Classroom; Ceiling install



CAFETERIA, COMMONS & NORTH CLASSROOM WING (L1)



North Classroom Wing (upper level)
– Classroom; Ceiling install



North Classroom Wing (upper level) – West Facing View; Ceiling install in progress and tile install next

South Classroom Wing (upper level)
– Classroom; HVAC work continues,
paint next

