



Clayton Construction Report
May 21, 2018



South Elevation – Main Entrance; Sitework continues, concrete to be poured soon.



East Elevation – Plaza Between Classroom Wings; Sitework continues, concrete newly poured.



Grand Hall – South Facing View; Drywall install finishing, ceiling being installed, and painting to begin soon.



Grand Hall – West Facing View to Plaza; Painting to begin soon.



Gym – Flooring newly installed.

Admin Area –
Cabinets being
installed.



South Classroom
Wing (L1) – SPED
Area; Tilework in
progress.





Cafeteria – Kitchen equipment infrastructure being installed.

Learning Commons – Mechanical, electrical, and ceiling work continues.



North Classroom Wing (lower level) – Classroom; Ceiling tile being installed.



CAFETERIA, COMMONS & NORTH CLASSROOM WING (L1)



North Classroom Wing (upper level) – Painting finishing, ceiling tile to be installed soon.

North Classroom Wing (upper level) – Classroom; Ceiling tile to be installed soon.



North Classroom Wing (upper level) – Flooring to be installed soon.