



Clayton Construction Report
May 14, 2018



South Elevation – Main Entrance; Sitework continues.



West Elevation – Plaza Between Classrooms; Sitework continues, walkways newly poured.



East Elevation – Sitework continues.

Grand Hall – South Facing View; Drywall recently completed, painting to begin soon.



Grand Hall – North Entrance; Framing and glass install.



South Classroom Wing (L1) – Classroom; Cabinets being installed.

Admin Area – Painting in progress. Ceiling install next.



South Classroom Wing (lower level) – Teacher Restroom; Tilework in progress.



GYM, OFFICE AREA & SOUTH CLASSROOM WING (L1)



Cafeteria – HVAC and electrical work continues. Painting to begin soon.

North Classroom Wing (lower level) – Classroom; Ceiling tile to be installed soon.





North Classroom Wing (upper level) – Glass recently installed.

North Classroom Wing (upper level) – Classroom; Ceiling tile to be installed soon.

