




Clayton Construction Report
April 30, 2018



Front Entrance – South Elevation; Sitework in progress.



East Elevation –South Classroom Wing; Storefront frames being installed.



West Elevation – Plaza Between Classroom Wings; Sitework in progress.



Grand Hall – North Facing View; HVAC, electrical, framing, insulation and drywall install continues.



Grand Hall – North Facing View; HVAC, electrical, insulation and drywall install continues.

Grand Hall – North Facing View; HVAC, electrical, framing, insulation and drywall install continues.






Gym – Painting in progress.

Reception Area –
Painting in progress .




South Classroom Wing
(lower level) –
Classroom; Cabinets
to be installed soon .



North Classroom Wing (lower level) – Ceiling install continues. Light fixtures and wall tile to be installed next.



Learning Commons – Insulation and drywall install continues.



North Classroom Wing (lower level) – Classroom; Cabinets newly installed.



North Classroom Wing (upper level) – Wall tile being installed.

North Classroom Wing (upper level)
– Classroom; Light fixtures newly installed.



North Classroom Wing (upper level)
– Restroom; Wall tile newly installed.

