



Clayton Construction Report  
June 4, 2018



West Elevation – Plaza Between Classroom Wings; Sitework continues, concrete paths newly poured.



Old Clayton– Abatement currently in progress at southern end of school.



Grand Hall – South Facing View; Storefront glass and frames on lower level and ceiling being installed and painting in progress.



Grand Hall – North Facing View; Tile being installed and painting to begin soon.



Grand Hall – North Facing View; Windows and ceiling being installed.



Reception Area – Cabinets being installed.



South Classroom Wing (L1) – Classroom; Flooring to be installed soon. Painting and cabinets complete.



GYM, OFFICE AREA & SOUTH CLASSROOM WING (L1)



Cafeteria – Painting, HVAC and electrical work continues.



STEM Classroom –  
Garage doors and tile  
newly installed.



North Classroom Wing  
(L1) – Flooring to be  
installed soon.



CAFETERIA, COMMONS & NORTH CLASSROOM WING (L1)



North Classroom Wing (upper level) – Classroom; Ceiling tile newly installed.



South Classroom Wing (upper level) – Carpet to be installed soon.