





South Elevation – Main Entrance; Work on drive aisle and parking lot continues.





Grand Hall – North Facing View; Flooring install and final paint nearly complete.







Gym and Music Room – Flooring nearly complete in music room.



Office / Reception Area – Transaction countertop to be installed soon.



Cafeteria – Kitchen equipment and supplies nearing completion.



Learning Commons – Final paint in progress.





Upper Level Classroom Wing – Punchlist identification underway.