



Maddox ECE Construction Report March 19, 2018



Stem wall rebar at West wing.



Facing East from Huron.



Using surveying equipment to perform quality control on stem wall forms.



Conduit stub-ups at East wall.