



## Maddox ECE Construction Report

March 26, 2018



East wing with stem wall poured.





North central section, closeup of insulation, dampproofing and IT conduit.



West wing.





West wing stub-ups and stem wall rebar.

Wall mock-up progression.

