



Maddox ECE Construction Report April 9, 2018



Utility stub-ups.



Looking West – backfilled with utility stub-ups.



Looking East – North stem walls poured, South are formed.



West wing stem walls half poured.