



## Maddox ECE Construction Report September 17, 2018



Multi-purpose areas looking out.



Classroom Progress.

East wing progress.



West wing progress.






Mud room between classrooms.



East wing ceilings painted.



Front entry.



Exterior facilities.