

Everson Elementary School Progress Photos

Date: November 6, 2020



Over excavation is taking place at the South East corner of the new 10 classroom addition.



Fill material is being spread in place.



The jobsite is a busy place.



Structural fill material being delivered.



Aerial photo showing the south end of the site.



This photo shows where the 10 classroom addition will fit in relation to the existing school.