



March 26, 2019

ISD# 834
1875 Greely Street South
Stillwater, MN 55082
Attn: Mr. Tony Willger

RE: **Radon Sampling**
Site: **Early Childhood Family Center**

Field Environmental Consulting, Inc. (FIELD ENVIRONMENTAL) appreciates the opportunity to provide results for radon monitoring conducted at the Early Childhood Family Center.

Radon levels are measured in picocuries per liter or pCi/L. The Environmental Protection Agency (EPA) and the Minnesota Department of Health (MDH) action level for indoor radon is 4.0 pCi/L.

Radon monitoring was conducted using AccuStar® PicoCan 275 short-term open face charcoal canisters (registered device #AC-6048).

In January 2019, fifty-nine (59) detectors were analyzed for radon concentration. All samples were below the action level of 4.0 pCi/L. No additional action necessary.

PREPARED and REVIEWED BY:

Field Environmental Consulting, Inc.

Amy Weinzierl (CSP #27824)
EHS Manager / Licensed Radon Measurement Professional (RMEA-00111)
amy@fieldconsultinginc.com
952-746-5880

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082

Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3212187	3931397	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Fl 243 Custodial Office Top Slot	0.8
3212188	3931362	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Fl 243 Custodial Office Top Slot Field Blank	< 0.4
3212189	3931364	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 15 Top Shelf	0.9
3212190	3931365	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 16 Top Shelf	0.8
3212191	3931366	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 16 Top Shelf Duplicate	0.6
3212192	3931367	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 17 Top shelf	1.0
3212193	3931368	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 14 Top Shelf	0.5
3212194	3931369	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 181 Therapy Room Printer	0.4
3212195	3931370	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 187 Therapy Next cube	0.5
3212196	3931396	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 13 Top shelf	1.1
3212197	3931395	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 12 Top Shelf	0.8

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3212198	3931394	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 12 Top Shelf Duplicate	0.6
3212199	3931399	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 11 Top shelf	0.4
3212200	3931393	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 11 Top shelf Field Blank	< 0.4
3212201	3931400	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 10 Top Shelf	0.7
3212202	3931391	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 9 Top shelf	1.1
3212203	3931398	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 8 Top shelf	0.6
3212204	3931363	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 149 Therapy Shelf	0.5
3212205	3931361	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 143 Grey Cabinet	0.8
3212206	3931354	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 141 Top shelf	1.1
3212207	3931355	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 141 Top shelf Duplicate	0.7
3212208	3931356	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 140 Top shelf	1.3

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082

Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3212209	3931392	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 173 Therapy Grey	1.3
3212210	3931353	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 172 Therapy Black	0.6
3212211	3931359	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 131 Top shelf	< 0.4
3212212	3931360	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 131 Top shelf	0.6
3212213	3931358	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 129 Top shelf	1.2
3212214	3931357	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 128 Grey Top shelf	1.1
3212215	3931344	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 126 Shelf by Green	0.5
3212216	3931341	01/22/2019 9:30 am	01/24/2019 2:00 pm	First Floor Room 120 By Door	0.6
3212217	3931345	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 121 Top shelf	0.8
3212218	3931342	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 121 Top shelf Duplicate	1.0
3212219	3931352	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 125 Top shelf by Sink	< 0.4

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082


Log Number	Device Number	Test Exposure Duration:	Area Tested	Result pCi/L
3212220	3931343	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Reception By Phone	0.9
3212221	3933953	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Open Office Mail Area	1.3
3212222	3933912	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Open Office Mail Area Duplicate	1.0
3212223	3931351	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Open Office Ashley File	1.0
3212224	3933919	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room 227 Back cabinet	< 0.4
3212225	3933918	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Open Office Field Blank	< 0.4
3212226	3931421	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room 228 Office	1.0
3212227	3933688	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Office 229	0.4
3212228	3933716	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Office 231	0.9
3212229	3933679	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room 236 Lounge Brown Shelf	1.0
3212230	3933680	01/22/2019 9:30 am 01/24/2019 2:30 pm	First Floor Room Library Parent Ed Cab	1.2

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3212231	3933678	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 240 Nurse Cab by Computer	0.7
3212232	3931377	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 204 Sensory Sanitizer	1.2
3212233	3931375	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 166 Therapy Blue Cab	0.9
3212234	3931378	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 167 Therapy Blue Cab	1.2
3212235	3931376	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 168 Therapy Cab	1.1
3212236	3931379	01/22/2019 9:30 am	01/24/2019 2:30 pm	First Floor Room 169 Therapy Cab	0.8
3212237	3931374	01/22/2019 9:30 am	01/24/2019 3:00 pm	First Floor Room 200 Gym First Aid Kit	1.2
3212238	3931380	01/22/2019 9:30 am	01/24/2019 3:00 pm	First Floor Room 200 Gym Speaker	1.2
3212239	3931373	01/22/2019 9:30 am	01/24/2019 3:00 pm	First Floor Room 165 Therapy Cab	0.4
3212240	3931371	01/22/2019 9:30 am	01/24/2019 3:00 pm	First Floor Room 164 Therapy Cab	0.7
3212241	3931372	01/22/2019 9:30 am	01/24/2019 3:00 pm	First Floor Room 164 Therapy Cab Duplicate	0.8

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378


Early Childhood Family Center
1111 Holcombe Street S
Stillwater MN 55082


Log Number	Device Number	Test Exposure Duration:	Area Tested	Result pCi/L
3212242	3931298	01/22/2019 9:30 am 01/24/2019 3:00 pm	First Floor Room 192 Shelf	1.4
3212243	3931294	01/22/2019 9:30 am 01/24/2019 3:00 pm	First Floor Room 193 Shelf	0.9
3212244	3931295	01/22/2019 9:30 am 01/24/2019 3:00 pm	First Floor Room 222 Therapy by File Side	1.2
3212245	3931296	01/22/2019 9:30 am 01/24/2019 3:00 pm	First Floor Room 221 Therapy Side File	0.9

Test Performed By: Amy Weinzierl Certification Number: RMEA-00111

Distributed by: Field Environmental Consulting, Inc.

Date Received: 01/28/2019 Date Logged: 01/28/2019 Date Analyzed: 01/29/2019 Date Reported: 01/30/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

Shawn Price, Director of Laboratory Operations, AccuStar Labs

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

Early Childhood Family Center Short-Term Radon Monitoring Project #19036

Short-Term Radon (January 2019)

- ◆ Radon < 4 pCi/L
- ◆ Radon ≥ 4 pCi/L
- D Duplicate Detector
- FB Field Blank Detector

